Room / Photo Ref	Floor/Level	Significant features	Problem + Risk vs. Repair Requirement	Estimate Cost Item	Proposed Works	Works carried out	Consultation undertaken	Planning Permission References	Impact Assessment
Not Min Protect MF101 / 20002247	Living Room	Exposed elements of the timber construction, fireplace & pertinent wall finishes	Item 6 Timber frames: The roof structure is supported on original plates and frames, with original rafters and purlins embedded in the masonry of west elevation. Timbers affected with wet rot and wood boring beetles and may not be structurally adequate. Underside of common rafter plates and head of principal posts appear structurally decayed. Base of posts supporting south east porch structurally decayed. Item 7 Windows: Original windows replaced as sash type which are in poor state of repair. Certain sills have inadequate provision for ventilation by trickle ventilators to prevent condensation. Work to most frames, particularly those not centrally occupied by heat rad. Item 8 Ventilation & Condensation: Overall, ventilation of the property is poor with inadequate provision for trickle ventilators to prevent condensation resulting in mould growth etc. Due to inadequate extraction of moisture laden air at point of source, inadequate and irregular background ventilation to rooms etc. Item 9 Ventilation, insulation and consideration of roof structures: Some panel and acoustic insulation, provided over the finished roof structure, are gaps in places, however existing provision for insulation over the ceilings are inadequate and readily contaminated. Item 10 Damp proofing: Some evidence of localised rising damp in the property with some plaster work. Item 12 Solid floors: Internal floors consist of mixed tile finishes on floor joists during previous refurbishment and are not, we believe, sympathetic for insulation of damp proofing and were allowing	Existing walls surrounding at time and modern fenestration have been carried out with unsympathetic working using a concrete reinforcement. Lancaster Road, modern timber style casement window with toplights	Remove modern fenestration as detailed. Point all brickwork and pargetting externally where required to prevent wall ingress. Repair & renew timber posts with timber sizes agreed on site. Allow for making good, repairing timber underneath & where necessary using traditional carpentry methods and use for like for like. Demolish timber porch detail, excepting of which is still evident to the external wall to the front and base existing reinforced concrete to the historic core. Retain modern fenestration as item 7 above. Make good as necessary throughout using traditional like for like materials and practices and provision of existing carefully salvaged timber. Remove & form mixed, Make good as necessary throughout using traditional like for like material to replicate the existing. All timbers found to be unsound to be replaced with timbers to match existing, unless otherwise agreed with Structural Engineer's report. Remove existing plaster and render to inside of walls, including plaster and brick internally with exception to chimney breasts and fireplaces which are to remain. Redecorate throughout to agreed scheme internally with the exception of