Room / Photo Ref	Floor/Level	Significant features	Current condition & Reason for significance	Comments from Heritage Officer	Proposed works	Works carried out	Documentation submitted in support of	Planning/Listed Building Refs.	Impact Assessment
Mill Mill Protect									
MF101 / 20002247	Living Room	External elements of the timber construction, fireplace & internal wall division.	Item 6 Timber frames: The roof structure is supported on original plates and frames, with original rafters and purlins embedded in the masonry of west elevation. Timbers affected with wet rot and wood boring beetles and may not be structurally adequate. Underside of common rafter plates and head of principal purlin appear structurally adequate. Base of posts supporting south east porch structurally damaged. Item 7 Windows: Original windows replaced as new type which are in poor state of repair. Leaded lights are generally damaged by vandals. Item 8 Ventilation & Condensation: Overall, ventilation of roof void is adequate. Item 9 Insulation & Thermal Efficiency: Insulation at ceiling level is generally adequate. Item 10 Services: Electrical wiring is generally adequate. Item 11 Underpinning: Some evidence of localised underpinning to internal load bearing walls and chimney breasts. Item 12 Solid floors: Internal floors consist of concrete screeds on ground floor with floating boards on timber joists at first floor. Item 13 Miscellaneous: Staircase is in good condition. Item 14 Dampness: Some evidence of rising damp to base of external walls. Item 15 Woodworm: Some evidence of woodworm attack to roof timbers. Item 16 Asbestos: No asbestos materials identified.	Existing walls surrounding at time and modern brickwork have been filled with counterbalance soil by linings on a previous refurbishment. Set aside floor, modern timber style casement window with toplights	Remove modern brickwork to internal face of north and west boundaries. Remove internal modern fittings to west wall where historic chimney piece with timber lintel was removed. Allow for making good, repointing timber mantelpiece & reinstating original fireplace opening. Allow for making good, repointing timber mantelpiece & reinstating original fireplace opening. Allow for making good, repointing timber mantelpiece & reinstating original fireplace opening. Remove existing modern internal partitions and provide new internal partitions as detailed on drawing numbers to form room. Make good as necessary throughout using traditional materials to replicate the existing. All timbers found to be unsound and beyond economic repair to be replaced with new timbers to match existing sizes and profiles as per Architectural Engineer's report. Remove existing door and window to North elevation including lintel, and brick internally with new to match. Reconfigure to form a glazed screen internally within the elevation comprising door to match new and existing door. Form new internal partitions as detailed on drawing numbers to form room. Make good as necessary throughout using traditional materials to replicate the existing. All timbers found to be unsound and beyond economic repair to be replaced with new timbers to match existing sizes and profiles as per Architectural Engineer's report. Remove and install new internally to accommodate new sanitary fittings as detailed on drawing numbers