

Site Photographs

38 Dallaway Road – Arundel



Existing rear of property. Proposals seek to extend this towards the rear.



Side of property is screened by a fence and soft landscaping



Entrance to property is currently rather weak – proposals seek to address this by wrapping canopy and cladding around the corner and putting house number on canopy.



Front recess to be pulled out – this will help maximise the internal space and remove the existing leaf trap. New windows to this elevation although set back by the garage are all to non habitable rooms.