

Site Photographs

38 Dallaway Road – Arundel



Existing rear of property. Proposals seek to extend this towards the rear.



Side of property is screened by a fence and soft landscaping



Entrance to property is currently rather weak – proposals seek to address this by wrapping canopy and cladding around the corner and putting house number on canopy.



Front recess to be pulled out – this will help maximise the internal space and remove the existing leaf trap. New windows to this elevation although set back by the garage are all to non habitable rooms.



Other properties on the road with Fencing to the street side.