


repair cracks/replace bonding to chimney.

existing lead roof to bay
at Ground floor level.



existing slate roof.

repoint brickwork joints

existing lead cloak ridge + hip

New Velux CK01 roof
window - top hung to
provide maintenance
access to valley gutter.

falls

valley gutter

line

Velux
CK01

existing downpipe

N°19 Maltravers

N°17 Maltravers

existing lead roof to bay

existing felled
flat roof

N°17

N°15

Proposed Works at
17 Maltravers St
ARUNDEL BN18 9AP

Roof Plan
Proposed

1:50 Feb'21

16

A