

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 1	
Date: 15/08/2019	
Overview of HDP101	
Photo No. 2	
Date: 15/08/2019	
View showing the depth of clean capping within HDP101 to be at least 600 mm thick	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No.
3

Date:
15/08/2019

HDP101
capping layer
observed to
be underlain
by a geo-
marker
membrane



Photo No.
4


Date:
21/08/2019

View
showing the
depth of
clean
capping
within
HDP102 to
be at least
600 mm thick




PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 5	
Date: 21/08/2019	
HDP102 capping layer observed to be underlain by a geo-marker membrane	
Photo No. 6	
Date: 13/08/2019	
View showing the depth of clean capping within HDP103 to be at least 600 mm thick	

PHOTOGRAPHIC LOG


Site Location: Land at West End Nursery, Angmering – SE POS


Photo No. 7	
Date: 13/08/2019	
HDP103 capping layer observed to be underlain by a geo- marker membrane	
Photo No. 8	
Date: 13/08/2019	
Overview of HDP104	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 9	
Date: 13/08/2019	
View showing the depth of clean capping within HDP104 to be at least 600 mm thick	
Photo No. 10	
Date: 13/08/2019	
HDP104 capping layer observed to be underlain by a geo-marker membrane	



PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 11	
Date: 15/08/2019	
View showing the depth of clean capping within HDP105 to be at least 600 mm thick	
Photo No. 12	
Date: 15/08/2019	
View of capping layer in HDP105	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 13	
Date: 15/08/2019	
HDP105 capping layer observed to be underlain by a geo-marker membrane	
Photo No. 14	
Date: 13/08/2019	
Overview of HDP106	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 15	
Date: 13/08/2019	
View showing the depth of clean capping within HDP106 to be at least 600 mm thick	
Photo No. 16	
Date: 13/08/2019	
HDP106 capping layer observed to be underlain by a geo-marker membrane	


PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 17	
Date: 13/08/2019	
View showing the depth of clean capping within HDP107 to be at least 600 mm thick	
Photo No. 18	
Date: 13/08/2019	
HDP107 capping layer observed to be underlain by a geo-marker membrane	



PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 19	
Date: 15/08/2019	
View showing the depth of clean capping within HDP108 to be at least 600 mm thick	
Photo No. 20	
Date: 15/08/2019	
View of capping layer in HDP108	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 21	
Date: 15/08/2019	
HDP108 capping layer observed to be underlain by a geo-marker membrane	
Photo No. 22	
Date: 13/08/2019	
View showing the depth of clean capping within HDP109 to be at least 600 mm thick	


PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 23	
Date: 13/08/2019	
View of capping material in HDP109	
Photo No. 24	
Date: 13/08/2019	
HDP109 capping layer observed to be underlain by a geo-marker membrane	



PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 25	
Date: 13/08/2019	
View showing the depth of clean capping within HDP110 to be at least 600 mm thick	
Photo No. 26	
Date: 13/08/2019	
HDP110 capping layer observed to be underlain by a geo-marker membrane	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 27	
Date: 21/08/2019	
View showing the depth of clean capping within HDP111 to be at least 600 mm thick	
Photo No. 28	
Date: 21/08/2019	
HDP111 capping layer observed to be underlain by a geo-marker membrane	

PHOTOGRAPHIC LOG


Site Location: Land at West End Nursery, Angmering – SE POS


Photo No. 29	
Date: 15/08/2019	
Overview of HDP112	
Photo No. 30	
Date: 15/08/2019	
View showing the depth of clean capping within HDP112 to be at least 600 mm thick	

PHOTOGRAPHIC LOG


Site Location: Land at West End Nursery, Angmering – SE POS


Photo No. 31	
Date: 15/08/2019	
HDP112 capping layer observed to be underlain by a geo-marker membrane	
Photo No. 32	
Date: 13/08/2019	
Overview of HDP113	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 33	
Date: 13/08/2019	
View showing the depth of clean capping within HDP113 to be at least 600 mm thick	
Photo No. 34	
Date: 13/08/2019	
HDP113 capping layer observed to be underlain by a geo-marker membrane	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 35	
Date: 15/08/2019	
Overview of HDP114	
Photo No. 36	
Date: 15/08/2019	
View showing the depth of clean capping within HDP114 to be at least 600 mm thick	


PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 37	
Date: 15/08/2019	
View of HDP114 - water perched on top of geo- marker layer	
Photo No. 38	
Date: 15/08/2019	
Overview of HDP115	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 39	
Date: 15/08/2019	
View showing the depth of clean capping within HDP115 to be at least 600 mm thick	
Photo No. 40	
Date: 15/08/2019	
HDP115 capping layer observed to be underlain by a geo-marker membrane	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering – SE POS	
Photo No. 41	
Date: 15/08/2019	
Overview of HDP116	
Photo No. 42	
Date: 15/08/2019	
View showing the depth of clean capping within HDP116 to be at least 600 mm thick	


PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 43	
Date: 15/08/2019	
HDP116 capping layer observed to be underlain by a geo- marker membrane	
Photo No. 44	
Date: 15/08/2019	
Overview of HDP117	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 45	
Date: 15/08/2019	
View showing the depth of clean capping within HDP117 to be at least 600 mm thick	
Photo No. 46	
Date: 15/08/2019	
HDP117 capping layer observed to be underlain by a geo-marker membrane	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No. 47	
Date: 13/08/2019	
Overview of HDP118	
Photo No. 48	
Date: 13/08/2019	
View showing the depth of clean capping within HDP118 to be at least 600 mm thick	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering – SE POS

Photo No.
49

Date:
13/08/2019

HDP118
capping layer
observed to
be underlain
by a geo-
marker
membrane

