

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 7	
Date: 17/05/2018	
<u>Phase 2A:</u> Facing east: hydrocarbon hotspot excavation works in progress.	
Photo No. 8	
Date: 17/05/2018	
<u>Phase 2A:</u> Facing east: View of final excavation following removal of hydrocarbon impact in the vicinity of Plot 325 (east-central foundations).	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
9

Date:
17/05/2018

Phase 2A: Eastern face of resulting excavation following removal of hydrocarbon impacts (Plot 325) with the resulting temporary stockpile TSP02-P3 behind.




Photo No.
10

Date:
17/05/2018

Phase 2A: Facing north west: hydrocarbon-impacted soils placed on polythene sheeting to prohibit leaching of contaminants to ground. Temporary stockpile ID TSP02-P3.



PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
11

Date:
18/05/2018

Phase 2A: Facing north: polythene sheeting covering TSP02-P3 to prohibit rainwater infiltrating the hydrocarbon-impacted soil.



Photo No.
12

Date:
18/05/2018

Phase 2A: Facing southwest: polythene sheeting covering TSP02-P3 to prohibit rainwater infiltrating the hydrocarbon-impacted soil, potentially result in hydrocarbons leaching from the soil.



PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 13	
Date: 20/06/2018	
<u>Phase 2A:</u> View showing visual signs of septic tank impacts (stained flint gravel) from the soakaway feature underlying Plot 319 removed during hotspot excavation works.	
Photo No. 14	
Date: 20/06/2018	
<u>Phase 2A:</u> View showing the remains of a concrete structure. Perched water with visual signs of localised septic tank impacts (sheen) noted to seep out from beneath the stained flint gravel. By the following day all perched groundwater observed to have evaporated.	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No. 15	
Date: 20/06/2018	
<u>Phase 2A:</u> View showing the Plot 319 excavation. Further visual signs of septic tanks impacts (stained concrete and flint gravels) were present underlying the perched water. By the following day all perched groundwater observed to have evaporated.	
Photo No. 16	
Date: 20/06/2018	
<u>Phase 2A:</u> View showing excavation arisings removed from the Plot 319 hotspot, placed on geo-marker membrane.	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
17

Date:
20/06/2018

Phase 2A:
View showing
the Plot 319
excavation
arising
covered by
geo-marker
membrane.



Photo No.
18

Date:
26/06/2018

Phase 2A:
View of the
Plot 319
excavation,
from the
south during
hotspot
removal
works.
Exposed
services can
be seen in
the east wall
following its
collapse.



PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 19	
Date: 26/06/2018	
<u>Phase 2A:</u> View of the Plot 319 excavation from the north during hotspot removal works. Perched groundwater observed in the south eastern corner. By the following day all perched groundwater observed to have evaporated.	
Photo No. 20	
Date: 26/06/2018	
<u>Phase 2A:</u> View of the Plot 319 excavation from the north, during hotspot removal works. The depth of excavation at this point observed to be approximately 4.9 m bgl in the south eastern corner.	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
21

Date:
17/07/2018


Phase 2A:
View of the eastern wall of the Plot 319 excavation following hotspot removal works. Validation sample collected from 3.00 m bgl.



Photo No.
22

Date:
17/07/2018

Phase 2A:
View of the base of the Plot 319 excavation showing the validation sampling location at the base of the excavation within the chalk (~6.00 m bgl).



PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No. 23	
Date: 17/07/2018	
<u>Phase 2A:</u> View of the upper half of the southern wall of the Plot 319 excavation following hotspot removal works, showing the southern wall sampling location at 3.80 m bgl.	
Photo No. 24	
Date: 26/07/2018	
<u>Phase 2A:</u> View of the Plot 319 excavation following digging out impacted material and backfilling with concrete rings and clean soils. View shows the south and east walls.	


PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 25 Date: 02/07/2018 <u>Phase 2A:</u> View of the Plot 317 parking bay hydrocarbon hotspot validation excavation from the north.	
Photo No. 26 Date: 02/07/2018 <u>Phase 2A:</u> View of the Plot 317 parking bay hydrocarbon hotspot validation excavation from the south. Showing the location of the sample taken from the base of the excavation.	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No. 27	
Date: 02/07/2018	
<u>Phase 2A:</u> Location of the eastern wall validation sampling location from the Plot 317 parking bay hydrocarbon hotspot validation.	

Photo No. 28	
Date: 02/07/2018	
<u>Phase 2A:</u> Location of the southern wall validation sampling location from the Plot 317 parking bay hydrocarbon hotspot validation.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 29	
Date: 02/07/2018	
<u>Phase 2A:</u> Location of the western wall validation sampling location from the Plot 317 parking bay hydrocarbon hotspot validation.	
Photo No. 30	
Date: 02/07/2018	
<u>Phase 2A:</u> Location of the northern wall validation sampling location from the Plot 317 parking bay hydrocarbon hotspot validation.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 31	
Date: 12/07/2018	
<u>Phase 2A:</u> View of Plot 320-323 parking bay septic tank hotspot during validation. excavation from the south west.	
Photo No. 32	
Date: 12/07/2018	
<u>Phase 2A:</u> View of Plot 320-323 parking bay septic tank hotspot during validation. Sampling location on the southern wall. Sample was collected from 1.7 m bgl. Photo shows the full depth of excavation to 3.7 m bgl.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 33	
Date: 12/07/2018	
<u>Phase 2A:</u> Arisings from Plot 320-323 septic tank validation excavation. A black discolouration and organic odour noted.	
Photo No. 34	
Date: 12/07/2018	
<u>Phase 2A:</u> View of the Plot 320-323 parking bay septic tank hotspot validation sampling location on the northern wall. Validation sample collected from 2.5 m bgl.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 35	
Date: 12/07/2018	
<u>Phase 2A:</u> View of the Plot 320-323 parking bay septic tank hotspot validation sampling location on the western wall. Validation sample collected from 1.5 m bgl.	
Photo No. 36	
Date: 12/07/2018	
<u>Phase 2A:</u> View of the Plot 320-323 parking bay septic tank hotspot validation sampling location on the eastern wall. Sample was collected from 2.0 m bgl.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 37	
Date: 01/11/2018	
South West Bund A validation pit 1 overview. Capping layer thickness observed to be >600 mm thick.	
Photo No. 38	
Date: 01/11/2018	
South West Bund A validation pit 1, detailed view showing orange marker membrane at the base.	