

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 39	
Date: 01/11/2018	
South West Bund A validation pit 1 overview. Capping layer thickness observed to be 600 mm thick.	
Photo No. 40	
Date: 01/11/2018	
South West Bund A validation pit 2, detailed view showing orange marker membrane at the base.	

PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
41

Date:
20/11/2018

View of west side of south west bund B. Bund observed to be fenced off and planted with prickly vegetation.



Photo No.
42

Date:
20/11/2018

View of centre of south west bund B. Bund observed to be fenced off and planted with prickly vegetation.



PHOTOGRAPHIC LOG

Site Location: Land at West End Nursery, Angmering

Photo No.
43

Date:
20/11/2018

View of centre of south west bund B. Bund observed to be fenced off and planted with prickly vegetation.



Photo No.
44

Date:
20/11/2018

View of east side of south west bund B. Bund observed to be fenced off and planted with prickly vegetation.





PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 45	
Date: 07/02/2019	
Northern wall of validation trial pit at V2 (location of localised oil seepage observed during 2016 validation works) base sample 1 collected from the at 1.10 mbgl (approximately in the original location of V2). No visual or olfactory signs of hydrocarbon contamination observed.	
Photo No. 46	
Date: 07/02/2019	
Western wall of validation trial pit V2. Two validation samples collected at 0.7 m and 1.0 m. No visual or olfactory signs of hydrocarbon contamination observed.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 47	
Date: 07/02/2019	
Eastern wall of validation trial pit V2. Two validation samples collected at 0.6 m and 0.9 mbgl. No visual or olfactory signs of hydrocarbon contamination observed.	
Photo No. 48	
Date: 07/02/2019	
Southern wall of validation trial pit V2. Two validation samples collected at 0.5 m and 0.8 mbgl. No visual or olfactory signs of hydrocarbon contamination observed.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 49	
Date: 07/02/2019	
View of validation trial pit V2 following excavation to 1.1 m bgl, prior to the trial pit being extended further to reach natural strata. No visual or olfactory signs of hydrocarbon contamination observed.	
Photo No. 50	
Date: 07/02/2019	
View of validation trial pit V2 based at 1.1 m bgl, prior to the trial pit being extended further to reach natural strata. No visual or olfactory signs of hydrocarbon contamination observed.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 51	
Date: 07/02/2019	
Eastern wall of validation trial pit V2 following excavation to the final trial pit depth of 2.0 m bgl. No visual or olfactory signs of hydrocarbon contamination observed.	
Photo No. 52	
Date: 07/02/2019	
Northern wall of validation trial pit V2 following excavation to the final trial pit depth of 2.0 m bgl. No visual or olfactory signs of hydrocarbon contamination observed.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 53	
Date: 07/02/2019	
Southern wall of validation trial pit V2 following excavation to the final trial pit depth of 2.0 m bgl. No visual or olfactory signs of hydrocarbon contamination observed.	
Photo No. 54	
Date: 07/02/2019	
Western wall of validation trial pit V2 following excavation to the final trial pit depth of 2.0 m bgl. No visual or olfactory signs of hydrocarbon contamination observed.	

PHOTOGRAPHIC LOG	
Site Location: Land at West End Nursery, Angmering	
Photo No. 55	
Date: 07/02/2019	
View of validation trial pit V2 following excavation to the final trial pit depth of 2.0 m bgl. No visual or olfactory signs of hydrocarbon contamination observed.	