



Section Inspection - 25/05/2021 - SP5X

Item No. 6	Insp. No. 1	Date 25/05/21	Time 10:58	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP5X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP5
Road:	Dappers Lane	Inspected Length:	4.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.40 m	Downstream Node:	F17
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F17



0.00

MH

Start node, manhole, reference: F17

0.00

WL

Water level, 0% of the vertical dimension

3.80

LU

Line deviates up

4.40

MHF

Finish node, manhole, reference: SP5

SP5

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

12

Section Pictures - 25/05/2021 - SP5X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
6	Upstream	SP5X		



1, 00:00:05, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:24, 3.80 m
Line deviates up



3, 00:00:33, 4.40 m
Finish node, manhole, reference: SP5



Section Inspection - 25/05/2021 - SP6X

Item No. 7	Insp. No. 1	Date 25/05/21	Time 11:00	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP6X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP6
Road:	Dappers Lane	Inspected Length:	11.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.50 m	Downstream Node:	F17
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:100 Position [m] Code Observation Grade

Depth: m

F17



0.00

MH

Start node, manhole, reference: F17

0.00

WL

Water level, 0% of the vertical dimension

0.20

LR

Line deviates right

10.90

LU

Line deviates up

11.50

MHF

Finish node, manhole, reference: SP6

SP6

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

14




Section Pictures - 25/05/2021 - SP6X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
7	Upstream	SP6X		



1, 00:00:09, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:49, 10.90 m
Line deviates up



3, 00:00:56, 11.50 m
Finish node, manhole, reference: SP6



Section Inspection - 25/05/2021 - F17X

Item No. 8	Insp. No. 1	Date 25/05/21	Time 11:09	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F17X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F17
Road:	Dappers Lane	Inspected Length:	10.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.20 m	Downstream Node:	F3
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:88 Position [m] Code Observation Grade

Depth: m

F17



0.00

MH

Start node, manhole, reference: F17

0.00

WL

Water level, 0% of the vertical dimension

0.50

LR

Line deviates right

5.90

LR

Line deviates right

8.50

LD

Line deviates down

10.00

LR

Line deviates right

10.20

MHF

Finish node, manhole, reference: F3: Not accessible

F3
Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

16

Section Pictures - 25/05/2021 - F17X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
8	Downstream	F17X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: F17




2, 00:00:09, 0.50 m
Line deviates right




3, 00:00:24, 5.90 m
Line deviates right



4, 00:00:36, 8.50 m
Line deviates down



5, 00:00:46, 10.00 m
Line deviates right



6, 00:00:54, 10.20 m
Finish node, manhole, reference: F3, Not accessible



Section Inspection - 25/05/2021 - SP7X

Item No. 9	Insp. No. 1	Date 25/05/21	Time 12:33	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP7X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP7
Road:	Dappers Lane	Inspected Length:	13.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.60 m	Downstream Node:	F19
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:118 Position [m] Code Observation Grade

Depth: m

F19

0.00

MH

Start node, manhole, reference: F19

0.00

WL

Water level, 0% of the vertical dimension

3.10

LL

Line deviates left

11.10

LL

Line deviates left

13.10

LU

Line deviates up

13.60

MHF

Finish node, manhole, reference: SP7

SP7

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0




Dappers Lane


18



Section Pictures - 25/05/2021 - SP7X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
9	Upstream	SP7X		





	PLR SP8X
	Alternative ID Not Specified

SP8
Depth:
Side:
Water Depth:


Recommendations:

Scale:	1:105	Position [m]	Code	Observation	Grade
Depth: m					
F19					
0.00			MH	Start node, manhole, reference: F19	
0.00			WL	Water level, 0% of the vertical dimension	
0.10			LR	Line deviates right	
2.40			LL	Line deviates left	
7.90			LL	Line deviates left	
11.50			LU	Line deviates up	
12.10			MHF	Finish node, manhole, reference: SP8	
SP8					
Depth: m					

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 25/05/2021 - SP8X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
10	Upstream	SP8X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F19



2, 00:00:23, 2.40 m
Line deviates left



3, 00:00:52, 7.90 m
Line deviates left



4, 00:01:02, 11.50 m
Line deviates up



5, 00:01:08, 12.10 m
Finish node, manhole, reference: SP8



Section Inspection - 25/05/2021 - SP9X


Item No. 11	Insp. No. 1	Date 25/05/21	Time 12:38	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP9X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP9
Road:	Dappers Lane	Inspected Length:	2.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.50 m	Downstream Node:	F19
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

22



Section Pictures - 25/05/2021 - SP9X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
11	Upstream	SP9X		



1, 00:00:06, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:20, 1.50 m
Pipe material changes to vitrified clay at this point



3, 00:00:23, 1.70 m
Line deviates up



4, 00:00:28, 2.50 m
Finish node, manhole, reference: SP9



Section Inspection - 25/05/2021 - F19X

Item No. 12	Insp. No. 1	Date 25/05/21	Time 12:40	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F19X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F19
Road:	Dappers Lane	Inspected Length:	12.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.00 m	Downstream Node:	F3
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:104 Position [m] Code Observation Grade

Depth: m

F19



0.00

MH

Start node, manhole, reference: F19

0.00

WL

Water level, 0% of the vertical dimension

10.60

LL

Line deviates left

11.80

LL

Line deviates left

12.00

F3

Depth: m

MHF

Finish node, manhole, reference: F3: Not accessible

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

Section Pictures - 25/05/2021 - F19X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
12	Downstream	F19X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: F19



2, 00:00:46, 10.60 m
Line deviates left



3, 00:00:55, 11.60 m
Line deviates left



4, 00:01:00, 12.00 m
Finish node, manhole, reference: F3, Not accessible



Section Inspection - 25/05/2021 - SP10X

Item No. 13	Insp. No. 1	Date 25/05/21	Time 12:53	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP10X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP10
Road:	Dappers Lane	Inspected Length:	11.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.40 m	Downstream Node:	F16
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:99 Position [m] Code Observation Grade

Depth: m

F16



0.00

MH

Start node, manhole, reference: F16

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

3.70

LL

Line deviates left

11.20

LU

Line deviates up

11.40

MHF

Finish node, manhole, reference: SP10

SP10

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

Section Pictures - 25/05/2021 - SP10X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
13	Upstream	SP10X		



1, 00:00:08, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:27, 3.70 m
Line deviates left



3, 00:00:45, 11.20 m
Line deviates up



4, 00:00:50, 11.40 m
Finish node, manhole, reference: SP10



Section Inspection - 25/05/2021 - SP11X

Item No. 14	Insp. No. 1	Date 25/05/21	Time 12:55	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP11X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP11
Road:	Dappers Lane	Inspected Length:	4.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.20 m	Downstream Node:	F16
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F16



0.00

MH

Start node, manhole, reference: F16

0.00

WL

Water level, 0% of the vertical dimension

2.50

LL

Line deviates left

3.50

LU

Line deviates up

4.20

MHF

Finish node, manhole, reference: SP11

SP11

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

28




Section Pictures - 25/05/2021 - SP11X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
14	Upstream	SP11X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F16



2, 00:00:18, 2.80 m
Line deviates left



3, 00:00:22, 3.60 m
Line deviates up



4, 00:00:27, 4.20 m
Finish node, manhole, reference: SP11



Section Inspection - 25/05/2021 - SP12X

Item No. 15	Insp. No. 1	Date 25/05/21	Time 12:57	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP12X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP12
Road:	Dappers Lane	Inspected Length:	10.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.80 m	Downstream Node:	F16
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:94 Position [m] Code Observation Grade

Depth: m

F16

0.00

MH

Start node, manhole, reference: F16

0.00

WL

Water level, 0% of the vertical dimension

2.30

LU

Line deviates up

10.30

LU

Line deviates up

10.80

MHF

Finish node, manhole, reference: SP12

SP12

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

30

Section Pictures - 25/05/2021 - SP12X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
15	Upstream	SP12X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F16



2, 00:00:19, 2.30 m
Line deviates up



3, 00:00:40, 10.30 m
Line deviates up



4, 00:00:49, 10.80 m
Finish node, manhole, reference: SP12



Section Inspection - 25/05/2021 - F16X

Item No. 16	Insp. No. 1	Date 25/05/21	Time 13:44	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F16X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F16
Road:	Dappers Lane	Inspected Length:	15.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.90 m	Downstream Node:	F4
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:136	Position [m]	Code	Observation	Grade
Depth: m F16 0.00 0.00 0.40 7.40 8.00 11.20 12.80 12.80 15.90 15.90 F4 Depth: m					
			MH	Start node, manhole, reference: F16	
			WL	Water level, 0% of the vertical dimension	
			LR	Line deviates right	
			LL	Line deviates left	
			LL	Line deviates left	
		S01	DER	Settled deposits, coarse, 30% cross-sectional area loss, start	
		F01	DER	Settled deposits, coarse, 30% cross-sectional area loss, finish	4
		S02	CUD	Loss of vision, silt, start	
		F02	CUD	Loss of vision, silt, finish	
			MHF	Finish node, manhole, reference: F4: Channel full of debris	

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	5.0	0.6	10.0	4.0

Dappers Lane


32

Section Pictures - 25/05/2021 - F16X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
16	Downstream	F16X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F16



2, 00:00:10, 0.40 m
Line deviates right



3, 00:00:36, 7.40 m
Line deviates left



4, 00:00:39, 8.00 m
Line deviates left



5, 00:00:53, 11.20 m
Settled deposits, coarse, 30% cross-sectional area loss, start



6, 00:01:09, 12.80 m
Loss of vision, silt, start



Section Pictures - 25/05/2021 - F16X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
16	Downstream	F16X		



7, 00:01:28, 15.90 m
Finish node, manhole, reference: F4, Channel full of debris



Section Inspection - 25/05/2021 - SP13X

Item No. 17	Insp. No. 1	Date 25/05/21	Time 14:15	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP13X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP13
Road:	Dappers Lane	Inspected Length:	11.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.10 m	Downstream Node:	F15
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:96 Position [m] Code Observation Grade

Depth: m

F15



0.00

MH

Start node, manhole, reference: F15

0.00

WL

Water level, 0% of the vertical dimension

2.40

LL

Line deviates left

4.40

LR

Line deviates right

11.00

LU

Line deviates up

11.10

MHF

Finish node, manhole, reference: SP13

SP13

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


35

Section Pictures - 25/05/2021 - SP13X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
17	Upstream	SP13X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F15




2, 00:00:14, 2.40 m
Line deviates left



3, 00:00:25, 4.40 m
Line deviates right



4, 00:01:18, 11.00 m
Line deviates up



5, 00:01:25, 11.10 m
Finish node, manhole, reference: SP13



Section Inspection - 25/05/2021 - SP14X

Item No. 18	Insp. No. 1	Date 25/05/21	Time 14:17	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP14X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP14
Road:	Dappers Lane	Inspected Length:	3.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.90 m	Downstream Node:	F15
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F15



0.00

MH

Start node, manhole, reference: F15

0.00

WL

Water level, 0% of the vertical dimension

3.30

LU

Line deviates up

3.90

MHF

Finish node, manhole, reference: SP14

SP14

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


37

Section Pictures - 25/05/2021 - SP14X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
18	Upstream	SP14X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F15



2, 00:00:22, 3.30 m
Line deviates up



3, 00:00:27, 3.90 m
Finish node, manhole, reference: SP14



Section Inspection - 25/05/2021 - SP15X

Item No. 19	Insp. No. 1	Date 25/05/21	Time 14:19	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP15X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP15
Road:	Dappers Lane	Inspected Length:	11.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.00 m	Downstream Node:	F15
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:95 Position [m] Code Observation Grade

Depth: m

F15



0.00

MH

Start node, manhole, reference: F15

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

4.10

LU

Line deviates up

10.50

LU

Line deviates up

11.00

MHF

Finish node, manhole, reference: SP15

SP15

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


39

Section Pictures - 25/05/2021 - SP15X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
19	Upstream	SP15X		




1, 00:00:07, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:26, 4.10 m
Line deviates up



3, 00:00:57, 10.50 m
Line deviates up



4, 00:01:07, 11.00 m
Finish node, manhole, reference: SP15



Section Inspection - 25/05/2021 - F15X

Item No. 20	Insp. No. 1	Date 25/05/21	Time 14:23	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F15X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F15
Road:	Dappers Lane	Inspected Length:	10.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.40 m	Downstream Node:	F2
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:90 Position [m] Code Observation Grade

Depth: m

F15



0.00

MH

Start node, manhole, reference: F15

0.00

WL

Water level, 0% of the vertical dimension

0.30

LR

Line deviates right

5.80

LL

Line deviates left

9.90

S01

DER

Settled deposits, coarse, 20% cross-sectional area loss, start

4

10.30

GP

General photograph taken at this point

4

10.40

F01

DER

Settled deposits, coarse, 20% cross-sectional area loss, finish

4

10.40

F2

MHF

Finish node, manhole, reference: F2: Debris in channel

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	3	5.0	1.4	15.0	4.0

Dappers Lane

41

Section Pictures - 25/05/2021 - F15X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
20	Downstream	F15X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F15



2, 00:00:09, 0.30 m
Line deviates right




3, 00:00:32, 5.80 m
Line deviates left



4, 00:00:49, 9.90 m
Settled deposits, coarse, 20% cross-sectional area loss, start



5, 00:00:55, 10.30 m
General photograph taken at this point



6, 00:01:06, 10.40 m
Finish node, manhole, reference: F2, Debris in channel



Section Inspection - 26/05/2021 - SP16X

Item No. 21	Insp. No. 1	Date 26/05/21	Time 9:25	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP16X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP16
Road:	Dappers Lane	Inspected Length:	13.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.00 m	Downstream Node:	F13
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:113 Position [m] Code Observation Grade

Depth: m

F13



0.00

MH

Start node, manhole, reference: F13

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

12.50

LU

Line deviates up

13.00

MHF

Finish node, manhole, reference: SP16

SP16

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

43



Section Pictures - 26/05/2021 - SP16X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
21	Upstream	SP16X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F13



2, 00:00:41, 12.50 m
Line deviates up



3, 00:00:44, 13.00 m
Finish node, manhole, reference: SP16



Section Inspection - 26/05/2021 - SP17X

Item No. 22	Insp. No. 1	Date 26/05/21	Time 9:26	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP17X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP17
Road:	Dappers Lane	Inspected Length:	8.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.90 m	Downstream Node:	F13
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:77 Position [m] Code Observation Grade

Depth: m

F13

0.00

MH

Start node, manhole, reference: F13

0.00

WL

Water level, 0% of the vertical dimension

8.20

LU

Line deviates up

8.90

MHF

Finish node, manhole, reference: SP17

SP17

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

45



Section Pictures - 26/05/2021 - SP17X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
22	Upstream	SP17X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F13



2, 00:00:30, 8.20 m
Line deviates up



3, 00:00:35, 8.90 m
Finish node, manhole, reference: SP17



Section Inspection - 26/05/2021 - SP18X

Item No. 23	Insp. No. 1	Date 26/05/21	Time 9:28	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP18X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP18
Road:	Dappers Lane	Inspected Length:	12.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.70 m	Downstream Node:	F13
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:110 Position [m] Code Observation Grade

Depth: m

F13

0.00

MH

Start node, manhole, reference: F13

0.00

WL

Water level, 0% of the vertical dimension

5.10

LR

Line deviates right

12.10

LU

Line deviates up

12.70

MHF

Finish node, manhole, reference: SP18

SP18

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


47

Section Pictures - 26/05/2021 - SP18X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
23	Upstream	SP18X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F13



2, 00:00:25, 5.10 m
Line deviates right



3, 00:00:45, 12.10 m
Line deviates up



4, 00:00:52, 12.70 m
Finish node, manhole, reference: SP18



Section Inspection - 26/05/2021 - F13X

Item No. 24	Insp. No. 1	Date 26/05/21	Time 9:31	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F13X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F13
Road:	Dappers Lane	Inspected Length:	10.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.80 m	Downstream Node:	F1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:94 Position [m] Code Observation Grade

Depth: m

F13

0.00

MH

Start node, manhole, reference: F13

0.00

WL

Water level, 0% of the vertical dimension

9.50

LL

Line deviates left

10.10

WL

Water level, 5% of the vertical dimension

10.20

WL

Water level, 10% of the vertical dimension

10.30

WL

Water level, 30% of the vertical dimension

10.40

WL

Water level, 40% of the vertical dimension

10.70

WL

Water level, 10% of the vertical dimension

10.80

MHF

Finish node, manhole, reference: F1: Debris in channel

Depth: m

F1

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

49



Section Pictures - 26/05/2021 - F13X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
24	Downstream	F13X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F13



2, 00:00:28, 9.50 m
Line deviates left



3, 00:00:36, 10.20 m
Water level, 10% of the vertical dimension



4, 00:00:39, 10.30 m
Water level, 30% of the vertical dimension



5, 00:00:52, 10.70 m
Water level, 10% of the vertical dimension



6, 00:00:53, 10.80 m
Finish node, manhole, reference: F1, Debris in channel



Section Inspection - 20/07/2021 - F33X

Item No. 25	Insp. No. 1	Date 20/07/21	Time 8:34	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F33X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	F33
Road:	Dappers Lane	Inspected Length:	8.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.30 m	Downstream Node:	F12
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:72 Position [m] Code Observation Grade

Depth: m

F12



0.00

MH

Start node, manhole, reference: F12

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

8.30

MHF

Finish node, manhole, reference: F33

F33

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

51



Section Pictures - 20/07/2021 - F33X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
25	Upstream	F33X		



1, 00:00:49, 0.10 m
Line deviates right



2, 00:00:04, 8.30 m
Finish node, manhole, reference: F33



Section Inspection - 26/05/2021 - SP19X

Item No. 26	Insp. No. 1	Date 26/05/21	Time 10:13	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP19X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP19
Road:	Dappers Lane	Inspected Length:	7.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.40 m	Downstream Node:	F12
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:64 Position [m] Code Observation Grade

Depth: m

F12



0.00

MH

Start node, manhole, reference: F12

0.00

WL

Water level, 0% of the vertical dimension

1.10

LU

Line deviates up

6.80

LU

Line deviates up

7.40

MHF

Finish node, manhole, reference: SP19

SP19

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


53

Section Pictures - 26/05/2021 - SP19X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
26	Upstream	SP19X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F12



2, 00:00:09, 1.10 m
Line deviates up



3, 00:00:26, 6.90 m
Line deviates up



4, 00:00:30, 7.40 m
Finish node, manhole, reference: SP19



Section Inspection - 26/05/2021 - SP20X

Item No. 27	Insp. No. 1	Date 26/05/21	Time 10:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP20X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP20
Road:	Dappers Lane	Inspected Length:	8.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.80 m	Downstream Node:	F12
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:76 Position [m] Code Observation Grade

Depth: m

F12

0.00

MH

Start node, manhole, reference: F12

0.00

WL

Water level, 0% of the vertical dimension

8.30

LU

Line deviates up

8.80

MHF

Finish node, manhole, reference: SP20

SP20

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

55




Section Pictures - 26/05/2021 - SP20X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
27	Upstream	SP20X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F12



2, 00:00:34, 8.30 m
Line deviates up



3, 00:00:38, 8.80 m
Finish node, manhole, reference: SP20



Section Inspection - 26/05/2021 - F12X

Item No. 28	Insp. No. 1	Date 26/05/21	Time 10:17	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F12X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F12
Road:	Dappers Lane	Inspected Length:	13.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.50 m	Downstream Node:	F1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:117 Position [m] Code Observation Grade

Depth: m

F12



0.00

MH

Start node, manhole, reference: F12

0.00

WL

Water level, 0% of the vertical dimension

2.10

LD

Line deviates down

6.10

LR

Line deviates right

9.50

WL

Water level, 5% of the vertical dimension

9.90

WL

Water level, 10% of the vertical dimension

10.20

WL

Water level, 30% of the vertical dimension

10.50

WL

Water level, 40% of the vertical dimension

10.60

CUW

Loss of vision, camera under water

13.50

MHF

Finish node, manhole, reference: F1: Debris in Chamber

Depth: m

F1



Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

57




Section Pictures - 26/05/2021 - F12X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
28	Downstream	F12X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F12



2, 00:00:16, 2.10 m
Line deviates down



3, 00:00:39, 6.10 m
Line deviates right



4, 00:00:58, 9.50 m
Water level, 5% of the vertical dimension



5, 00:01:04, 9.90 m
Water level, 10% of the vertical dimension



6, 00:01:07, 10.20 m
Water level, 30% of the vertical dimension



Section Pictures - 26/05/2021 - F12X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
28	Downstream	F12X		



7, 00:01:12, 10.50 m
Water level, 40% of the vertical dimension



8, 00:01:15, 10.60 m
Loss of vision, camera under water



9, 00:01:26, 13.50 m
Finish node, manhole, reference: F1, Debris in Chamber



Section Inspection - 26/05/2021 - SP21X

Item No. 29	Insp. No. 1	Date 26/05/21	Time 10:43	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP21X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP21
Road:	Dappers Lane	Inspected Length:	6.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.20 m	Downstream Node:	F11
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:54 Position [m] Code Observation Grade

Depth: m

F11



0.00

MH

Start node, manhole, reference: F11

0.00

WL

Water level, 0% of the vertical dimension

0.90

WL

Water level, 5% of the vertical dimension

1.30

WL

Water level, 10% of the vertical dimension

2.30

WL

Water level, 5% of the vertical dimension

4.60

LL

Line deviates left

5.60

LU

Line deviates up

6.20

MHF

Finish node, manhole, reference: SP21

SP21

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0




Dappers Lane

60



Section Pictures - 26/05/2021 - SP21X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
29	Upstream	SP21X		

 1, 00:00:11, 0.00 m Water level, 0% of the vertical dimension	 2, 00:00:18, 0.90 m Water level, 5% of the vertical dimension
 3, 00:00:32, 1.30 m Water level, 10% of the vertical dimension	 4, 00:00:42, 2.30 m Water level, 5% of the vertical dimension
 5, 00:00:54, 4.60 m Line deviates left	 6, 00:01:04, 5.49 m Line deviates up



Section Pictures - 26/05/2021 - SP21X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
29	Upstream	SP21X		



7, 00:01:11, 6.20 m
Finish node, manhole, reference: SP21