



Section Inspection - 26/05/2021 - SP22X

Item No. 30	Insp. No. 1	Date 26/05/21	Time 10:45	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP22X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP22
Road:	Dappers Lane	Inspected Length:	13.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.10 m	Downstream Node:	F11
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:113 Position [m] Code Observation Grade

Depth: m

F11

0.00

MH

Start node, manhole, reference: F11

0.00

WL

Water level, 0% of the vertical dimension

1.50

LR

Line deviates right

10.10

LL

Line deviates left

12.40

LU

Line deviates up

13.10

MHF

Finish node, manhole, reference: SP22

SP22

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

Section Pictures - 26/05/2021 - SP22X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
30	Upstream	SP22X		



1, 00:00:09, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:22, 1.50 m
Line deviates right



3, 00:00:42, 10.10 m
Line deviates left



4, 00:00:52, 12.40 m
Line deviates up



5, 00:00:56, 13.10 m
Finish node, manhole, reference: SP22



Section Inspection - 26/05/2021 - F11X

Item No. 31	Insp. No. 1	Date 26/05/21	Time 10:48	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F11X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F11
Road:	Dappers Lane	Inspected Length:	10.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.00 m	Downstream Node:	F1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:87 Position [m] Code Observation Grade

Depth: m

F11



0.00

MH

Start node, manhole, reference: F11

0.00

WL

Water level, 0% of the vertical dimension

0.30

LL

Line deviates left

6.90

LR

Line deviates right

9.20

WL

Water level, 5% of the vertical dimension

9.30

WL

Water level, 10% of the vertical dimension

9.40

WL

Water level, 20% of the vertical dimension

10.00

MHF

Finish node, manhole, reference: F1: Debris in chamber

Depth: m

F1

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

65



Section Pictures - 26/05/2021 - F11X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
31	Downstream	F11X		



1, 00:00:05, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:09, 0.30 m
Line deviates left




3, 00:00:34, 6.90 m
Line deviates right



4, 00:00:51, 9.20 m
Water level, 5% of the vertical dimension



5, 00:01:01, 9.30 m
Water level, 10% of the vertical dimension




6, 00:01:05, 9.40 m
Water level, 20% of the vertical dimension



Section Pictures - 26/05/2021 - F11X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
31	Downstream	F11X		



7, 00:01:26, 10.00 m
Finish node, manhole, reference: F1, Debris in chamber



Section Inspection - 26/05/2021 - SP23X


Item No. 32	Insp. No. 1	Date 26/05/21	Time 11:01	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP23X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP23
Road:	Dappers Lane	Inspected Length:	0.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.80 m	Downstream Node:	F32
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


68

Section Pictures - 26/05/2021 - SP23X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
32	Upstream	SP23X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F32



2, 00:00:09, 0.40 m
Line deviates up



3, 00:00:13, 0.80 m
Finish node, manhole, reference: SP23



Section Inspection - 26/05/2021 - SP24X

Item No. 33	Insp. No. 1	Date 26/05/21	Time 11:02	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP24X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP24
Road:	Dappers Lane	Inspected Length:	3.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.20 m	Downstream Node:	F32
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:50	Position [m]	Code	Observation	Grade
		0.00	MH	Start node, manhole, reference: F32	
		0.00	WL	Water level, 0% of the vertical dimension	
		0.10	LR	Line deviates right	
		2.30	LR	Line deviates right	
		3.10	DEC	Settled deposits, hard or compacted, 100% cross-sectional area loss: Concrete	5
		3.20	SA	Survey abandoned: Possibly redundant	

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	10.0	3.1	10.0	5.0

Dappers Lane


70

Section Pictures - 26/05/2021 - SP24X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
33	Upstream	SP24X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F32



2, 00:00:18, 2.30 m
Line deviates right



3, 00:00:25, 3.10 m
Settled deposits, hard or compacted, 100% cross-sectional area loss, Concrete



4, 00:00:26, 3.20 m
Survey abandoned, Possibly redundant



Section Inspection - 26/05/2021 - F32X

Item No. 34	Insp. No. 1	Date 26/05/21	Time 11:03	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F32X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F32
Road:	Dappers Lane	Inspected Length:	7.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.70 m	Downstream Node:	F31
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:67 Position [m] Code Observation Grade

Depth: m

F32



0.00

MH

Start node, manhole, reference: F32

0.00

WL

Water level, 0% of the vertical dimension

7.60

LR

Line deviates right

7.70

MHF

Finish node, manhole, reference: F31

F31

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


72

Section Pictures - 26/05/2021 - F32X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
34	Downstream	F32X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F32



2, 00:00:32, 7.47 m
Line deviates right



3, 00:00:38, 7.70 m
Finish node, manhole, reference: F31



Section Inspection - 26/05/2021 - F31X

Item No. 35	Insp. No. 1	Date 26/05/21	Time 11:10	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F31X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F31
Road:	Dappers Lane	Inspected Length:	5.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.30 m	Downstream Node:	F14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F31



0.00

MH

Start node, manhole, reference: F31

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

1.40

WL

Water level, 5% of the vertical dimension

3.80

WL

Water level, 15% of the vertical dimension

4.30

WL

Water level, 20% of the vertical dimension

4.60

WL

Water level, 40% of the vertical dimension

5.10

LR

Line deviates right

5.30

MHF

Finish node, manhole, reference: F14

F14

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

74



Section Pictures - 26/05/2021 - F31X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
35	Downstream	F31X		



1, 00:00:01, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:10, 1.40 m
Water level, 5% of the vertical dimension




3, 00:00:29, 3.80 m
Water level, 15% of the vertical dimension



4, 00:00:36, 4.30 m
Water level, 20% of the vertical dimension



5, 00:00:44, 4.60 m
Water level, 40% of the vertical dimension



6, 00:00:54, 5.10 m
Line deviates right



Section Pictures - 26/05/2021 - F31X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
35	Downstream	F31X		



7, 00:01:00, 5.30 m
Finish node, manhole, reference: F14



Section Inspection - 26/05/2021 - F14X


Item No. 36	Insp. No. 1	Date 26/05/21	Time 11:18	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F14X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F14
Road:	Dappers Lane	Inspected Length:	1.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.00 m	Downstream Node:	F2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

77



Section Pictures - 26/05/2021 - F14X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
36	Downstream	F14X		



1, 00:00:00, 0.00 m
General photograph taken at this point, Water level in chamber



2, 00:00:06, 0.00 m
Start node, manhole, reference: F14



3, 00:00:19, 1.00 m
Survey abandoned, Dead stop, unable to continue



Section Inspection - 26/05/2021 - SP25X

Item No. 37	Insp. No. 1	Date 26/05/21	Time 11:28	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP25X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP25
Road:	Dappers Lane	Inspected Length:	7.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.80 m	Downstream Node:	F14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:68 Position [m] Code Observation Grade

Depth: m

F14



0.00

GP

General photograph taken at this point: Water level in chamber

0.00

CUW

Loss of vision, camera under water

0.00

MH

Start node, manhole, reference: F14

0.30

WL

Water level, 30% of the vertical dimension

1.00

WL

Water level, 10% of the vertical dimension

1.00

WL

Water level, 5% of the vertical dimension

1.20

WL

Water level, 0% of the vertical dimension

7.50

LU

Line deviates up

7.80

MHF

Finish node, manhole, reference: SP25

SP25

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

79

Section Pictures - 26/05/2021 - SP25X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
37	Upstream	SP25X		



1, 00:00:00, 0.00 m
General photograph taken at this point, Water level in chamber



2, 00:00:13, 0.00 m
Start node, manhole, reference: F14




3, 00:00:33, 0.90 m
Water level, 30% of the vertical dimension



4, 00:00:40, 1.00 m
Water level, 5% of the vertical dimension



5, 00:01:22, 7.50 m
Line deviates up



6, 00:01:27, 7.80 m
Finish node, manhole, reference: SP25



Section Inspection - 26/05/2021 - SP26X

Item No. 38	Insp. No. 1	Date 26/05/21	Time 12:31	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP26X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP26
Road:	Dappers Lane	Inspected Length:	15.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.10 m	Downstream Node:	F22
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:131 Position [m] Code Observation Grade

Depth: m

F22



0.00

MH

Start node, manhole, reference: F22

0.00

WL

Water level, 0% of the vertical dimension

7.20

LL

Line deviates left

14.60

LU

Line deviates up

15.10

MHF

Finish node, manhole, reference: SP26

SP26

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

81




Section Pictures - 26/05/2021 - SP26X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
38	Upstream	SP26X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F22



2, 00:00:25, 7.20 m
Line deviates left



3, 00:00:44, 14.60 m
Line deviates up



4, 00:00:55, 15.10 m
Finish node, manhole, reference: SP26



Section Inspection - 26/05/2021 - SP27X

Item No. 39	Insp. No. 1	Date 26/05/21	Time 12:33	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP27X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP27
Road:	Dappers Lane	Inspected Length:	7.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.40 m	Downstream Node:	F22
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:64 Position [m] Code Observation Grade

Depth: m

F22

0.00

MH

Start node, manhole, reference: F22

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

6.80

LR

Line deviates right

6.90

LU

Line deviates up

7.40

MHF

Finish node, manhole, reference: SP27

SP27

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

83



Section Pictures - 26/05/2021 - SP27X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
39	Upstream	SP27X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F22



2, 00:00:38, 6.80 m
Line deviates right



3, 00:00:45, 7.40 m
Finish node, manhole, reference: SP27



Section Inspection - 26/05/2021 - SP28X

Item No. 40	Insp. No. 1	Date 26/05/21	Time 12:36	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP28X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP28
Road:	Dappers Lane	Inspected Length:	11.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.70 m	Downstream Node:	F22
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:101 Position [m] Code Observation Grade

Depth: m

F22



0.00

MH

Start node, manhole, reference: F22

0.00

WL

Water level, 0% of the vertical dimension

11.30

LU

Line deviates up

11.70

MHF

Finish node, manhole, reference: SP28

SP28

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

85




Section Pictures - 26/05/2021 - SP28X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
40	Upstream	SP28X		



1, 00:00:10, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:48, 11.30 m
Line deviates up



3, 00:00:41, 11.70 m
Finish node, manhole, reference: SP28



Section Inspection - 26/05/2021 - F22X

Item No. 41	Insp. No. 1	Date 26/05/21	Time 12:38	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F22X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F22
Road:	Dappers Lane	Inspected Length:	8.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.60 m	Downstream Node:	F6
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:75 Position [m] Code Observation Grade

Depth: m

F22



0.00

MH

Start node, manhole, reference: F22

0.00

WL

Water level, 0% of the vertical dimension

0.50

LD

Line deviates down

6.50

LL

Line deviates left

8.60

MHF

Finish node, manhole, reference: F6: Buried under road

F6

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


87

Section Pictures - 26/05/2021 - F22X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
41	Downstream	F22X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: F22



2, 00:00:11, 0.50 m
Line deviates down



3, 00:00:46, 6.50 m
Line deviates left



4, 00:01:04, 8.60 m
Finish node, manhole, reference: F6, Buried under road



Section Inspection - 26/05/2021 - SP29X

Item No. 42	Insp. No. 1	Date 26/05/21	Time 13:13	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP29X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP29
Road:	Dappers Lane	Inspected Length:	14.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.00 m	Downstream Node:	F20
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:130 Position [m] Code Observation Grade

Depth: m

F20



0.00

REM

General remark: Water level in chamber

0.00

MH

Start node, manhole, reference: F20

0.00

CUW

Loss of vision, camera under water

6.20

WL

Water level, 50% of the vertical dimension

6.30

WL

Water level, 30% of the vertical dimension

6.50

WL

Water level, 20% of the vertical dimension

6.90

WL

Water level, 10% of the vertical dimension

7.30

LL

Line deviates left

14.50

LU

Line deviates up

14.80

MHF

Finish node, manhole, reference: SP29

SP29

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane



Section Pictures - 26/05/2021 - SP29X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
42	Upstream	SP29X		



1, 00:00:00, 0.00 m
General remark, Water level in chamber



2, 00:00:31, 0.00 m
Start node, manhole, reference: F20




3, 00:00:46, 6.20 m
Water level, 50% of the vertical dimension



4, 00:00:47, 6.30 m
Water level, 30% of the vertical dimension



5, 00:00:57, 6.90 m
Water level, 10% of the vertical dimension



6, 00:01:01, 7.30 m
Line deviates left




Section Pictures - 26/05/2021 - SP29X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
42	Upstream	SP29X		



7, 00:01:21, 14.50 m
Line deviates up



8, 00:01:42, 14.80 m
Finish node, manhole, reference: SP29



Section Inspection - 26/05/2021 - SP30X

Item No. 43	Insp. No. 1	Date 26/05/21	Time 13:35	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP30X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP30
Road:	Dappers Lane	Inspected Length:	11.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.90 m	Downstream Node:	F21
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:103 Position [m] Code Observation Grade

Depth: m

F21



0.00

MH

Start node, manhole, reference: F21

0.00

WL

Water level, 0% of the vertical dimension

3.80

LL

Line deviates left

4.00

LR

Line deviates right

7.00

LL

Line deviates left

11.40

LU

Line deviates up

11.90

MHF

Finish node, manhole, reference: SP30

SP30

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


92

Section Pictures - 26/05/2021 - SP30X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
43	Upstream	SP30X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F21



2, 00:00:23, 3.80 m
Line deviates left




3, 00:00:25, 4.00 m
Line deviates right



4, 00:00:36, 7.00 m
Line deviates left



5, 00:00:47, 11.40 m
Line deviates up



6, 00:00:51, 11.90 m
Finish node, manhole, reference: SP30



Section Inspection - 26/05/2021 - SP31X

Item No. 44	Insp. No. 1	Date 26/05/21	Time 13:37	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP31X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP31
Road:	Dappers Lane	Inspected Length:	4.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.20 m	Downstream Node:	F21
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F21



0.00

MH

Start node, manhole, reference: F21

0.00

WL

Water level, 0% of the vertical dimension

3.80

LU

Line deviates up

4.20

MHF

Finish node, manhole, reference: SP31

SP31

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


94

Section Pictures - 26/05/2021 - SP31X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
44	Upstream	SP31X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F21



2, 00:00:40, 3.60 m
Line deviates up



3, 00:00:48, 4.20 m
Finish node, manhole, reference: SP31



Section Inspection - 26/05/2021 - F21X

Item No. 45	Insp. No. 1	Date 26/05/21	Time 13:35	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F21X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F21
Road:	Dappers Lane	Inspected Length:	9.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	9.70 m	Downstream Node:	FA
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:84 Position [m] Code Observation Grade

Depth: m

F21



0.00

MH

Start node, manhole, reference: F21

0.00

WL

Water level, 0% of the vertical dimension

3.80

LL

Line deviates left

8.30

S01

DER

Settled deposits, coarse, 20% cross-sectional area loss, start

8.90

F01

DER

Settled deposits, coarse, 20% cross-sectional area loss, finish

4

8.90

DER

Settled deposits, coarse, 50% cross-sectional area loss

4

9.70

MHF

Finish node, manhole, reference: FA: Buried

Depth: m

FA

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	2	13.0	2.4	23.0	5.0

Dappers Lane


96

Section Pictures - 26/05/2021 - F21X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
45	Downstream	F21X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F21




2, 00:00:22, 3.80 m
Line deviates left



3, 00:00:38, 6.30 m
Settled deposits, coarse, 20% cross-sectional area loss, start



4, 00:00:02, 8.90 m
Settled deposits, coarse, 50% cross-sectional area loss



5, 00:01:07, 9.70 m
Finish node, manhole, reference: FA, Buried



Section Inspection - 26/05/2021 - SP32X

Item No. 46	Insp. No. 1	Date 26/05/21	Time 13:48	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP32X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP32
Road:	Dappers Lane	Inspected Length:	11.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.40 m	Downstream Node:	F21
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:99 Position [m] Code Observation Grade

Depth: m

F21



0.00

MH

Start node, manhole, reference: F21

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

10.00

LR

Line deviates right

10.70

LU

Line deviates up

11.40

MHF

Finish node, manhole, reference: SP32

SP32

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane




Section Pictures - 26/05/2021 - SP32X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
46	Upstream	SP32X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: F21



2, 00:00:41, 10.00 m
Line deviates right



3, 00:00:53, 10.70 m
Line deviates up



4, 00:00:57, 11.40 m
Finish node, manhole, reference: SP32



Section Inspection - 26/05/2021 - SP33X

Item No. 47	Insp. No. 1	Date 26/05/21	Time 14:02	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP33X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP33
Road:	Dappers Lane	Inspected Length:	7.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.40 m	Downstream Node:	F23
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:64 Position [m] Code Observation Grade

Depth: m

F23



0.00

MH

Start node, manhole, reference: F23

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

6.70

LU

Line deviates up

7.40

MHF

Finish node, manhole, reference: SP33

SP33

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

100



Section Pictures - 26/05/2021 - SP33X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
47	Upstream	SP33X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F23



2, 00:00:31, 6.70 m
Line deviates up



3, 00:00:36, 7.40 m
Finish node, manhole, reference: SP33



Section Inspection - 26/05/2021 - SP34X

Item No. 48	Insp. No. 1	Date 26/05/21	Time 14:05	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP34X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP34
Road:	Dappers Lane	Inspected Length:	7.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.20 m	Downstream Node:	F23
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:63 Position [m] Code Observation Grade

Depth: m

F23



0.00

MH

Start node, manhole, reference: F23

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

6.50

LU

Line deviates up

7.20

MHF

Finish node, manhole, reference: SP34

SP34

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

102

Section Pictures - 26/05/2021 - SP34X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
48	Upstream	SP34X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F23



2, 00:00:32, 6.90 m
Line deviates up



3, 00:00:38, 7.20 m
Finish node, manhole, reference: SP34



Section Inspection - 26/05/2021 - SP35X


Item No. 49	Insp. No. 1	Date 26/05/21	Time 14:07	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP35X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP35
Road:	Dappers Lane	Inspected Length:	2.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.50 m	Downstream Node:	F23
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

104



Section Pictures - 26/05/2021 - SP35X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
49	Upstream	SP35X		



1, 00:00:10, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:30, 2.40 m
Line deviates up



3, 00:00:37, 2.50 m
Finish node, manhole, reference: SP35



Section Inspection - 26/05/2021 - F23X

Item No. 50	Insp. No. 1	Date 26/05/21	Time 14:10	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F23X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F23
Road:	Dappers Lane	Inspected Length:	7.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.20 m	Downstream Node:	F25
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:63 Position [m] Code Observation Grade

Depth: m

F23

0.00

MH

Start node, manhole, reference: F23

0.00

WL

Water level, 0% of the vertical dimension

6.80

S01

DES

Settled deposits, fine, 15% cross-sectional area loss, start

6.80

C01

DES

Settled deposits, fine, 40% cross-sectional area loss, change

7.00

F01

DES

Settled deposits, fine, 40% cross-sectional area loss, finish

3

7.00

CUD

Loss of vision, silt

F25

7.20

MHF

Finish node, manhole, reference: F25: Debris in chamber

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.3	2.0	3.0

Dappers Lane

106

Section Pictures - 26/05/2021 - F23X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
50	Downstream	F23X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F23




2, 00:00:36, 6.60 m
Settled deposits, fine, 15% cross-sectional area loss, start



3, 00:00:40, 6.80 m
Settled deposits, fine, 40% cross-sectional area loss, change



4, 00:00:46, 7.00 m
Loss of vision, silt



5, 00:00:52, 7.20 m
Finish node, manhole, reference: F25, Debris in chamber