



Section Inspection - 27/05/2021 - LDX

Item No. 79	Insp. No. 1	Date 27/05/21	Time 12:08	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	14.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.10 m	Downstream Node:	S26
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:122 Position [m] Code Observation Grade

Depth: m

S26



0.00

MH

Start node, manhole, reference: S26

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

14.10

MHF

Finish node, manhole, reference: LD: Assumed end point

LD

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

168




Section Pictures - 27/05/2021 - LDX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
79	Upstream	LDX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S26



2, 00:01:03, 14.10 m
Finish node, manhole, reference: LD, Assumed end point



Section Inspection - 27/05/2021 - S26X

Item No. 80	Insp. No. 1	Date 27/05/21	Time 12:10	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S26X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S26
Road:	Dappers Lane	Inspected Length:	7.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.10 m	Downstream Node:	S27
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:62 Position [m] Code Observation Grade

Depth: m

S26



0.00

MH

Start node, manhole, reference: S26

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

7.10

MHF

Finish node, manhole, reference: S27

S27

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


170

Section Pictures - 27/05/2021 - S26X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
80	Downstream	S26X		



1, 00:00:01, 0.00 m
 Water level, 0% of the vertical dimension



2, 00:00:34, 7.10 m
 Finish node, manhole, reference: S27



Section Inspection - 27/05/2021 - S27X

Item No. 81	Insp. No. 1	Date 27/05/21	Time 12:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S27X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S27
Road:	Dappers Lane	Inspected Length:	11.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.70 m	Downstream Node:	S3
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:101 Position [m] Code Observation Grade

Depth: m

S27



0.00

MH

Start node, manhole, reference: S27

0.00

MH

Start node, manhole, reference: S27

0.10

S01

DER

Settled deposits, coarse, 15% cross-sectional area loss, start

1.50

JN

Junction at 10 o'clock, 100mm dia

7.00

F01

DER

Settled deposits, coarse, 15% cross-sectional area loss, finish

7.20

LL

Line deviates left

11.70

MHF

Finish node, manhole, reference: S3: Not accessible

S3

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


172

Section Pictures - 27/05/2021 - S27X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
81	Downstream	S27X		




1, 00:01:10, 0.00 m
Start node, manhole, reference: S27




2, 00:01:05, 0.10 m
Settled deposits, coarse, 15% cross-sectional area loss, start



3, 00:00:49, 1.50 m
Junction at 10 o'clock, 100mm dia



4, 00:00:23, 7.20 m
Line deviates left



5, 00:00:00, 11.70 m
Finish node, manhole, reference: S3, Not accessible



Section Inspection - 27/05/2021 - RWPX


Item No. 82	Insp. No. 1	Date 27/05/21	Time 13:00	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	2.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.50 m	Downstream Node:	S25
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

174




Section Pictures - 27/05/2021 - RWPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
82	Upstream	RWPX		



1, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:19, 2.00 m
Line deviates up



3, 00:00:30, 2.50 m
Finish node, manhole, reference: RWP



Section Inspection - 27/05/2021 - RE11X

Item No. 83	Insp. No. 1	Date 27/05/21	Time 13:02	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RE11X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RE11
Road:	Dappers Lane	Inspected Length:	12.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.20 m	Downstream Node:	S25
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:106 Position [m] Code Observation Grade

Depth: m

S25



0.00

MH

Start node, manhole, reference: S25

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

5.60

JN

Junction at 9 o'clock, 100mm dia

12.00

JN

Junction at 9 o'clock, 100mm dia

12.20

SA

Survey abandoned: Capped, rodding eye not installed

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

176



Section Pictures - 27/05/2021 - RE11X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
83	Upstream	RE11X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S25




2, 00:00:33, 5.60 m
Junction at 9 o'clock, 100mm dia



3, 00:00:54, 12.00 m
Junction at 9 o'clock, 100mm dia



4, 00:00:57, 12.20 m
Survey abandoned, Capped, rodding eye not installed



Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S25
Road:	Dappers Lane	Inspected Length:	10.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.10 m	Downstream Node:	S27
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		


Recommendations:

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.0	2.0	3.0



Section Pictures - 27/05/2021 - S25X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
84	Downstream	S25X		



1, 00:00:08, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:43, 9.90 m
Line deviates right



3, 00:00:46, 10.10 m
Finish node, manhole, reference: S27



Section Inspection - 27/05/2021 - S3X

Item No. 85	Insp. No. 1	Date 27/05/21	Time 14:01	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S3X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S3
Road:	Dappers Lane	Inspected Length:	20.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	20.50 m	Downstream Node:	S4
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:177 Position [m] Code Observation Grade

Depth: m

S4



0.00

MH

Start node, manhole, reference: S4

0.00

WL

Water level, 0% of the vertical dimension

0.60

WL

Water level, 5% of the vertical dimension

6.40

JN

Junction at 12 o'clock, 100mm dia

10.00

WL

Water level, 10% of the vertical dimension

10.30

JN

Junction at 10 o'clock, 100mm dia

11.40

WL

Water level, 5% of the vertical dimension

20.50

MHF

Finish node, manhole, reference: S3

S3

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

180




Section Pictures - 27/05/2021 - S3X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
85	Upstream	S3X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S4



2, 00:00:10, 0.60 m
Water level, 5% of the vertical dimension




3, 00:00:35, 6.40 m
Junction at 12 o'clock, 100mm dia



4, 00:00:55, 10.00 m
Water level, 10% of the vertical dimension



5, 00:00:59, 10.30 m
Junction at 10 o'clock, 100mm dia




6, 00:01:13, 11.40 m
Water level, 5% of the vertical dimension



Section Pictures - 27/05/2021 - S3X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
85	Upstream	S3X		



7, 00:01:45, 20.50 m
Finish node, manhole, reference: S3



Section Inspection - 27/05/2021 - S30X

Item No. 86	Insp. No. 1	Date 27/05/21	Time 14:29	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S30X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S30
Road:	Dappers Lane	Inspected Length:	16.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	16.50 m	Downstream Node:	S29
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:143 Position [m] Code Observation Grade

Depth: m

S29



0.00

MH

Start node, manhole, reference: S29

0.00

WL

Water level, 0% of the vertical dimension

1.20

JN

Junction at 3 o'clock, 100mm dia

6.70

JN

Junction at 3 o'clock, 100mm dia

12.50

JN

Junction at 3 o'clock, 100mm dia

16.50

MHF

Finish node, manhole, reference: S30

S30

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

183



Section Pictures - 27/05/2021 - S30X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
86	Upstream	S30X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S29



2, 00:00:13, 1.20 m
Junction at 3 o'clock, 100mm dia



3, 00:00:35, 6.70 m
Junction at 3 o'clock, 100mm dia



4, 00:00:53, 12.50 m
Junction at 3 o'clock, 100mm dia



5, 00:01:07, 16.50 m
Finish node, manhole, reference: S30



Section Inspection - 27/05/2021 - LDX

Item No. 87	Insp. No. 1	Date 27/05/21	Time 14:33	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	16.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	16.00 m	Downstream Node:	S29
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:136 Position [m] Code Observation Grade

Depth: m

S29



0.00

MH

Start node, manhole, reference: S29

0.00

WL

Water level, 0% of the vertical dimension

2.80

LR

Line deviates right

15.80

DER

Settled deposits, coarse, 100% cross-sectional area loss

5

16.00

MHF

Finish node, manhole, reference: LD: Assumed end point

LD

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	10.0	0.6	10.0	5.0

Dappers Lane

185

Section Pictures - 27/05/2021 - LDX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
87	Upstream	LDX		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S29



2, 00:00:22, 2.80 m
Line deviates right



3, 00:00:55, 15.80 m
Settled deposits, coarse, 100% cross-sectional area loss



4, 00:00:59, 16.00 m
Finish node, manhole, reference: LD, Assumed end point


Section Inspection - 27/05/2021 - RWPX

Item No. 88	Insp. No. 1	Date 27/05/21	Time 14:38	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	8.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	8.60 m	Downstream Node:	S29
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale:	1:75	Position [m]	Code	Observation	Grade
Depth: m S29 					
		0.00	MH	Start node, manhole, reference: S29	
		0.00	WL	Water level, 0% of the vertical dimension	
		0.10	LL	Line deviates left	
		0.10	WL	Water level, 5% of the vertical dimension	
		0.60	LL	Line deviates left	
		1.10	WL	Water level, 10% of the vertical dimension	
		2.60	WL	Water level, 5% of the vertical dimension	
		3.50	WL	Water level, 0% of the vertical dimension	
		7.00	LR	Line deviates right	
		8.20	LU	Line deviates up	
		8.60	MHF	Finish node, manhole, reference: RWP	
					Depth: m RWP

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

187



Section Pictures - 27/05/2021 - RWPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
88	Upstream	RWPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S29



2, 00:00:13, 0.10 m
Water level, 5% of the vertical dimension




3, 00:00:18, 0.60 m
Line deviates left



4, 00:00:23, 1.10 m
Water level, 10% of the vertical dimension



5, 00:00:35, 2.80 m
Water level, 5% of the vertical dimension




6, 00:00:38, 3.50 m
Water level, 0% of the vertical dimension



Section Pictures - 27/05/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
88	Upstream	RWPX		



7, 00:00:51, 7.00 m
Line deviates right



8, 00:00:55, 8.20 m
Line deviates up



9, 00:01:09, 8.60 m
Finish node, manhole, reference: RWP



Section Inspection - 27/05/2021 - S29X

Item No. 89	Insp. No. 1	Date 27/05/21	Time 14:44	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S29X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S29
Road:	Dappers Lane	Inspected Length:	12.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.60 m	Downstream Node:	S31
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:109 Position [m] Code Observation Grade

Depth: m

S29



0.00

MH

Start node, manhole, reference: S29

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

8.40

S01

DER

Settled deposits, coarse, 10% cross-sectional area loss, start

8.90

F01

DER

Settled deposits, coarse, 10% cross-sectional area loss, finish

3

9.00

JN

Junction at 10 o'clock, 100mm dia

11.40

S02

DES

Settled deposits, fine, 10% cross-sectional area loss, start

12.20

LR

Line deviates right

12.60

F02

DES

Settled deposits, fine, 10% cross-sectional area loss, finish

3

12.60

MHF

Finish node, manhole, reference: S31

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	2	2.0	0.5	6.0	3.0

Dappers Lane

190

Section Pictures - 27/05/2021 - S29X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
89	Downstream	S29X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S29




2, 00:00:33, 8.40 m
Settled deposits, coarse, 10% cross-sectional area loss, start



3, 00:00:36, 9.00 m
Junction at 10 o'clock, 100mm dia



4, 00:00:50, 11.40 m
Settled deposits, fine, 10% cross-sectional area loss, start



5, 00:00:57, 12.20 m
Line deviates right



6, 00:01:05, 12.60 m
Finish node, manhole, reference: S31



Section Inspection - 27/05/2021 - RWPX


Item No. 90	Insp. No. 1	Date 27/05/21	Time 15:00	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	2.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.60 m	Downstream Node:	S30
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

192



Section Pictures - 27/05/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
90	Upstream	RWPX		



1, 00:00:11, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:11, 0.10 m
Junction at 3 o'clock, 100mm dia



3, 00:00:21, 0.40 m
Water level, 5% of the vertical dimension



4, 00:00:32, 1.60 m
Water level, 10% of the vertical dimension



5, 00:00:35, 1.90 m
Line deviates right



6, 00:01:15, 2.20 m
Line deviates up



Section Pictures - 27/05/2021 - RWPX

Item No.
90

Inspection Direction
Upstream

PLR
RWPX

Client's Job Ref

Contractor's Job Ref



7, 00:01:03, 2.60 m
Finish node, manhole, reference: RWP



Section Inspection - 27/05/2021 - ACOX

Item No. 91	Insp. No. 1	Date 27/05/21	Time 15:17	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR ACOX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	ACO
Road:	Dappers Lane	Inspected Length:	3.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.10 m	Downstream Node:	S31
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S31

0.00

MH

Start node, manhole, reference: S31

0.00

WL

Water level, 0% of the vertical dimension

2.50

LU

Line deviates up

3.10

MHF

Finish node, manhole, reference: ACO

ACO

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


195

Section Pictures - 27/05/2021 - ACOX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
91	Upstream	ACOX		



1, 00:00:05, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:26, 2.50 m
Line deviates up



3, 00:00:33, 3.10 m
Finish node, manhole, reference: ACO



Section Inspection - 27/05/2021 - S31X

Item No. 92	Insp. No. 1	Date 27/05/21	Time 15:21	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S31X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S31
Road:	Dappers Lane	Inspected Length:	7.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.40 m	Downstream Node:	S3
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:64 Position [m] Code Observation Grade

Depth: m

S31



0.00

MH

Start node, manhole, reference: S31

0.00

WL

Water level, 10% of the vertical dimension

0.30

WL

Water level, 30% of the vertical dimension

1.00

CUW

Loss of vision, camera under water

4.50

WL

Water level, 30% of the vertical dimension

5.00

WL

Water level, 10% of the vertical dimension

7.00

WL

Water level, 0% of the vertical dimension

7.40

MHF

Finish node, manhole, reference: S3: Not accessible

S3

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Dappers Lane

197



Section Pictures - 27/05/2021 - S31X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
92	Downstream	S31X		

	
1, 00:00:00, 0.00 m Start node, manhole, reference: S31	2, 00:00:09, 0.30 m Water level, 30% of the vertical dimension
	
3, 00:00:11, 1.00 m Loss of vision, camera under water	4, 00:00:27, 4.50 m Water level, 30% of the vertical dimension
	
5, 00:00:46, 5.00 m Water level, 10% of the vertical dimension	6, 00:01:03, 7.40 m Finish node, manhole, reference: S3, Not accessible



Section Inspection - 27/05/2021 - S14X

Item No. 93	Insp. No. 1	Date 27/05/21	Time 15:24	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S14X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S14
Road:	Dappers Lane	Inspected Length:	18.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	18.00 m	Downstream Node:	S31
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:156 Position [m] Code Observation Grade

Depth: m

S31



0.00

MH

Start node, manhole, reference: S31

0.00

WL

Water level, 0% of the vertical dimension

0.10

WL

Water level, 5% of the vertical dimension

0.30

WL

Water level, 10% of the vertical dimension

0.90

WL

Water level, 15% of the vertical dimension

2.00

WL

Water level, 10% of the vertical dimension

6.00

WL

Water level, 5% of the vertical dimension

14.20

JN

Junction at 9 o'clock, 100mm dia

17.80

LL

Line deviates left

18.00

MHF

Finish node, manhole, reference: S14

S14

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

199



Section Pictures - 27/05/2021 - S14X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
93	Upstream	S14X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S31




2, 00:00:07, 0.10 m
Water level, 5% of the vertical dimension




3, 00:00:14, 0.30 m
Water level, 10% of the vertical dimension



4, 00:00:20, 0.90 m
Water level, 15% of the vertical dimension




5, 00:00:28, 2.00 m
Water level, 10% of the vertical dimension



6, 00:00:44, 6.00 m
Water level, 5% of the vertical dimension

Section Pictures - 27/05/2021 - S14X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
93	Upstream	S14X		



7, 00:01:01, 14.20 m
Junction at 9 o'clock, 100mm dia



8, 00:01:16, 17.90 m
Line deviates left



9, 00:01:22, 18.00 m
Finish node, manhole, reference: S14



Section Inspection - 28/05/2021 - RWPX

Item No. 94	Insp. No. 1	Date 28/05/21	Time 8:47	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	4.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.50 m	Downstream Node:	S14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S14



0.00

MH

Start node, manhole, reference: S14

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

4.10

LU

Line deviates up

4.50

MHF

Finish node, manhole, reference: RWP

RWP

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

202




Section Pictures - 28/05/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
94	Upstream	RWPX		



1, 00:00:09, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:32, 4.10 m
Line deviates up



3, 00:00:37, 4.50 m
Finish node, manhole, reference: RWP



Section Inspection - 28/05/2021 - RWP2X

Item No. 95	Insp. No. 1	Date 28/05/21	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWP2X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP2
Road:	Dappers Lane	Inspected Length:	4.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.20 m	Downstream Node:	S14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S14



0.00

MH

Start node, manhole, reference: S14

0.00

WL

Water level, 5% of the vertical dimension

0.20

WL

Water level, 10% of the vertical dimension

1.50

WL

Water level, 5% of the vertical dimension

1.60

WL

Water level, 0% of the vertical dimension

3.70

LU

Line deviates up

4.20

MHF

Finish node, manhole, reference: RWP2

RWP2

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

204



Section Pictures - 28/05/2021 - RWP2X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
95	Upstream	RWP2X		




1, 00:00:04, 0.00 m
Water level, 5% of the vertical dimension




2, 00:00:11, 0.20 m
Water level, 10% of the vertical dimension



3, 00:00:27, 1.50 m
Water level, 5% of the vertical dimension



4, 00:00:32, 1.60 m
Water level, 0% of the vertical dimension



5, 00:00:43, 3.70 m
Line deviates up



6, 00:00:48, 4.20 m
Finish node, manhole, reference: RWP2



Section Inspection - 28/05/2021 - LDX

Item No. 96	Insp. No. 1	Date 28/05/21	Time 9:06	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	14.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.50 m	Downstream Node:	S32
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:


Scale: 1:91	Position [m]	Code	Observation	Grade
Depth: m 				
	0.00	MH	Start node, manhole, reference: S32	
	0.00	WL	Water level, 0% of the vertical dimension	
	0.10	LL	Line deviates left	
	4.10	WL	Water level, 5% of the vertical dimension	
	4.70	WL	Water level, 0% of the vertical dimension	
	5.80	WL	Water level, 5% of the vertical dimension	
	6.70	WL	Water level, 10% of the vertical dimension	
	6.90	WL	Water level, 30% of the vertical dimension	
	7.30	WL	Water level, 50% of the vertical dimension	
	7.50	CUW	Loss of vision, camera under water	
	8.10	WL	Water level, 50% of the vertical dimension	
	8.20	WL	Water level, 30% of the vertical dimension	
	8.50	WL	Water level, 50% of the vertical dimension	
	8.60	CUW	Loss of vision, camera under water	
	10.40	WL	Water level, 30% of the vertical dimension	

Section Pictures - 28/05/2021 - LDX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
96	Upstream	LDX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S32




2, 00:00:40, 4.10 m
Water level, 5% of the vertical dimension




3, 00:00:45, 4.70 m
Water level, 0% of the vertical dimension



4, 00:00:52, 5.80 m
Water level, 5% of the vertical dimension




5, 00:00:58, 6.70 m
Water level, 10% of the vertical dimension




6, 00:01:02, 6.90 m
Water level, 30% of the vertical dimension

Section Pictures - 28/05/2021 - LDX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
96	Upstream	LDX		




7, 00:01:06, 7.30 m
Water level, 50% of the vertical dimension




8, 00:01:10, 7.50 m
Loss of vision, camera under water




9, 00:01:16, 8.10 m
Water level, 50% of the vertical dimension



10, 00:01:23, 8.20 m
Water level, 30% of the vertical dimension




11, 00:01:25, 8.50 m
Water level, 50% of the vertical dimension




12, 00:01:27, 8.60 m
Loss of vision, camera under water

Section Pictures - 28/05/2021 - LDX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
96	Upstream	LDX		



13, 00:01:54, 10.40 m
Water level, 30% of the vertical dimension



14, 00:01:59, 10.60 m
Water level, 10% of the vertical dimension




15, 00:02:02, 10.80 m
Water level, 0% of the vertical dimension



16, 00:02:12, 13.50 m
Water level, 5% of the vertical dimension



17, 00:02:17, 14.00 m
Water level, 20% of the vertical dimension



18, 00:02:30, 14.50 m
Finish node, manhole, reference: Land Drain, Assumed end point



Section Inspection - 28/05/2021 - RE14X

Item No. 97	Insp. No. 1	Date 28/05/21	Time 9:08	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RE14X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RE14
Road:	Dappers Lane	Inspected Length:	14.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.60 m	Downstream Node:	S32
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:126 Position [m] Code Observation Grade

Depth: m

S32

0.00

MH Start node, manhole, reference: S32

0.00

WL Water level, 0% of the vertical dimension

0.10

LL Line deviates left

3.60

JN Junction at 9 o'clock, 100mm dia

8.30

JN Junction at 9 o'clock, 100mm dia

13.60

JN Junction at 9 o'clock, 100mm dia

13.60

LU Line deviates up

14.60

MHF Finish node, manhole, reference: RE14

RE14
Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

211




Section Pictures - 28/05/2021 - RE14X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
97	Upstream	RE14X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S32



2, 00:00:18, 3.60 m
Junction at 9 o'clock, 100mm dia




3, 00:00:31, 8.30 m
Junction at 9 o'clock, 100mm dia



4, 00:00:43, 13.60 m
Junction at 9 o'clock, 100mm dia



5, 00:00:47, 13.60 m
Line deviates up



6, 00:00:54, 14.60 m
Finish node, manhole, reference: RE14