



Section Inspection - 28/05/2021 - RWPX


Item No. 98	Insp. No. 1	Date 28/05/21	Time 9:13	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	1.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.40 m	Downstream Node:	S32
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

213




Section Pictures - 28/05/2021 - RWPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
98	Upstream	RWPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S32



2, 00:00:11, 0.80 m
Line deviates up



3, 00:00:16, 1.40 m
Finish node, manhole, reference: RWP



Section Inspection - 28/05/2021 - S32X

Item No. 99	Insp. No. 1	Date 28/05/21	Time 9:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S32X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S32
Road:	Dappers Lane	Inspected Length:	12.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	12.60 m	Downstream Node:	S32A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:109	Position [m]	Code	Observation	Grade
Depth: m				
S32				
0.00		MH	Start node, manhole, reference: S32	
0.00		WL	Water level, 0% of the vertical dimension	
0.20		LR	Line deviates right	
0.60		DER	Settled deposits, coarse, 10% cross-sectional area loss	3
1.60		JN	Junction at 3 o'clock, 100mm dia	
8.90		JN	Junction at 3 o'clock, 100mm dia	
12.60		MHF	Finish node, manhole, reference: S32A	
S32A				
Depth: m				

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations




STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.0	2.0	3.0

Dappers Lane

215

Section Pictures - 28/05/2021 - S32X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
99	Downstream	S32X		

 Dappers Lane Sec99	 Dappers Lane Sec99
1, 00:00:00, 0.00 m Start node, manhole, reference: S32	2, 00:00:06, 0.20 m Line deviates right
 Dappers Lane Sec99	 Dappers Lane Sec99
3, 00:00:12, 0.60 m Settled deposits, coarse, 10% cross-sectional area loss	4, 00:00:17, 1.60 m Junction at 3 o'clock, 100mm dia
 Dappers Lane Sec99	 Dappers Lane Sec99
5, 00:00:33, 8.90 m Junction at 3 o'clock, 100mm dia	6, 00:00:44, 12.60 m Finish node, manhole, reference: S32A



Section Inspection - 28/05/2021 - S32AX

Item No. 100	Insp. No. 1	Date 28/05/21	Time 9:24	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S32AX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S32A
Road:	Dappers Lane	Inspected Length:	2.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.30 m	Downstream Node:	S6
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S32A



0.00

MH

Start node, manhole, reference: S32A

0.00

WL

Water level, 0% of the vertical dimension

2.30

MHF

Finish node, manhole, reference: S6

S6

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

217




Section Pictures - 28/05/2021 - S32AX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
100	Downstream	S32AX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S32A



2, 00:00:18, 2.30 m
Finish node, manhole, reference: S6



Section Inspection - 28/05/2021 - S4X

Item No. 101	Insp. No. 1	Date 28/05/21	Time 9:47	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S4X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S4
Road:	Dappers Lane	Inspected Length:	21.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	21.50 m	Downstream Node:	S5
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:186 Position [m] Code Observation Grade

Depth: m

S4

0.00

MH

Start node, manhole, reference: S4

0.00

WL

Water level, 0% of the vertical dimension

10.30

WL

Water level, 5% of the vertical dimension

15.10

WL

Water level, 0% of the vertical dimension

21.50

MHF

Finish node, manhole, reference: S5

S5

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

219

Section Pictures - 28/05/2021 - S4X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
101	Downstream	S4X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S4



2, 00:00:55, 10.30 m
Water level, 5% of the vertical dimension



3, 00:01:28, 15.10 m
Water level, 0% of the vertical dimension



4, 00:02:00, 21.50 m
Finish node, manhole, reference: S5



Section Inspection - 28/05/2021 - S5X

Item No. 102	Insp. No. 1	Date 28/05/21	Time 10:21	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S5X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S5
Road:	Dappers Lane	Inspected Length:	14.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.10 m	Downstream Node:	S6
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:122 Position [m] Code Observation Grade

Depth: m

S5

0.00

MH

Start node, manhole, reference: S5

0.00

WL

Water level, 0% of the vertical dimension

5.80

WL

Water level, 5% of the vertical dimension

7.90

WL

Water level, 0% of the vertical dimension

10.50

WL

Water level, 5% of the vertical dimension

10.90

WL

Water level, 10% of the vertical dimension

11.20

WL

Water level, 20% of the vertical dimension

11.50

WL

Water level, 30% of the vertical dimension

12.10

CUW

Loss of vision, camera under water

14.10

MHF

Finish node, manhole, reference: S6: High water level in catch pit

Depth: m

S6

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


221

Section Pictures - 28/05/2021 - S5X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
102	Downstream	S5X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S5



2, 00:00:48, 5.80 m
Water level, 5% of the vertical dimension




3, 00:01:03, 7.90 m
Water level, 0% of the vertical dimension



4, 00:01:16, 10.50 m
Water level, 5% of the vertical dimension



5, 00:01:21, 10.90 m
Water level, 10% of the vertical dimension



6, 00:01:24, 11.20 m
Water level, 20% of the vertical dimension



Section Pictures - 28/05/2021 - S5X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
102	Downstream	S5X		



7, 00:01:27, 11.50 m
Water level, 30% of the vertical dimension



8, 00:01:33, 12.10 m
Loss of vision, camera under water



9, 00:02:03, 14.10 m
Finish node, manhole, reference: S6, High water level in catch pit



Section Inspection - 28/05/2021 - S36X

Item No. 103	Insp. No. 1	Date 28/05/21	Time 10:35	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S36X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S36
Road:	Dappers Lane	Inspected Length:	7.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.00 m	Downstream Node:	S6
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:61 Position [m] Code Observation Grade

Depth: m

S6



0.00

MH

Start node, manhole, reference: S6

0.00

WL

Water level, 0% of the vertical dimension

7.00

MHF

Finish node, manhole, reference: S36



S36

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

224



Section Pictures - 28/05/2021 - S36X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
103	Upstream	S36X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S6



2, 00:00:41, 7.00 m
Finish node, manhole, reference: S36



Section Inspection - 28/05/2021 - S7X

Item No. 104	Insp. No. 1	Date 28/05/21	Time 11:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S7X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S7
Road:	Dappers Lane	Inspected Length:	10.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.00 m	Downstream Node:	S8
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:87 Position [m] Code Observation Grade

Depth: m

S8



0.00

MH

Start node, manhole, reference: S8

0.70

LP

Line deviates right

1.30

WL

Water level, 10% of the vertical dimension

3.00

WL

Water level, 5% of the vertical dimension

3.40

LP

Line deviates right

3.70

WL

Water level, 0% of the vertical dimension

7.10

WL

Water level, 10% of the vertical dimension

7.40

WL

Water level, 15% of the vertical dimension

7.90

CUW

Loss of vision, camera under water

10.00

MHF

Finish node, manhole, reference: S7: Buried under road

S7

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


226

Section Pictures - 28/05/2021 - S7X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
104	Upstream	S7X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S8




2, 00:00:12, 0.70 m
Line deviates right




3, 00:00:21, 1.30 m
Water level, 10% of the vertical dimension



4, 00:00:34, 3.00 m
Water level, 5% of the vertical dimension



5, 00:00:34, 3.40 m
Line deviates right



6, 00:00:50, 7.10 m
Water level, 10% of the vertical dimension




Section Pictures - 28/05/2021 - S7X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
104	Upstream	S7X		



7, 00:00:53, 7.40 m
Water level, 15% of the vertical dimension



8, 00:00:56, 7.90 m
Loss of vision, camera under water



9, 00:01:29, 10.00 m
Finish node, manhole, reference: S7, Buried under road



Section Inspection - 28/05/2021 - RGX

Item No. 105	Insp. No. 1	Date 28/05/21	Time 11:37	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RGX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RG
Road:	Dappers Lane	Inspected Length:	6.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.70 m	Downstream Node:	S8
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S8

0.00

MH

Start node, manhole, reference: S8

0.00

WL

Water level, 0% of the vertical dimension

0.90

S01

DES

Settled deposits, fine, 10% cross-sectional area loss, start

1.50

LR

Line deviates right

3.40

C01

DES

Settled deposits, fine, 20% cross-sectional area loss, change

6.70

F01

DES

Settled deposits, fine, 20% cross-sectional area loss, finish

3

6.70

MHF

Finish node, manhole, reference: RG: Debris in gully

RG

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	1.8	12.0	3.0

Dappers Lane


229

Section Pictures - 28/05/2021 - RGX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
105	Upstream	RGX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S8



2, 00:00:09, 0.90 m
Settled deposits, fine, 10% cross-sectional area loss, start



3, 00:00:12, 1.50 m
Line deviates right



4, 00:00:20, 3.40 m
Settled deposits, fine, 20% cross-sectional area loss, change



5, 00:00:41, 6.70 m
Finish node, manhole, reference: RG, Debris in gully



Section Inspection - 28/05/2021 - RG2X

Item No. 106	Insp. No. 1	Date 28/05/21	Time 11:41	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RG2X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RG2
Road:	Dappers Lane	Inspected Length:	11.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	11.60 m	Downstream Node:	S8
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:100 Position [m] Code Observation Grade

Depth: m

S8



0.00

MH

Start node, manhole, reference: S8

0.00

WL

Water level, 0% of the vertical dimension

11.60

MHF

Finish node, manhole, reference: RG2

RG2

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	0.0	0.0	2.0	1.0

Dappers Lane

231




Section Pictures - 28/05/2021 - RG2X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
106	Upstream	RG2X		



1, 00:00:04, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:42, 11.60 m
Finish node, manhole, reference: RG2



Section Inspection - 28/05/2021 - S8X

Item No. 107	Insp. No. 1	Date 28/05/21	Time 11:53	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S8X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S8
Road:	Dappers Lane	Inspected Length:	13.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.20 m	Downstream Node:	S9
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	300 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:114 Position [m] Code Observation Grade

Depth: m

S8



0.00

MH

Start node, manhole, reference: S8

0.00

WL

Water level, 0% of the vertical dimension

2.00

WL

Water level, 5% of the vertical dimension

2.40

WL

Water level, 10% of the vertical dimension

13.20

MHF

Finish node, manhole, reference: S9

S9

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


233

Section Pictures - 28/05/2021 - S8X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
107	Downstream	S8X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S8



2, 00:00:15, 2.00 m
Water level, 5% of the vertical dimension



3, 00:00:17, 2.40 m
Water level, 10% of the vertical dimension



4, 00:00:44, 13.20 m
Finish node, manhole, reference: S9



Section Inspection - 28/05/2021 - S9X

Item No. 108	Insp. No. 1	Date 28/05/21	Time 12:02	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S9X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S9
Road:	Dappers Lane	Inspected Length:	4.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	4.60 m	Downstream Node:	AT2
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	300 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S9



0.00

MH

Start node, manhole, reference: S9

0.00

WL

Water level, 0% of the vertical dimension

1.70

WL

Water level, 5% of the vertical dimension

3.40

LL

Line deviates left

4.60

MHF

Finish node, manhole, reference: AT2

AT2

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

235




Section Pictures - 28/05/2021 - S9X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
108	Downstream	S9X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S9



2, 00:00:15, 1.70 m
Water level, 5% of the vertical dimension



3, 00:00:28, 3.40 m
Line deviates left



4, 00:00:38, 4.60 m
Finish node, manhole, reference: AT2



Section Inspection - 28/05/2021 - S9X

Item No. 109	Insp. No. 1	Date 28/05/21	Time 12:17	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S9X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S9
Road:	Dappers Lane	Inspected Length:	19.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	19.70 m	Downstream Node:	S10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	300 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:170 Position [m] Code Observation Grade

Depth: m

S9



0.00

MH

Start node, manhole, reference: S9

7.80

WL

Water level, 10% of the vertical dimension

8.20

CUW

Loss of vision, camera under water

15.10

WL

Water level, 20% of the vertical dimension

16.30

WL

Water level, 5% of the vertical dimension

16.40

S01

DES

Settled deposits, fine, 20% cross-sectional area loss, start

19.50

F01

DES

Settled deposits, fine, 20% cross-sectional area loss, finish

4

19.70

Depth: m

S10

MHF

Finish node, manhole, reference: S10

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations



STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	5.0	1.0	20.0	4.0

Dappers Lane

237

Section Pictures - 28/05/2021 - S9X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
109	Downstream	S9X		

	
1, 00:00:00, 0.00 m Start node, manhole, reference: S9	2, 00:01:07, 7.80 m Water level, 10% of the vertical dimension
	
3, 00:01:14, 8.20 m Loss of vision, camera under water	4, 00:01:54, 15.10 m Water level, 20% of the vertical dimension
	
5, 00:01:51, 16.40 m Settled deposits, fine, 20% cross-sectional area loss, start	6, 00:01:40, 19.70 m Finish node, manhole, reference: S10



Section Inspection - 28/05/2021 - LDX

Item No. 110	Insp. No. 1	Date 28/05/21	Time 12:30	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	31.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	31.60 m	Downstream Node:	S34
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:273 Position [m] Code Observation Grade

Depth: m

S34



0.00

MH

Start node, manhole, reference: S34

0.00

WL

Water level, 0% of the vertical dimension

11.00

JN

Junction at 12 o'clock, 100mm dia

31.20

D

Deformed sewer or drain, 40%

S / 4

31.60

SA

Survey abandoned: Unable to continue

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
1	165.0	5.2	165.0	5.0	1	5.0	0.2	5.0	4.0

Dappers Lane

239




Section Pictures - 28/05/2021 - LDX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
110	Upstream	LDX		




1, 00:00:01, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:49, 11.00 m
Junction at 12 o'clock, 100mm dia



3, 00:02:07, 31.20 m
Deformed sewer or drain, 40%



4, 00:02:12, 31.60 m
Survey abandoned, Unable to continue

Section Inspection - 28/05/2021 - S33X

Item No. 111	Insp. No. 1	Date 28/05/21	Time 12:45	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S33X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S33
Road:	Dappers Lane	Inspected Length:	21.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	21.70 m	Downstream Node:	S34
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:186	Position [m]	Code	Observation	Grade
Depth: m				
S34				
0.00		MH	Start node, manhole, reference: S34	
0.00		WL	Water level, 0% of the vertical dimension	
0.40		LL	Line deviates left	
2.60		JN	Junction at 9 o'clock, 100mm dia	
8.60		OBM	Other obstacles, pipe material in invert from 4 o'clock to 7 o'clock, 5% cross-sectional area loss	5
8.70		JN	Junction at 9 o'clock, 100mm dia	
12.80		DER	Settled deposits, coarse, 15% cross-sectional area loss	3
14.10		JN	Junction at 9 o'clock, 100mm dia	
19.70		JN	Junction at 9 o'clock, 100mm dia	
20.90		LU	Line deviates up	
21.70		REF	Finish node, rodding eye, reference: S33	
S33				
Depth: m				

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	2	10.0	0.6	12.0	5.0


Dappers Lane

241




Section Pictures - 28/05/2021 - S33X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
111	Upstream	S33X		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S34



2, 00:00:12, 0.40 m
Line deviates left



3, 00:00:24, 2.60 m
Junction at 9 o'clock, 100mm dia



4, 00:00:39, 8.60 m
Other obstacles, pipe material in invert from 4 o'clock to 7 o'clock, 5% cross-sectional area loss



5, 00:02:04, 13.90 m
Settled deposits, coarse, 15% cross-sectional area loss




6, 00:02:04, 14.10 m
Junction at 9 o'clock, 100mm dia



Section Pictures - 28/05/2021 - S33X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
111	Upstream	S33X		



7, 00:01:13, 19.70 m
Junction at 9 o'clock, 100mm dia



8, 00:01:27, 20.90 m
Line deviates up



9, 00:01:21, 21.70 m
Finish node, rodding eye, reference: S33



Section Inspection - 28/05/2021 - S34X

Item No. 112	Insp. No. 1	Date 28/05/21	Time 12:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S34X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S34
Road:	Dappers Lane	Inspected Length:	10.70 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.70 m	Downstream Node:	S10A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:93 Position [m] Code Observation Grade

Depth: m

S34



0.00

MH

Start node, manhole, reference: S34

0.00

WL

Water level, 10% of the vertical dimension: Live

0.10

LR

Line deviates right

0.20

WL

Water level, 20% of the vertical dimension: Live

2.00

WL

Water level, 40% of the vertical dimension

2.50

CUW

Loss of vision, camera under water

9.10

WL

Water level, 30% of the vertical dimension

9.40

WL

Water level, 20% of the vertical dimension

10.10

WL

Water level, 10% of the vertical dimension

10.70

MHF

Finish node, manhole, reference: S10A

S10A

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

244

Section Pictures - 28/05/2021 - S34X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
112	Downstream	S34X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S34



2, 00:00:11, 0.20 m
Water level, 20% of the vertical dimension, Live



3, 00:00:24, 2.00 m
Water level, 40% of the vertical dimension



4, 00:00:29, 2.80 m
Loss of vision, camera under water



5, 00:00:48, 9.10 m
Water level, 30% of the vertical dimension



6, 00:00:51, 9.40 m
Water level, 20% of the vertical dimension




Section Pictures - 28/05/2021 - S34X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
112	Downstream	S34X		



7, 00:00:56, 10.10 m
Water level, 10% of the vertical dimension



8, 00:01:00, 10.70 m
Finish node, manhole, reference: S10A



Section Inspection - 28/05/2021 - S10AX

Item No. 113	Insp. No. 1	Date 28/05/21	Time 12:51	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S10AX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S10A
Road:	Dappers Lane	Inspected Length:	5.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.30 m	Downstream Node:	S10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	150 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S10A



0.00

MH

Start node, manhole, reference: S10A

0.00

WL

Water level, 10% of the vertical dimension

0.30

LR

Line deviates right

5.30

MHF

Finish node, manhole, reference: S10

S10

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


247

Section Pictures - 28/05/2021 - S10AX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
113	Downstream	S10AX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S10A



2, 00:00:07, 0.30 m
Line deviates right



3, 00:00:31, 5.30 m
Finish node, manhole, reference: S10



Section Inspection - 28/05/2021 - CAPX

Item No. 114	Insp. No. 1	Date 28/05/21	Time 13:21	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR CAPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	CAP
Road:	Dappers Lane	Inspected Length:	22.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	22.00 m	Downstream Node:	S10
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:190	Position [m]	Code	Observation	Grade
Depth: m				
S10				
0.00		MH	Start node, manhole, reference: S10	
0.00		WL	Water level, 0% of the vertical dimension	
0.10		LL	Line deviates left	
0.40		DES	Settled deposits, fine, 5% cross-sectional area loss	3
2.60		JN	Junction at 3 o'clock, 100mm dia	
8.50		JN	Junction at 3 o'clock, 100mm dia	
13.90		JN	Junction at 3 o'clock, 100mm dia	
20.00		JN	Junction at 3 o'clock, 100mm dia	
21.50		LU	Line deviates up	
22.00		MHF	Finish node, manhole, reference: CAP	
CAP				
Depth: m				

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.0	2.0	3.0

Dappers Lane

249

Section Pictures - 28/05/2021 - CAPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
114	Upstream	CAPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S10




2, 00:00:14, 0.40 m
Settled deposits, fine, 5% cross-sectional area loss




3, 00:00:27, 2.60 m
Junction at 3 o'clock, 100mm dia



4, 00:00:41, 8.50 m
Junction at 3 o'clock, 100mm dia



5, 00:00:52, 13.90 m
Junction at 3 o'clock, 100mm dia



6, 00:01:05, 20.00 m
Junction at 3 o'clock, 100mm dia




Section Pictures - 28/05/2021 - CAPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
114	Upstream	CAPX		



7, 00:01:15, 21.50 m
Line deviates up



8, 00:01:18, 22.00 m
Finish node, manhole, reference: CAP



Section Inspection - 28/05/2021 - RWPX

Item No. 115	Insp. No. 1	Date 28/05/21	Time 13:36	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	2.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.30 m	Downstream Node:	S37A
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

252




Section Pictures - 28/05/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
115	Upstream	RWPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S37A



2, 00:00:13, 2.10 m
Line deviates up



3, 00:00:16, 2.30 m
Finish node, manhole, reference: RWP



Section Inspection - 28/05/2021 - S37AX

Item No. 116	Insp. No. 1	Date 28/05/21	Time 13:38	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S37AX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S37A
Road:	Dappers Lane	Inspected Length:	9.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	9.50 m	Downstream Node:	S37
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:82 Position [m] Code Observation Grade

Depth: m

S37A



0.00

MH

Start node, manhole, reference: S37A

0.00

WL

Water level, 0% of the vertical dimension

2.30

LL

Line deviates left

3.90

JN

Junction at 10 o'clock, 100mm dia

6.70

JN

Junction at 10 o'clock, 100mm dia

9.30

LL

Line deviates left

9.50

MHF

Finish node, manhole, reference: S37

S37

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


254

Section Pictures - 28/05/2021 - S37AX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
116	Downstream	S37AX		




1, 00:00:00, 0.00 m
Start node, manhole, reference: S37A




2, 00:00:17, 2.30 m
Line deviates left




3, 00:00:24, 3.90 m
Junction at 10 o'clock, 100mm dia



4, 00:00:34, 6.70 m
Junction at 10 o'clock, 100mm dia



5, 00:00:43, 9.30 m
Line deviates left



6, 00:00:45, 9.50 m
Finish node, manhole, reference: S37



Section Inspection - 28/05/2021 - S37X

Item No. 117	Insp. No. 1	Date 28/05/21	Time 13:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S37X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S37
Road:	Dappers Lane	Inspected Length:	14.40 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	14.40 m	Downstream Node:	S37B
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:125 Position [m] Code Observation Grade

Depth: m

S37



0.00

MH

Start node, manhole, reference: S37

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

9.40

JN

Junction at 10 o'clock, 100mm dia

10.90

WL

Water level, 10% of the vertical dimension

14.40

MHF

Finish node, manhole, reference: S37B

S37B

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


256

Section Pictures - 28/05/2021 - S37X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
117	Downstream	S37X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S37



2, 00:00:32, 9.40 m
Junction at 10 o'clock, 100mm dia



3, 00:00:38, 10.90 m
Water level, 10% of the vertical dimension



4, 00:00:58, 14.40 m
Finish node, manhole, reference: S37B



Section Inspection - 28/05/2021 - S37BX


Item No. 118	Insp. No. 1	Date 28/05/21	Time 13:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S37BX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S37B
Road:	Dappers Lane	Inspected Length:	0.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.90 m	Downstream Node:	S9
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

258




Section Pictures - 28/05/2021 - S37BX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
118	Downstream	S37BX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S37B



2, 00:00:16, 0.90 m
Finish node, manhole, reference: S9



Section Inspection - 28/05/2021 - SPX


Item No. 119	Insp. No. 1	Date 28/05/21	Time 13:57	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP
Road:	Dappers Lane	Inspected Length:	2.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.60 m	Downstream Node:	F29A
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

260

Section Pictures - 28/05/2021 - SPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
119	Upstream	SPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29A



2, 00:00:15, 2.30 m
Line deviates up



3, 00:00:18, 2.60 m
Finish node, manhole, reference: SP



Section Inspection - 28/05/2021 - F29AX

Item No. 120	Insp. No. 1	Date 28/05/21	Time 13:59	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29AX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29A
Road:	Dappers Lane	Inspected Length:	5.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.10 m	Downstream Node:	F29B
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F29A



0.00

MH

Start node, manhole, reference: F29A

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

5.00

LR

Line deviates right

5.10

MHF

Finish node, manhole, reference: F29B

F29B

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

262