


Section Pictures - 28/05/2021 - F29AX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
120	Downstream	F29AX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29A



2, 00:00:30, 5.00 m
Line deviates right



3, 00:00:32, 5.10 m
Finish node, manhole, reference: F29B



Section Inspection - 28/05/2021 - F29BX

Item No. 121	Insp. No. 1	Date 28/05/21	Time 14:01	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29BX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29B
Road:	Dappers Lane	Inspected Length:	2.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.30 m	Downstream Node:	F29C
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F29B



0.00

MH

Start node, manhole, reference: F29B

0.00

WL

Water level, 0% of the vertical dimension

0.20

LR

Line deviates right

2.30

MHF

Finish node, manhole, reference: F29C

F29C

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


264

Section Pictures - 28/05/2021 - F29BX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
121	Downstream	F29BX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29B



2, 00:00:07, 0.20 m
Line deviates right



3, 00:00:18, 2.30 m
Finish node, manhole, reference: F29C



Section Inspection - 28/05/2021 - SPX


Item No. 122	Insp. No. 1	Date 28/05/21	Time 14:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP
Road:	Dappers Lane	Inspected Length:	2.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.60 m	Downstream Node:	F29C
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

266

Section Pictures - 28/05/2021 - SPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
122	Upstream	SPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29C



2, 00:00:30, 1.80 m
Line deviates left



3, 00:00:37, 2.60 m
Finish node, manhole, reference: SP



Section Inspection - 28/05/2021 - F29CX

Item No. 123	Insp. No. 1	Date 28/05/21	Time 14:16	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29CX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29C
Road:	Dappers Lane	Inspected Length:	7.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.30 m	Downstream Node:	F29D
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:63 Position [m] Code Observation Grade

Depth: m

F29C



0.00

MH

Start node, manhole, reference: F29C

0.00

WL

Water level, 0% of the vertical dimension

7.30

MHF

Finish node, manhole, reference: F29D

F29D

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

268




Section Pictures - 28/05/2021 - F29CX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
123	Downstream	F29CX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29C



2, 00:00:31, 7.30 m
Finish node, manhole, reference: F29D



Section Inspection - 28/05/2021 - SPX


Item No. 124	Insp. No. 1	Date 28/05/21	Time 14:23	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP
Road:	Dappers Lane	Inspected Length:	2.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	2.80 m	Downstream Node:	F29D
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


270

Section Pictures - 28/05/2021 - SPX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
124	Upstream	SPX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29D




2, 00:00:26, 0.60 m
Line deviates left



3, 00:00:33, 1.80 m
Line deviates left



4, 00:00:38, 2.60 m
Line deviates up



5, 00:00:44, 2.80 m
Finish node, manhole, reference: SP



Section Inspection - 28/05/2021 - F29DX

Item No. 125	Insp. No. 1	Date 28/05/21	Time 14:24	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29DX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29D
Road:	Dappers Lane	Inspected Length:	3.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.00 m	Downstream Node:	F29E
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F29D



0.00

MH

Start node, manhole, reference: F29D

0.00

WL

Water level, 0% of the vertical dimension

2.40

LR

Line deviates right

3.00

MHF

Finish node, manhole, reference: F29E

F29E

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

272

Section Pictures - 28/05/2021 - F29DX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
125	Downstream	F29DX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29D



2, 00:00:15, 2.40 m
Line deviates right



3, 00:00:19, 3.00 m
Finish node, manhole, reference: F29E



Section Inspection - 28/05/2021 - F29EX

Item No. 126	Insp. No. 1	Date 28/05/21	Time 14:25	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29EX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29E
Road:	Dappers Lane	Inspected Length:	7.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	7.60 m	Downstream Node:	F29
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:66 Position [m] Code Observation Grade

Depth: m

F29E



0.00

MH

Start node, manhole, reference: F29E

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

7.40

LL

Line deviates left

7.60

MHF

Finish node, manhole, reference: F29

F29

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


274

Section Pictures - 28/05/2021 - F29EX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
126	Downstream	F29EX		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29E



2, 00:00:25, 7.40 m
Line deviates left



3, 00:00:29, 7.60 m
Finish node, manhole, reference: F29



Section Inspection - 28/05/2021 - F29X

Item No. 127	Insp. No. 1	Date 28/05/21	Time 14:26	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F29X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F29
Road:	Dappers Lane	Inspected Length:	3.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	3.10 m	Downstream Node:	JN
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

F29



0.00

MH

Start node, manhole, reference: F29

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

2.40

LR

Line deviates right

3.10

BRF

Finish node, major connection without manhole, reference: JN

JN

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

276

Section Pictures - 28/05/2021 - F29X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
127	Downstream	F29X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: F29



2, 00:00:15, 2.40 m
Line deviates right



3, 00:00:22, 3.10 m
Finish node, major connection without manhole, reference: JN



Section Inspection - 28/05/2021 - S10X

Item No. 128	Insp. No. 1	Date 28/05/21	Time 14:56	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S10X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S10
Road:	Dappers Lane	Inspected Length:	18.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	18.20 m	Downstream Node:	S11
Surface Type:	Block Paved	Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	300 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:157 Position [m] Code Observation Grade

Depth: m

S10



0.00

MH

Start node, manhole, reference: S10

0.00

WL

Water level, 5% of the vertical dimension

10.80

WL

Water level, 10% of the vertical dimension

15.70

S01

DES

Settled deposits, fine, 15% cross-sectional area loss, start

17.80

F01

DES

Settled deposits, fine, 15% cross-sectional area loss, finish

3

18.20

CPF

Finish node, catchpit, reference: S11

S11

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	1	2.0	0.3	6.0	3.0

Dappers Lane

278



Section Pictures - 28/05/2021 - S10X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
128	Downstream	S10X		



1, 00:00:00, 0.00 m
Start node, manhole, reference: S10



2, 00:01:12, 10.80 m
Water level, 10% of the vertical dimension



3, 00:01:35, 15.70 m
Settled deposits, fine, 15% cross-sectional area loss, start



4, 00:02:09, 18.20 m
Finish node, catchpit, reference: S11



Section Inspection - 28/05/2021 - S11X

Item No. 129	Insp. No. 1	Date 28/05/21	Time 15:11	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S11X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S11
Road:	Dappers Lane	Inspected Length:	0.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.00 m	Downstream Node:	
Surface Type:	Grass	Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	225 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S11



0.00

MH

Start node, manhole, reference: S11

0.00

SA

Survey abandoned: Unable to cctv past hydrobrake

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations


STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

280

Section Pictures - 28/05/2021 - S11X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
129	Downstream	S11X		



1, 00:00:29, 0.00 m
Start node, manhole, reference: S11



2, 00:00:33, 0.00 m
Survey abandoned, Unable to cctv past hydrobrake



Section Inspection - 20/07/2021 - RWP1X

Item No. 130	Insp. No. 1	Date 20/07/21	Time 7:21	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWP1X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP1
Road:	Dappers Lane	Inspected Length:	5.60 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.60 m	Downstream Node:	S14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S14



0.00

MH

Start node, manhole, reference: S14

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

5.40

LU

Line deviates up

5.60

MHF

Finish node, manhole, reference: RWP1

RWP1

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

282



Section Pictures - 20/07/2021 - RWP1X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
130	Upstream	RWP1X		



1, 00:00:01, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:29, 5.40 m
Line deviates up



3, 00:00:34, 5.60 m
Finish node, manhole, reference: RWP1



Section Inspection - 20/07/2021 - RWP2X

Item No. 131	Insp. No. 1	Date 20/07/21	Time 7:24	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWP2X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP2
Road:	Dappers Lane	Inspected Length:	5.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	5.80 m	Downstream Node:	S14
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade

Depth: m

S14



0.00

MH

Start node, manhole, reference: S14

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

2.00

LR

Line deviates right

5.50

LU

Line deviates up

5.80

MHF

Finish node, manhole, reference: RWP2

RWP2

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

284




Section Pictures - 20/07/2021 - RWP2X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
131	Upstream	RWP2X		



1, 00:00:09, 0.10 m
Line deviates right



2, 00:00:23, 2.00 m
Line deviates right



3, 00:00:46, 5.50 m
Line deviates up



4, 00:00:51, 5.80 m
Finish node, manhole, reference: RWP2



Section Inspection - 20/07/2021 - S14X

Item No. 132	Insp. No. 1	Date 20/07/21	Time 7:29	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S14X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S14
Road:	Dappers Lane	Inspected Length:	10.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	10.80 m	Downstream Node:	S16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:94 Position [m] Code Observation Grade

Depth: m

S14



0.00

MH

Start node, manhole, reference: S14

0.00

WL

Water level, 0% of the vertical dimension

10.60

LL

Line deviates left

10.80

MHF

Finish node, manhole, reference: S16

S16

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

286



Section Pictures - 20/07/2021 - S14X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
132	Downstream	S14X		



1, 00:00:02, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:46, 10.60 m
Line deviates left



3, 00:00:52, 10.80 m
Finish node, manhole, reference: S16



Section Inspection - 20/07/2021 - AX


Item No. 133	Insp. No. 1	Date 20/07/21	Time 7:46	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR AX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	A
Road:	Dappers Lane	Inspected Length:	1.90 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.90 m	Downstream Node:	S16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

288

Section Pictures - 20/07/2021 - AX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
133	Upstream	AX		



1, 00:00:07, 0.10 m
Line deviates left



2, 00:00:31, 1.60 m
Line deviates left



3, 00:00:37, 1.90 m
Finish node, other special chamber, reference: A, Assumed attenuation



Section Inspection - 20/07/2021 - RWPX

Item No. 134	Insp. No. 1	Date 20/07/21	Time 7:50	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	6.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	6.20 m	Downstream Node:	S16
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:54 Position [m] Code Observation Grade

Depth: m

S16

0.00

MH

Start node, manhole, reference: S16

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

5.80

LU

Line deviates up

6.20

MHF

Finish node, manhole, reference: RWP

RWP

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

290



Section Pictures - 20/07/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
134	Upstream	RWPX		




1, 00:00:03, 0.10 m
Line deviates right



2, 00:00:29, 5.80 m
Line deviates up



3, 00:00:28, 6.20 m
Finish node, manhole, reference: RWP



Item No. 135	Insp. No. 1	Date 20/07/21	Time 7:53	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S17X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Comments:	
Recommendations:	


Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Section Pictures - 20/07/2021 - S17X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
135	Upstream	S17X		



1, 00:00:06, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:21, 3.30 m
Line deviates left



3, 00:00:28, 3.40 m
Finish node, manhole, reference: S17



Section Inspection - 20/07/2021 - S17.1X

Item No. 136	Insp. No. 1	Date 20/07/21	Time 7:56	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S17.1X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	S17.1
Road:	Dappers Lane	Inspected Length:	15.00 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.00 m	Downstream Node:	S17
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:130 Position [m] Code Observation Grade

Depth: m

S17



0.00

MH

Start node, manhole, reference: S17

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

3.70

JN

Junction at 3 o'clock, 100mm dia

14.80

LL

Line deviates left

15.00

MHF

Finish node, manhole, reference: S17.1

S17.1

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane


294

Section Pictures - 20/07/2021 - S17.1X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
136	Upstream	S17.1X		




1, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:16, 3.70 m
Junction at 3 o'clock, 100mm dia



3, 00:00:52, 14.80 m
Line deviates left



4, 00:00:57, 15.00 m
Finish node, manhole, reference: S17.1



Section Inspection - 20/07/2021 - REX

Item No. 137	Insp. No. 1	Date 20/07/21	Time 8:05	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR REX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RE
Road:	Dappers Lane	Inspected Length:	13.30 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.30 m	Downstream Node:	S17.1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:115 Position [m] Code Observation Grade

Depth: m

S17.1



0.00

MH

Start node, manhole, reference: S17.1

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

0.40

JN

Junction at 9 o'clock, 100mm dia

4.70

JN

Junction at 9 o'clock, 100mm dia

8.50

JN

Junction at 9 o'clock, 100mm dia

12.80

JN

Junction at 9 o'clock, 100mm dia

12.90

LU

Line deviates up

13.30

REF

Finish node, rodding eye, reference: RE

RE

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

296



Section Pictures - 20/07/2021 - REX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
137	Upstream	REX		



1, 00:00:07, 0.10 m
Line deviates left



2, 00:00:18, 0.40 m
Junction at 9 o'clock, 100mm dia



3, 00:00:39, 4.70 m
Junction at 9 o'clock, 100mm dia



4, 00:00:54, 8.50 m
Junction at 9 o'clock, 100mm dia



5, 00:01:08, 12.80 m
Junction at 9 o'clock, 100mm dia



6, 00:01:16, 12.90 m
Line deviates up



Section Pictures - 20/07/2021 - REX

Item No.
137

Inspection Direction
Upstream

PLR
REX

Client's Job Ref

Contractor's Job Ref



7, 00:01:14, 13.30 m
Finish node, rodding eye, reference: RE



Section Inspection - 20/07/2021 - LDX


Item No. 138	Insp. No. 1	Date 20/07/21	Time 8:06	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	0.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.10 m	Downstream Node:	S17.1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

299



Section Pictures - 20/07/2021 - LDX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
138	Upstream	LDX		



1, 00:00:07, 0.10 m
Finish node, manhole, reference: LD



Section Inspection - 20/07/2021 - SP45X

Item No. 139	Insp. No. 1	Date 20/07/21	Time 8:14	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR SP45X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	SP45
Road:	Dappers Lane	Inspected Length:	1.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.50 m	Downstream Node:	F33.1
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

301



Section Pictures - 20/07/2021 - SP45X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
139	Upstream	SP45X		



1, 00:00:04, 0.10 m
Line deviates left



2, 00:00:13, 1.00 m
Line deviates up



3, 00:00:20, 1.50 m
Finish node, manhole, reference: SP45



Section Inspection - 20/07/2021 - F33.1X

Item No. 140	Insp. No. 1	Date 20/07/21	Time 8:19	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR F33.1X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	F33.1
Road:	Dappers Lane	Inspected Length:	9.10 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	9.10 m	Downstream Node:	F33
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Foul	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:79 Position [m] Code Observation Grade

Depth: m

F33.1



0.00

MH

Start node, manhole, reference: F33.1

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

8.90

LR

Line deviates right

9.10

MHF

Finish node, manhole, reference: F33

F33

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


Dappers Lane

303



Section Pictures - 20/07/2021 - F33.1X

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
140	Downstream	F33.1X		



1, 00:00:04, 0.10 m
Line deviates right



2, 00:00:42, 8.90 m
Line deviates right



3, 00:00:51, 9.10 m
Finish node, manhole, reference: F33



Section Inspection - 20/07/2021 - S15X

Item No. 141	Insp. No. 1	Date 20/07/21	Time 8:44	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR S15X
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Downstream	Upstream Node:	S15
Road:	Dappers Lane	Inspected Length:	13.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	13.50 m	Downstream Node:	JN
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:117 Position [m] Code Observation Grade

Depth: m

S15



0.00

MH

Start node, manhole, reference: S15

0.00

WL

Water level, 0% of the vertical dimension

0.10

LL

Line deviates left

12.00

JN

Junction at 9 o'clock, 100mm dia

13.40

LR

Line deviates right

13.50

BRF

Finish node, major connection without manhole, reference: JN

JN

Depth: m

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

305




Section Pictures - 20/07/2021 - S15X


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
141	Downstream	S15X		




1, 00:00:03, 0.10 m
Line deviates left



2, 00:00:48, 12.00 m
Junction at 9 o'clock, 100mm dia



3, 00:00:55, 13.40 m
Line deviates right



4, 00:00:58, 13.50 m
Finish node, major connection without manhole, reference: JN



Section Inspection - 20/07/2021 - LDX


Item No. 142	Insp. No. 1	Date 20/07/21	Time 8:49	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR LDX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	LD
Road:	Dappers Lane	Inspected Length:	1.20 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	1.20 m	Downstream Node:	S18
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

307




Section Pictures - 20/07/2021 - LDX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
142	Upstream	LDX		



1, 00:00:03, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:12, 1.20 m
Finish node, manhole, reference: LD



Section Inspection - 20/07/2021 - REX

Item No. 143	Insp. No. 1	Date 20/07/21	Time 8:51	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR REX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RE
Road:	Dappers Lane	Inspected Length:	15.50 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	15.50 m	Downstream Node:	S18
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:134 Position [m] Code Observation Grade

Depth: m

S18



0.00

MH

Start node, manhole, reference: S18

0.00

WL

Water level, 0% of the vertical dimension

0.10

LR

Line deviates right

4.00

JN

Junction at 3 o'clock, 100mm dia

9.90

JN

Junction at 3 o'clock, 100mm dia

15.40

JN

Junction at 3 o'clock, 100mm dia

15.50

LU

Line deviates up

15.50

SA

Survey abandoned: Capped

Construction Features

Structural Defects

Miscellaneous Features

Service & Operational Observations

STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

309




Section Pictures - 20/07/2021 - REX


Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
143	Upstream	REX		



1, 00:00:02, 0.10 m
Line deviates right



2, 00:00:23, 4.00 m
Junction at 3 o'clock, 100mm dia



3, 00:00:43, 9.90 m
Junction at 3 o'clock, 100mm dia



4, 00:01:01, 15.40 m
Junction at 3 o'clock, 100mm dia



5, 00:01:04, 15.50 m
Survey abandoned, Capped



Section Inspection - 20/07/2021 - RWPX


Item No. 144	Insp. No. 1	Date 20/07/21	Time 8:53	Client's Job Ref Not Specified	Weather No Rain Or Snow	Pre Cleaned Yes	PLR RWPX
Operator Luke		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Private Drain	Alternative ID Not Specified

Town or Village:	Angmering	Inspection Direction:	Upstream	Upstream Node:	RWP
Road:	Dappers Lane	Inspected Length:	0.80 m	Upstream Pipe Depth:	
Location:	Property or buildings	Total Length:	0.80 m	Downstream Node:	S18
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water	Pipe Shape:	Circular		
Type of Pipe:	Gravity drain/sewer	Dia/Height:	100 mm		
Flow Control:	No flow control	Material:	Polyvinyl chloride		
Year Constructed:	Not Specified	Lining Type:	No Lining		
Inspection Purpose:	Routine inspection	Lining Material:	No Lining		

Comments:

Recommendations:

Scale: 1:50 Position [m] Code Observation Grade



Depth: m

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

Dappers Lane

311



Section Pictures - 20/07/2021 - RWPX

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
144	Upstream	RWPX		



1, 00:00:12, 0.00 m
Water level, 0% of the vertical dimension



2, 00:00:19, 0.50 m
Line deviates up



3, 00:00:26, 0.80 m
Finish node, manhole, reference: RWP