




From: Laura Gibbons <Laura.Gibbons@arun.gov.uk>

Sent: 07 December 2021 11:04

To: Planning.Responses <Planning.Responses@arun.gov.uk>

Cc: Michael Eastham <Michael.Eastham@arun.gov.uk>

Subject: BE/160/21/DOC Land At Salt Box West Of Shripney Road Bognor Regis PO22 9NW

Hi Michael,

I have reviewed the pipes downstream of 503. There does not appear to be scope within the layout to relay the pipe downstream of 503 to achieve 1m/s self-cleansing velocity without completing significant work downstream. We would suggest that the maintenance manual is updated to increase the maintenance frequency of catchpits and pipework within this network.

There are other pipes within the network which are also slack, we would therefore recommend site wide increases in maintenance frequency.

Please can an updated maintenance manual be supplied.

Kind regards,

Laura Gibbons

Drainage Engineer

Engineering Services

Please note that I work Tuesdays 08:00-16:00 for Arun only.



T: 01903 221374

E: laura.gibbons@arun.gov.uk

Arun District Council, Civic Centre, Maltravers Rd, Littlehampton, West Sussex, BN17 5LF