

DYNAMIC DRAINAGE LTD

24 HOUR DRAIN SERVICES

Mr. J. Weller
285A Chichester Road
Bognor Regis
West Sussex
PO21 5HA

15th November 2018

RE. SOUTHERN WATER DRAIN RUN LOCATIONS

Dear Mr Weller,

As per your instruction, we visited the above address and adjacent area and carried out visual searches for the inspection chambers indicated on the provided Southern Water plan document.

We can confirm that there is only 1 inspection chamber, which is located within the adjacent footpath to the West of your land. This provides access to the surface water drain. There are NO other inspection chambers to be found at all.

We can confirm we put the CCTV camera into the surface water drain and it appears the drain line run is straight and does not deviate away from the path. The drain is severely blocked with debris, which limited the extent we could insert the CCTV.

As indicated on the Southern Water plan document of the sewer records, the rising pumped foul sewer runs to the West of the surface water drain. This would therefore run along the line of the footpath too, even further West from the boundary of your land.

Clearly therefore neither the rising pumped foul sewer or the surface water drain of the above lines go onto your property at all.

Yours Faithfully,

Terry Stevens
Managing Director.

