

Appendix E Southern Water Public Sewer Records

SOUTHERN WATER SERVICES LIMITED



101432
480073

LEGEND - MAINS	
	Distribution Mains / Communication pipe
	Truck Main
	Raw water main
	Non potable
	Abandoned main
	Proposed Main
	Fire main
	Non BWS
	Glass valve
	Closed valve
	Air valve
	Butterfly valve
	Pressure reducing valve
	Reflux valve
	Motorised valve
	Cookhouse closing valve
	Wastohut
	Wastohut hydrant
	Meter
	Capacit end
	Emptying plug
	Leak Meter Correlator Survey Point
	Airlock
	Telemetry cable
	Access point / hatchbox
	Dialysis machine
	Break pressure tank
	Pumping station
	Booster station
	Insertion Flow Meter Point
	Water tower
	Service reservoir
	Water Supply Works
	Stone hole / Well
	Intake
	Customer site
	Sewer insertion point

MATERIALS	
	Asbestos
	Cast iron
	Spun (grey) iron
	Concrete
	Ductile iron
	Banded Asbestos Cement
	Glass reinforced plastic
	Insertion Flow Meter Point
	Glass reinforced epoxy
	(Continuous) Poly(vinyl) chloride
	Polyethylene
	Steel
	Concrete segments bedded
	Concrete segments bedded
	Galvanised iron
	Ductile sleeve
	Concrete pre-stressed
	High performance polyethylene
	Unknown
	AK
	CI
	SE
	CO
	DI
	BAC
	GRP
	GPE
	PVC
	PE
	ST
	CSB
	CSU
	DI
	DS
	CFS
	HPS
	YP

O.S. Ref.	Drawn by: duttaai
TQ0002SW	Scale: 1:2500
	Date: 22/08/2019
Title: Land to the West of Church Lan	

The positions of pipes shown on this plan are believed to be correct, but Southern Water Services Ltd accept no responsibility in the event of inaccuracy. The actual position of pipes must be determined on site.

WARNING: BAC pipes are constructed of Banded Asbestos Cement.
WARNING: Unknown (UPK) materials may include Banded Asbestos Cement.

Based upon Ordnance Survey Digital Data with the permission of the Controller of H.M.S.O. Crown Copyright
Reserved Licence No. WU298530

501001

[illegible]