

JULIAN MUNN DRAINAGE SERVICES Ltd
15 WHITFIELD CLOSE, BOGNOR REGIS, PO22 8DY

Customer: Alison Baird

Address:

Contact:

Site Location:

Rigates
Climping Street
BN17 5RQ

Date:

01/07/2025

Job No:

S1420/07/25

Manhole ID:

MH03

Cover Size:

670mm x 510mm

Chamber Size:

450mm

Depth:

680mm

Duty:

F/W

Weather:

DRY

Manhole Access:




OK



Covered with earth




Covered with hard surface




Covered with Fencing


Manhole Construction:



Brick



Concrete




Rendered




U.P.V.C

Step Irons:

NONE



Satisfactory



Missing




Corroded



Unsecure


Manhole cover type:



Light duty



Medium duty



Heavy duty


Manhole wall Condition:




Satisfactory




Cracked




Missing Render



Eroded




Bar Exposed



Water infiltration




Mineral build-up




Root ingress


Benching/Channel condition:




Satisfactory




Debris




Cracked




Broken




Missing



Offset



Mineral build-up




Root ingress


Manhole cover condition:



Satisfactory




Rocking




Broken



Worn



Stuck



Replace

Remarks:


B-100mm from FWG04

A-100mm from SP01

C-150mm from MH02

D-100mm from SP02

X-150mm to MH04



JULIAN MUNN DRAINAGE SERVICES Ltd
15 WHITFIELD CLOSE, BOGNOR REGIS, PO22 8DY

Customer: Alison Baird

Address:

Contact:

Site Location:

Rigates
Climping Street
BN17 5RQ

Date:

01/07/2025

Job No:

S1420/07/25

Manhole ID:

MH04

Cover Size:

670mm x 510mm

Chamber Size:

600mm x 450mm

Depth:

700mm

Duty:

F/W


Weather:

DRY


Manhole Access:




OK



Covered with earth



Covered with hard surface




Covered with Fencing


Manhole Construction:




Brick



Concrete



Rendered



U.P.V.C

Step Irons: NONE




Satisfactory



Missing



Corroded



Unsecure


Manhole cover type:



Light duty



Medium duty




Heavy duty


Manhole wall Condition:




Satisfactory




Cracked




Missing Render




Eroded




Bar Exposed



Water infiltration



Mineral build-up




Root ingress

Benching/Channel condition:



Satisfactory




Debris



Cracked



Broken




Missing



Offset



Mineral build-up




Root ingress


Manhole cover condition:



Satisfactory




Rocking




Broken



Worn




Stuck



Replace

Remarks:

A-150mm from MH03



X-150mm to MH05

B-100mm from FWG05

JULIAN MUNN DRAINAGE SERVICES Ltd
15 WHITFIELD CLOSE, BOGNOR REGIS, PO22 8DY

Customer: Alison Baird

Address:

Contact:

Site Location:

Rigates

Climping Street

BN17 5RQ

Date:

01/07/2025

Job No:

S1420/07/25

Manhole ID:

MH05

Cover Size:

650mm x 510mm

Chamber Size:

600mm x 450mm

Depth:

1150mm

Duty:

F/W


Weather:

DRY

Manhole Access:



OK



Covered with earth




Covered with hard surface



Covered with Fencing

Manhole Construction:




Brick



Concrete




Rendered



U.P.V.C

Step Irons:

NONE



Satisfactory



Missing




Corroded



Unsecure

Manhole cover type:



Light duty



Medium duty



Heavy duty

Manhole wall Condition:




Satisfactory



Cracked




Missing Render




Eroded




Bar Exposed



Water infiltration



Mineral build-up



Root ingress


Benching/Channel condition:




Satisfactory



Debris



Cracked



Broken




Missing



Offset



Mineral build-up




Root ingress


Manhole cover condition:



Satisfactory




Rocking



Broken



Worn




Stuck



Replace

Remarks:

A-150mm from MH04



B-150mm from Office

X-150mm to MH06