

PHOTOGRAPHIC APPENDICES I

in connection with

Climping Mill, Littlehampton
External



INSTITUTE · OF · HISTORIC ·
BUILDING · CONSERVATION

Registered Office:
The Spinney St Marys Lane Bexhill on
Sea E. Sussex TN39 5JE

DGC (Historic Buildings) Consultants
Limited

REF: DGC21732 Rev A

Date of Issue: 15/08/2017

Web: www.dgc-consultants.com


Registered in England and Wales No. 239626
VAT Reg No. 914 8059 15

Generally

North Elevation



DSC02699 Mid-20th Century extension to Mill House



DSC02700 Mid-20th century extension in context with historic form



DSC02701



DSC02704

DSC02701 & DSC02704 Rear elevation of Outbuildings and first floor 20th century flat roof link connecting the Mill House with the modern northern extension.




DSC03183 Remains of flint dwarf retaining wall




DSC03184 Exposed earth bank

East Elevation



DSC02708 & DSC03118 East Elevation showing Mill House, Historic Outbuildings & Mid-20th Century extension




DSC03133

DSC03133 East elevation of first floor link in context



DSC03126

DSC03126 Close up of first floor link




DSC03130

DSC03130 Close up of masonry walls beneath the first floor link.



DSC02703 Brick cill detail to replicate the historic form



DSC03117 Garden wall to East Elevation




DSC02716 Garden wall to East Elevation




DSC02715 Inner face of garden wall



DSC03113



DSC3114



DSC3116

DSC03113 & DSC3114 Images of the curtilage listed garden wall to Mill House


DSC3116 East elevation of flint wall with brick dressing associated with outbuildings

South Elevation



DSC02772

DSC02772 South elevation showing Mill, first floor link and Mill House



DSC03143

DSC03143 Masonry wall of Mill contained under first floor sun room link



DSC03143 Double Height Canted Bay



DSC03143 Parapet Gable

West Elevation



DSC02734 General view of extensions to Mill House



DSC02733 General view




DSC02698

DSC02698 Hipped end North of the curtilage listed Mill flint wall



DSC03171

DSC03171 South courtyard wall the Mill House south of the early 20th century addition



DSC03172

DSC03172 East courtyard wall the Mill House south of the early 20th century addition

DSC03173 First Floor East courtyard wall of Mill House




DSC03173


The Mill (Late 18th Century)




DSC03149



DSC03152




DSC03156



DSC03160



DSC03164




DSC03167


General views showing the elevation of The Mill



DSC02733 West Elevation Ivy growth to side of stack



DSC02808 Lead flashings to chimney stack



DSC02728 Extensive Vegetation growth to base



DSC02739 Cementitious pointing to knapped flint



DSC03153



DSC03154



DSC3163

Typical defects, extensive vegetation growth, cracking through masonry, cementitious pointing and general delapidated condition of building.

Mill House (Mid-19th Century)



2017-04-26 11.48.49 East / Principal Façade




DSC02718 East & South Elevations, view looking North West

Detail and Defects




DSC02720

DSC02720 Roof detail above canted bay



DSC02719

DSC02719 Typical brick cill detail



DSC03133

DSC03133 Inappropriate rainwater goods



DSC02695

DSC02695 Eroded core and missing flints to walls



DSC03138

DSC03138 Vertical Cracking through the masonry



DSC03144

DSC03144 Horizontal cracking through brickwork

Photographic Appendices: Climping Mill - External


DSC03140 Decay cill and bottom rail of sash window

DSC03144 Repointing of flintwork using cementitious mortar


DSC03144 Comparative between the original lime mortar (with coal inclusion) and cementitious mortar



DSC03140




DSC03135




DSC03136


Historic Outbuildings




DSC02710 View of Flint wall integral to the Outbuildings



DSC02711 South Elevation of External Store (OB01)



DSC03188 View looking South West showing parapet rear wall of Outbuilding (OB1)



DSC03123




DSC03128

DSC03123 Internal view looking East (OB01)

DSC03123 Vertical cracking to North wall internally (OB01)




DSC02712




DSC03187

DSC02712 South Elevation of Workshop / Boiler room (OB02)


DSC03187 North Elevation of Workshop / Boiler room (OB02)



DSC03116



DSC03127




DSC03128

DSC03116 Undermining of flint walls by establishment of saplings

DSC03127 View looking North (OB02)

DSC03127 View looking East (OB02)

First Floor Link



DSC02722



DSC02722



DSC02722 View looking West


DSC02722 View looking North West

DSC02749 North Elevation of link

West Extension 1st Quarter 20th Century




DSC02699 West Elevation




DSC03178 North Elevation

Curtilage Listed flint constructed Mill wall



DSC02695 External view looking South East showing truncated mill and curtilage listed flint wall



DSC03190




DSC03192



DSC03193



DSC03195



DSC03196



DSC03197

General views showing construction arrangement including flint contracted buttresses, brick dressing to change of directions and openings and general defects associated with Mill wall



DSC02726 Internal view looking North



DSC02727 Internal view looking West by The Mill