

False Window to be mounted in vault.

Because the area shown on the layout plan to be the bedroom was formerly used as a vault when Barclays Bank occupied the site in the early 1990's, the walls and roof in this area are constructed in re-enforced concrete impregnated with plastic, such that they cannot be drilled or cut through to form a window. It is proposed that this area be insulated and dry-lined and a false window be installed. The make-up of the latter feature is shown below:

