

694 / PHO - Existing Photographs of Elm Lodge



Existing side elevation



Existing rear elevation



Existing living room



Existing hallway



Existing side elevation



Existing rear elevation



Existing view from bedroom 2 side dormer



Existing condition of floors



Existing front concrete paved area



Existing front concrete paved area



Existing porch (penetrating damp)



Existing porch (penetrating damp)