

Photos to show examples of existing condition of the interior and exterior of 30 Limmer Lane

Main points identified include (but not limited to):

- Mould and damp on majority of internal walls
- Cracking of many internal walls and ceilings
- General dilapidated condition
- Crumbling interior finishes
- Water ingress
- Cracking of many areas on external walls
- Damaged roof















