

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: [REDACTED]

Project-Information

Project Name: 468	Contract Number:	Contact: Parchow Groundworks	Date: 05/05/2026
-----------------------------	------------------	--	----------------------------

Client: **Parchow Groundworks**
Contact:
Position:
Road: **Widley Farm, New Down Lane**
Town: **Purbrook**
Post Code: **PO7 5SE**
County: **Hampshire**
Telephone:

Contractor: **All Hours Plumbing Ltd**
Contact: **Steve Guest**
Position: **Owner**
Road: **70 Widley Road, Stamshaw**
Town: **Portsmouth**
County: **Hampshire**
Telephone: [REDACTED]
Fax: [REDACTED]
E-Mail: [REDACTED]


Site: **468**
Engineer:
Position:
Road:
Town: **Littlehampton**
County:
Telephone:

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 2	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 1 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 3	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 1 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 4	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 1 End MH: FIC 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 5	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 2 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 6	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 2 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 7	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 3 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 8	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 3 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 9	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 3 End MH: FIC 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 10	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 4 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



12.1M JN Line Drops In From The Right
14.0M JN Line Drops In From The Left
14.6M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 11	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 4 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 13	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FMH 51 End MH: FIC 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 150mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 14	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FMH 51 End MH: FIC 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIP


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 15	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 5 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIP


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 16	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 5 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIP


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 17	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 5 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.2M JN Line Drops In From The Right

8.8M JN Line Drops In From The Left

9.1M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 18	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 5 End MH: FIC 6 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 19	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 6 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.5M JN Line Drops In From The Right

9.0M JN Line Drops In From The Right

9.6M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 20	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 6 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 21	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 6 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 22	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 8 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.4M JN Line Drops In From The Left

8.6M JN Line Drops In From The Right

9.1M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 23	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 8 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 24	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 8 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 25	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 8 End MH: FIC 7 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 26	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 7 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 27	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 7 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 28	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 7 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 29	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 9 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 30	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 9 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 31	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 9 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.2M JN Line Drops In From Above

8.7M JN Line Drops In From The Left

9.5M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 32	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 9 End MH: FIC 10 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 33	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 10 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.5M JN Line Drops In From Above

8.7M JN Line Drops In From The Right

9.5M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 34	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 10 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 35	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 10 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 36	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 11 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 37	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 11 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 38	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 11 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.5M JN Line Drops In From The Right

8.8M JN Line Drops In From The Left

9.4M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 39	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 11 End MH: FIC 12 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 40	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 12 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.7M JN Line Drops In From The Right

8.6M JN Line Drops In From The Right

9.6M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 41	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 12 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 42	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 12 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 43	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FMH 51 End MH: FMH 56 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 150mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 44	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FMH 56 End MH: FMH 77 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 150mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.3M JN Line Drops In From The Left

2.1M JN Line Drops In From The Right



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 45	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 6 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 46	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FMH 56 End MH: FMH 78 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 150mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 53	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 10 End MH: FMH 92 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 54	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 15 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 55	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 15 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 56	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 15 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.2M JN Line Drops In From The Right

9.0M JN Line Drops In From The Left

10.0M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 57	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 15 End MH: FIC 16 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 58	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 16 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.3M JN Line Drops In From The Left

8.0M JN Line Drops In From The Right

8.8M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 59	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 16 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 60	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 16 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 61	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 16 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 62	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 13 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.5M JN Line Drops In From The Right

3.3M LU Line Turns Up

REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 63	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 13 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 64	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 13 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 65	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 13 End MH: FIC 14 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 66	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 14 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 67	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 14 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 68	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 14 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 69	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 14 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



2.2M JN Line Drops In From The Right

4.0M LU Line Turns Up

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 70	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: FIC 12 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.2M MC Pipe Changes To Clay



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 71	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 1 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
1.2M JN Line Drops In From The Right



12.3M JN Line Drops In From The Right
12.5M LU Line Turns Up To Rodding Eye

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 72	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 1 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 73	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 1 End MH: PPCP 2 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 74	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 2 End MH: SMH 63 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: CLAY Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.0M CR Cracks In Pipe

10.9M CR Cracks In Pipe

14.8M MH Camera Enters Manhole S 63

REM ; THERE ARE CRACKS IN THIS SECTION OF PIPE WHICH CAN BE REPAIRED WITH 2 PATCH LINERS


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Photos

Place 468 Littlehampton	Road:	Date: 05/05/26	Section Number 75	PLR:
-------------------------------	-------	-------------------	----------------------	------

05-05-26 4.00m

PPCP 2 DS TO SMH 63 100MM



CRACKS IN PIPE

Inspection Photos

Place 468 Littlehampton	Road:	Date: 05/05/26	Section Number 76	PLR:
-------------------------------	-------	-------------------	----------------------	------

05-05-26 10.92m

PPCP 2 DS TO SMH 63 100MM




CRACKS IN PIPE

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 77	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 2 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.4M JN Line Drops In From The Left
0.5M JN Line Drops In From The Right



12.4M JN Line Drops In From The Left
12.6M JN Line Drops In From The Left
13.2M LU Line Turns Up To Rodding Eye

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 78	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 2 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report


Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 79	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 2 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %

2.2M JN Line Drops In From The Right

8.4M MH Camera Enters Manhole PPCP 3



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 80	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 3 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.9M JN Line Drops In From The Left



11.5M JN Line Drops In From The Left
12.5M LU Line Turns Up To Rodding Eye

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 82	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 4 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 83	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 4 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 84	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 4 End MH: PPCP 5 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 85	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 5 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.2M JN Line Drops In From The Left
0.4M JN Line Drops In From The Right



11.6M JN Line Drops In From The Right
12.0M JN Line Drops In From The Left
12.5M LU Line Turns Up To Rodding Eye

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 86	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 5 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 87	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 5 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE, BUT MANHOLE PPCP 6 HAS SCAFFOLDING OVER IT SO CANT ACCESS

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Photos

Place 468 Littlehampton	Road:	Date: 05/05/26	Section Number 88	PLR:
-------------------------------	-------	-------------------	----------------------	------




MANHOLE PPCP 6
UNDER SCAFFOLD

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 89	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 5 End MH: SMH 63 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position	Code	Observation
----------	------	-------------



REM ; THERE ARE NO MAJOR PROBLEMS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 90	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 7 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 91	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 7 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 92	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 7 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %




REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 93	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 7 End MH: LAT 4 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position	Code	Observation
----------	------	-------------



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 94	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 7 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 96	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 8 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 97	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 8 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 98	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 8 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %




REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 99	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 8 End MH: LAT 4 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position	Code	Observation
----------	------	-------------



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 100	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 9 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 101	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 9 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 102	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 9 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 103	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 9 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
0.8M JN Line Drops In From The Right



6.7M JN Line Drops In From The Right

10.8M LU Line Turns Up

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 104	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 10 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 105	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 10 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 106	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 10 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 107	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 10 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.2M JN Line Drops In From The Left

5.7M JN Line Drops In From The Right

8.3M LU Line Turns Up To Rodding Eye

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 108	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 10 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 05/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 110	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 8 End MH: SMH 19 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 112	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 9 End MH: SMH 23 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



4.4M MC Pipe Changes To Clay

12.0M MH Camera Enters Manhole S 23

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 114	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 11 End MH: LAT 1 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 115	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 11 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 116	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 11 End MH: LAT 3 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 117	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 11 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %

1.6M MC Pipe Changes To Clay



9.0M LD Line Drops Into Main

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 119	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



1.8M MC Pipe Changes To Clay

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 121	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 122	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 123	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 124	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 125	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: PPCP 12 End MH: LAT 5 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 126	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: SMH 63 End MH: SMH 32 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 300mm Material: CONCRETE Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 127	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: SMH 32 End MH: SMH 49 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 225mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 128	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: SMH 32 End MH: SMH 19 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 525mm Material: CONCRETE Lining: Category:			

Position Code Observation


0.0M ST Start Of Survey
0.0M WL Water Level 0 %

2.6M JN Line Drops In From The Left
2.8M JN Line Drops In From The Right

11.7M JN Line Drops In From The Left

15.1M JN Line Drops In From The Right

28.2M MH Camera Enters Manhole S 19



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 129	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site: 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: SMH 23 End MH: SMH 37 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 300mm Material: CONCRETE Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 06/05/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 130	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; 468 Place: Littlehampton		Division: District: S.W Tape No: 1		Start MH: SMH 37 End MH: SMH 7 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 375mm Material: CONCRETE Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



12.5M JN Line Drops In From The Left
19.9M JN Line Drops In From The Right
32.5M JN Line Drops In From The Left
47.5M JN Line Drops In From The Right
50.0M JN Line Drops In From The Left

66.1M MH Camera Enters Manhole S 7

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features