

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants

Project-Information

Project Name:
468 Plots 88-78

Contract Number:

Contact:
Parchow Groundworks

Date:
10/06/2026


Client: **Parchow Groundworks**
Contact:
Position:
Road: **Widley Farm, New Down Lane**
Town: **Purbrook**
Post Code: **PO7 5SE**
County: **Hampshire**
Telephone:

Contractor: **All Hours Plumbing Ltd**
Contact: **Steve Guest**
Position: **Owner**
Road: **70 Widley Road, Stamshaw**
Town: **Portsmouth**
County: **Hampshire**
Telephone:
Fax:
E-Mail:

Site: **468 Plots 88-78**
Engineer:
Position:
Road:
Town: **Littlehampton**
County:
Telephone:

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 2	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 17 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 3	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 17 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 4	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1	Start MH: FIC 17 End MH: LAT 3 Total Length:		
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 100MM PLASTIC		

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 5	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 17 End MH: FIC 18 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 6	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 18 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 7	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 18 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 7	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 18 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 18

4.4M JN Line Drops In From The Right

8.9M JN Line Drops In From The Left

LAT 3

10.0M LU Line Turns Up

Flow

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 9	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 18 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 10	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 19 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 11	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 19 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 12	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 19 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 13	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 19 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey

0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 14	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1	Start MH: FIC 20 End MH: LAT 1 Total Length:		
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule		Size/Shape: Material: Lining: Category:	Circular dia 100MM PLASTIC	


Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

1.7M JN Line Drops In From Above

3.1M JN Line Drops In From The Right

9.5M LU Line Turns Up



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 15	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 20 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 16	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 20 End MH: FIC 21 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 17	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 21 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 18	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 21 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 19	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 21 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 20	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 21 End MH: FMH 67 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



8.0M MC Pipe Changes To Clay
8.6M MH Camera Enters Manhole FMH 67

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 21	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FMH 67 End MH: FMH 68 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



9.8M JN Line Drops In From The Left From FIC 18
11.8M JN Line Drops In From The Right From FIC 19

38.0M MH Camera Enters Manhole FMH 68

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 22	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 22 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 22

4.0M JN Line Drops In From The Left

Flow

8.9M JN Line Drops In From The Right

LAT 1

9.2M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 23	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 22 End MH: LAT 2 Total Length:	
Purpose: Structural Defects Use: FOUL Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 24	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 22 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 25	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 22 End MH: FIC 23 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 26	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 23 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 27	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 23 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 28	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 23 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 23

5.2M JN Line Drops In From Above

Flow

9.3M JN Line Drops In From The Left

LAT 3

10.2M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 29	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 23 End MH: FMH 54 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE BUT THE MAINLINE IS RUNNING HIGH SO THERE IS WATER LAYING IN THE PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 30	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 24 End MH: FIC 25 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



0.9M MH Camera Enters Manhole FIC 25

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 31	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 24 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 24

4.7M JN Line Drops In From The Left

Flow

LAT 1

8.9M JN Line Drops In From The Left

9.4M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 32	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 24 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 33	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 24 End MH: LAT 3 Total Length:	
Purpose: Structural Defects Use: FOUL Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

02392693923

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 34	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 25 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 25

4.4M JN Line Drops In From The Left

Flow

LAT 1

8.9M JN Line Drops In From The Right
9.4M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


ALL HOURS PLUMBING

Inspection Report

Date: 10/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 35	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 25 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 36	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 25 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 10/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 37	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 25 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 38	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 26 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 39	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 26 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 40	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 26 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

FIC 26

3.9M JN Line Drops In From The Right

8.5M JN Line Drops In From The Left

LAT 3

9.5M LU Line Turns Up

Flow

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects

Constructional Features

Service Defects


Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 41	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 26 End MH: FIC 27 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



0.5M MH Camera Enters Manhole FIC 27

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 42	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 27 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 43	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 27 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 44	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 27 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 45	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: FIC 27 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects FOUL P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 46	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 47	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 13

Flow

LAT 2

4.9M JN Line Drops In From The Right

8.3M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 48	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 49	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 13

Flow

LAT 4

6.5M JN Line Drops In From The Left

9.6M LU Line Turns Up To Rodding Eye

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 50	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: LAT 5 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

70 [REDACTED]
[REDACTED]
[REDACTED] 23

ALL HOURS PLUMBING


Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 51	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 13 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

1.6M PC Pipe Changes To Clay
1.8M MC Multiple Cracks In Pipe



REM; THERE ARE MULTIPLE CRACKS IN THE PIPE AT 1.8 METRES WHICH CAN BE PATCH REPAIRED

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection Photos

Place
PLOTS 88-78
LITTLEHAMPTON

Date:
11/06/26

Section Number
52A


PLR:

11-06-26

1.60m

PPCP 13 DS TO MAIN

100MM




MULTIPLE CRACKS IN PIPE

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 53	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 14 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 54	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 14 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 55	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 14 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey

0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 56	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 14 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report


Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 57	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 14 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

0.7M PC Pipe Changes To Clay

5.9M LD Line Drops into Main



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 58	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 59	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 15

Flow

LAT 2

5.4M JN Line Drops In From The Right

8.2M LU Line Turns Up To Rodding Eye

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects

Constructional Features

Service Defects


Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 60	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 61	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 15

5.3M JN Line Drops In From The Left
6.0M WL Water Level 20 %

Flow

LAT 4

11.5M LU Line Turns Up

REM; THERE IS AN UNDEROW IN THIS SECTION OF PIPE FROM 6 METRES TO BOTTOM OF STACK

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features




ALL HOURS PLUMBING

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 62	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: LAT 5 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 63	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 15 End MH: SMH 7 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



1.2M PC Pipe Changes To Clay

6.4M MH Camera Enters Manhole S 7

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 64	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 16 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 65	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 16 End MH: PPCP 17 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 66	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 17 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



9.9M JN Line Drops In From The Left

12.7M LD Line Drops Into Main

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 67	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 18 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 68	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 18 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 69	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 20 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 70	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 20 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 71	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 20 End MH: PPCP 21 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 72	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 21 End MH: SMH 43 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 74	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: SMH 43 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 78	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 19 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 79	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 19 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



1.2M WL Water Level 20 %

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 80	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 22 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 81	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 22 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 82	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 22 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 11/06/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 83	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; Plots 88-78 Place ; Littlehampton		Division: District: Tape No: 1		Start MH: PPCP 22 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features