




Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 2	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 30 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING**Inspection Report**

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 3	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 30 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 30

Flow

LAT 2

6.4M JN Line Drops In From The Right

8.7M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects**Constructional Features**

Service Defects


Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 4	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 30 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 5	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 30 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 6	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 30 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

REM; THERE IS AN UNDERROLL IN THIS SECTION OF PIPE

Structural Defects**Constructional Features**

Service Defects


Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 7	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 31 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 8	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 31 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 9	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 31 End MH: CRATES SYSTEM Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 10	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 32 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 11	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 32 End MH: SMH 40 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

0.5M MC Pipe Changes To Clay



8.1M MH Camera Enters Manhole SMH 40

REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 12	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SMH 40 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 13	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 33 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 14	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 33 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:		Structural Defects STORM P1 Schedule			
		Size/Shape: Material: Lining: Category:			
		Circular dia 100MM PLASTIC			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 15	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 33 End MH: CRATE SYSTEM Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 16	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 34 End MH: LAT 1 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 17	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 34 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features



Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 18	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 34 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 19	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 35 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 20	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 35 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 21	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 36 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 22	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 36 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 23	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 24	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: LAT 2 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 25	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 26	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 37

6.0M JN Line Drops In From The Left

Flow

LAT 4

9.2M LU Line Turns Up To Rodding Eye

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects

Constructional Features

Service Defects


Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 27	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: LAT 5 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 28	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 37 End MH: MAIN Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 29	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 38 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 30	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 38 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 31	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 38 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 38

6.7M JN Line Drops In From The Left

Flow

LAT 3

10.0M LU Line Turns Up To Rodding Eye

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 32	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 38 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 33	PLR: 		
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:		
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 38 End MH: MAIN Total Length:			
Purpose: Use: Catchment:		Structural Defects STORM P1 Schedule				Size/Shape: Material: Lining: Category:	Circular dia 100MM PLASTIC



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 35	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 1 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 36	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 1 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 37	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 1 End MH: PPCP 39 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 38	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 39 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 39	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 39 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 40	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 2 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 41	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 2 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 42	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 2 End MH: PPCP 39 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 43	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 3 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 44	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 3 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 45	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 3 End MH: PPCP 40 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 46	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 40 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 47	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 40 End MH: SIC 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 48	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 4 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 49	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: SIC 4 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:		Structural Defects STORM P1 Schedule			
		Size/Shape: Material: Lining: Category:			
		Circular dia 100MM PLASTIC			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 50	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 40 End MH: MAIN Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 51	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 41 { HWCP 1] End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 52	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 41 End MH: SMH 37 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 58	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 42 End MH: SMH 14 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 60	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 43 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 61	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 43 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			


Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%
0.1M JN Line Drops In From The Right
0.5M WL Water Level 0 %

6.0M JN Line Drops In From The Right

8.2M WL Water Level 0 %

10.1M LU Line Turns Up To Rodding Eye



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 62	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 43 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 63	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 43 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 64	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 43 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 65	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 44 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 66	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 44 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 67	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 44 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 71	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 45 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THIS SECTION IS CAPPED OFF AND NOT CONNECTED TO CRATE SYSTEM

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 72	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 45 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

PPCP 45

4.4M JN Line Drops In From The Right

Flow

LAT 2

8.4M LU Line Turns Up And Capped Off

REM; THIS SECTION IS CAPPED OFF AND THE RODDING EYE HAS NOT BEEN INSTALLED YET

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report


Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 73	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 45 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%
0.8M JN Line Drops In From The Left

6.0M JN Line Drops In From The Left

10.4M LU Line Turns Up To Rodding Eye



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 74	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 45 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THIS SECTION HAS NOT BEEN CONNECTED TO THE CRATE SYSTEM


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 75	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 45 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS IN THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


ALL HOURS PLUMBING

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 76	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 46 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 77	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 46 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%
0.2M JN Line Drops In From The Left



6.9M JN Line Drops In From The Left
7.1M LU Line Turns Up To Rodding Eye

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 78	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 46 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 79	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 46 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 89	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 49 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 90	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 49 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 91	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 49 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 92	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 93	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 94	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: LAT 3 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 95	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 96	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: LAT 5 Total Length:	
Purpose: Use: Catchment:		Structural Defects STORM P1 Schedule			
		Size/Shape: Material: Lining: Category:			
		Circular dia 100MM PLASTIC			

Position Code Observation

0.0M ST Start Of Survey

0.0M WL Water Level 0%




REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No : 	Weather: DRY	Operator: MICK	Section Number 97	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 50 End MH: MAIN Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			



Structural Defects	Constructional Features
Service Defects	Miscellaneous Features


Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 81	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 47 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

1.0M JN Line Drops In From The Right



10.0M JN Line Drops In From The Right
10.6M LU Line Turns Up

REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 82	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 47 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 83	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 48 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 84	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 48 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 07/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 86	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 48 End MH: LAT 4 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 04/09/2026	Job No :	Weather: DRY	Operator: MICK	Section Number 87	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site ; 468 Place ; LITTLEHAMPTON		Division: District: Tape No: 1		Start MH: PPCP 48 End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100MM Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants

7

468 Littlehampton - Defects

PPCP 45 LAT 1 - NOT CONNECTED TO CRATE SYSTEM - PLOT 98
PPCP 45 LAT 2 - NOT CONNECTED TO RODDING EYE - PLOT 98
PPCP 45 LAT 4- NOT CONNECTED TO CRATE SYSTEM - PLOT 99