

13 South Terrace Floor 3



- 3 windows on the top floor are poorly double glazed and need to be replaced with more period symathetic timber windows. [redacted]
- Top floor bathroom – retile & add shower unit. [redacted]