

Photograph 01


General view of ceiling joist layout showing primary beam and non pairing of joists.



ARUN DISTRICT COUNCIL				
No.	LY	6	07	L.
RECEIVED	27.2.07.			

Photograph 02


Junction of joist and primary beam showing minimal joist bearing within beam.



ARUN DISTRICT COUNCIL				
No.	LY	6	07	L
RECEIVED	27.02.07			

Photograph 03

This shows the proportion of a joist cut away to accommodate service cables. Also raking cracking of the joist is clearly evident.



ARUN DISTRICT COUNCIL				
No.	LY	6	07	L
RECEIVED	27.2.07			

Photograph 04


Advanced beetle infestation to one of the joists.



ARUN DISTRICT COUNCIL				
No.	LY	6	07	L
RECEIVED	27.2.07			

Photograph 05

Extensive cutting away of joists to accommodate service cables.



ARUN DISTRICT COUNCIL				
No.	LY	6	07	L
RECEIVED	27.2.07			

Photograph 06

Area of modern sawn softwood joists which have been used to infill the space of an earlier staircase.



ARUN DISTRICT COUNCIL			
No.	LY	6	07/L
RECEIVED 27.2.07			