

NOTEPAD

OK

COMPENSATION - For full details of compensation please see Land Charges

compensation payable on whole of land.

DOE REF: 20/485

Church Farm Club

C18. Two storeys. Five windows. Red brick, with diaper pattern of grey

headers in west wall. Tiled roof. Glazing bars intact on first floor

only. Modern windows below. Modern ground floor supermarket addition in
front of each half of south front.

PDR P/25/92L - facing timber not to be stained (P/32/92)