

PHOTOGRAPHIC SCHEDULE: EXISTING FARMHOUSE

REPLACEMENT FARMHOUSE, FARM OFFICE & EQUESTRIAN FACILITIES

AT

GOOSE GREEN, HOE LANE, BINSTED, ARUNDEL, BN18 OLQ.



Plate I : West (front) elevation of existing house



Plate II : East (rear) elevation of existing house



Plate III : South elevation of existing house



Plate IV : North elevation of existing house



Plate V : South East elevation of existing house



Plate VI : Ground floor entrance hall – damaged ceiling




Plate VII : Ground floor front room



Plate VIII : Ground floor dining room – damaged ceiling with water ingress to the failing roof covering



Plate IX : Ground floor rear reception room



Plate X : Ground floor rear reception room – Further water ingress damage to ceilings



Plate XI : Rear ground floor - Structural cracking and water damage



Plate XII : Ground floor rear flat roofed area – Damp ingress to ceiling and failed glazing



Plate XIII : Ground floor – kitchen facilities.



Plate XIV : First floor – front bedroom with signs of rainwater ingress.



Plate XV : First floor north bedroom – Mould growth and worn fittings



Plate XVI : First floor – north bedroom



Plate XVII : First floor - bathroom