

**Project**


**Project Name:** Park Rd Culvert - Barnham

**Project Description:** Culvert Survey

**Project Status:** Complete

**Project Date:** 18/08/2024

**Inspection Standard:** MSCC5 Sewers & Drainage GB (SRM5 Scoring)



**EYES ON DRAINAGE**

**CCTV-Trace-Plot-Map-Repair**

## Table of Contents

Project Name Park Rd Culvert - Barnham	Project Number	Project Date 18/08/2024
Project Information .....		P-1
Scoring Summary .....		P-3
Section Profile .....		P-4
Section Summary .....		P-5
Section Item 1: HW1 > HW2 (HW1X) .....		1
Disclaimer .....		3

## Project Information


**Project Name**  
Park Rd Culvert - Barnham

**Project Number**

**Project Date**  
18/08/2024

### Client

**Company:** Folkes Architects  
**Department:** The Old Forge  
**Street:** 6 Church St  
**Town or City:** Storrington  
**County:** West sussex  
**Post Code:** RH20 4LA




### Site

**Description:** North of Lake Lane  
**Department:** Kilkenny  
**Street:** Park Rd  
**Town or City:** Barnham  
**County:** West Sussex  
**Post Code:** PO22 0AJ

### Contractor

**Company:** Eyes On Drainage Services Ltd  
**Contact:** Jay Young  
**Department:** Merrion House  
**Street:** Bines Green  
**Town or City:** Horsham  
**County:** West Sussex  
**Post Code:** RH13 8EH  
**Phone:** 01403 710971  
**Mobile:** 077111 84951  
**Email:** info@eyesondrainage.co.uk



## Project Information

Project Name  
Park Rd Culvert - Barnham

Project Number

Project Date  
18/08/2024

### Project Drawing, Page 'Park Rd Culvert - Barnham'



## Scoring Summary

Project Name Park Rd Culvert - Barnham	Project Number	Project Date 18/08/2024
---	----------------	----------------------------

### Structural Defects

Section	PLR	Grade	Description
All inspected pipes are in an acceptable structural condition (< grade 3).			

### Service / Operational Condition

Section	PLR	Grade	Description
All inspected pipes are in an acceptable service condition (< grade 3).			

### Abandoned Surveys

Section	PLR	Description
All inspections complete, none are abandoned.		

### Information

These scoring summaries are based on the SRM grading from the WRc.

## Section Profile

**Project Name**  
 Park Rd Culvert - Barnham

**Project Number**

**Project Date**  
 18/08/2024

### Circular, 450 mm

Item No.	Upstream Node	Downstream Node	Date	Road	Material	Total Length	Inspected Length
1	HW1	HW2	18/08/2024	Park Rd	Concrete	55.00 m	55.00 m

**Total: 1 Inspection x Circular 450 mm, 0 mm = 55.00 m Total Length and 55.00 m Inspected Length**

Total: 1 Inspection = 55.00 m Total Length and 55.00 m Inspected Length

## Section Summary

Project Name	Project Number	Project Date
Park Rd Culvert - Barnham		18/08/2024

Number of sections	1
Total length of sections	55.00 m
Total length of inspected sections	55.00 m
Total length of not inspected sections	0.00 m
Number of abandoned inspections	0
Number of section inspection photos	4
Number of section inspection videos	0
Number of section inspection scans	0
Number of section inclination measurements	0

<b>PLR:</b>	HW1X	<b>Upstream Node:</b>	HW1
<b>Inspection Direction:</b>	Downstream	<b>Downstream Node:</b>	HW2
<b>Inspected Length:</b>	55.00 m	<b>Dia/Height:</b>	450 mm
<b>Total Length:</b>	55.00 m	<b>Material:</b>	Concrete

No.	m+	Code	Observation
1	0.00	OF	Start node, outfall, reference: HW1, Located within private grounds
2	0.00	WL	Water level, 0% of the vertical dimension
3	0.00	WL	Water level, 70% of the vertical dimension
4	55.00	OFF	Finish node, outfall, reference: HW2, Unable to carry out full CCTV survey due to permissions.

**Section Inspection - 18/08/2024 - HW1X**


Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
1	1	18/08/24	7:51	Not Specified	No Rain Or Snow	No	HW1X
<b>Operator</b> JY		<b>Vehicle</b> BV21 CDX		<b>Camera</b> Not Specified	<b>Preset Length</b> Not Specified	<b>Legal Status</b> Watercourse	<b>Alternative ID</b> Not Specified

<b>Town or Village:</b>	Barnham	<b>Inspection Direction:</b>	Downstream	<b>Upstream Node:</b>	HW1
<b>Road:</b>	Park Rd	<b>Inspected Length:</b>	55.00 m	<b>Upstream Pipe Depth:</b>	
<b>Location:</b>	Gardens (private)	<b>Total Length:</b>	55.00 m	<b>Downstream Node:</b>	HW2
<b>Surface Type:</b>	Various	<b>Joint Length:</b>		<b>Downstream Pipe Depth:</b>	

<b>Use:</b>	Culverted watercourse	<b>Pipe Shape:</b>	Circular
<b>Type of Pipe:</b>	Gravity drain/sewer	<b>Dia/Height:</b>	450 mm
<b>Flow Control:</b>	No flow control	<b>Material:</b>	Concrete
<b>Year Constructed:</b>	Not Specified	<b>Lining Type:</b>	No Lining
<b>Inspection Purpose:</b>	Routine inspection	<b>Lining Material:</b>	No Lining

**Comments:**
**Recommendations:**

Scale: 1:477	Position [m]	Code	Observation	MPEG	Photo	Grade
--------------	--------------	------	-------------	------	-------	-------

**Depth: m**
**HW1**


0.00 OF Start node, outfall, reference: HW1: Located within private grounds

1, 2

0.00 WL Water level, 0% of the vertical dimension

0.00 WL Water level, 70% of the vertical dimension

00:00:01

**HW2**
**Depth: m**

55.00

OFF Finish node, outfall, reference: HW2: Unable to carry out full CCTV survey due to permissions.

3, 4

Construction Features					Miscellaneous Features						
Structural Defects					Service & Operational Observations						
STR No.	Def	STR Peak	STR Mean	STR Total	STR Grade	SER No.	Def	SER Peak	SER Mean	SER Total	SER Grade
0		0.0	0.0	0.0	1.0	0		0.0	0.0	0.0	1.0

**Section Pictures - 18/08/2024 - HW1X**

Item No.	Inspection Direction	PLR	Client's Job Ref	Contractor's Job Ref
1	Downstream	HW1X		


**1, 0.00 m**

Start node, outfall, reference: HW1, Located within private grounds


**2, 0.00 m**

Start node, outfall, reference: HW1, Located within private grounds


**3, 55.00 m**

Finish node, outfall, reference: HW2, Unable to carry out full CCTV survey due to permissions.


**4, 55.00 m**

Finish node, outfall, reference: HW2, Unable to carry out full CCTV survey due to permissions.

## **Disclaimer**

Although every effort has been made to produce a thorough and precise report, Eyes On Drainage Services Ltd cannot be held liable for any discrepancies or omissions.

Furthermore Eyes On Drainage Services Ltd cannot be held responsible for any actions taken based on the information supplied within this report.