



Outfalls - see separate drawings for detail.

4 off greenhouse drains identified and shown on drawing "Pipes and inverts"

Pipes and inspection chambers constructed in accordance with standard practice. Pipes laid with falls shown on drawing "Invert levels and pipe details". Pipes bedded on sand as required according to spoil material type.

Flerurie Nursery
Lakes Lane
Barnham

Drainage

Pipe routes

Date: 23.11.23
Scale 1:1000 (A1)
Drawn AM

Revisions

Hennock International Ltd

Church Road
Hennock
Newton Abbot
Devon TQ13 9QE