

ALL HOURS PLUMBING

All Hours Plumbing Ltd
70 Widley Road, Stamshaw
Portsmouth, Hants
Tel: [REDACTED]

Project-Information

Project Name: Tye Lane	Contract Number:	Contact: Aeropark	Date: 14/04/2026
---------------------------	------------------	----------------------	---------------------

Client:	Aeropark
Contact:	
Position:	
Road:	Hounsdown House, Hounsdown Business Park
Town:	Southampton
Post Code:	SO40 9LX
County:	Hampshire
Telephone:	

Contractor:	All Hours Plumbing Ltd
Contact:	Steve Guest
Position:	Owner
Road:	70 Widley Road, Stamshaw
Town:	Portsmouth
County:	Hampshire
Telephone:	[REDACTED]
Fax:	
E-Mail:	[REDACTED]


Site:	Tye Lane
Engineer:	
Position:	
Road:	Tye Lane
Town:	Walberton
County:	West Sussex
Telephone:	

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 2	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site: Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 14 End MH: SMH 13 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 375mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



5.0M JN Line Drops In From The Left

6.1M JN Line Drops In From The Right

13.1M MH Camera Enters Manhole S 13

REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 3	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 13 End MH: SMH 12 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 375mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO DEFECTS WITH THE PIPEWORK BUT THERE IS DEBRIS IN THE LINE, WE HAVE TRIED TO REMOVE AS MUCH AS WE CAN BY BACK JETTING THE LINE AS UNABLE TO GET LORRY NEAR TO MANHOLE S 12


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 4	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site: Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 12 End MH: SMH 11 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 450mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %
1.9M JN Line Drops In From Above



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 5	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site: Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 11 End MH: SMH 10 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 450mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 6	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 9 End MH: SMH 10 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 450mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 14/04/2026	Job No:	Weather: Dry	Operator: Mick	Section Number 7	PLR:
Present:	Vehicle: [REDACTED]	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site: Tye Lane Place: Walberton		Division: District: S.W Tape No: 1		Start MH: SMH 9 End MH: SMH 8 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 450mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM ; THERE ARE NO MAJOR DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features