


Inspection Report

|                                      |                                           |                                                                             |                   |                                                    |        |
|--------------------------------------|-------------------------------------------|-----------------------------------------------------------------------------|-------------------|----------------------------------------------------|--------|
| Date:<br>17/12/24                    | Job No:                                   | Weather:<br>Dry                                                             | Operator:<br>Mick | Section Number<br>13                               | PLR:   |
| Present:                             | Vehicle:<br>WM69 YNA                      | Camera:<br>Camera 1                                                         | Preset:           | Cleaned:<br>YES                                    | Grade: |
| Site; Tye Lane<br>Place: Warblington |                                           | Division:<br>District: S.W<br>Tape No: 1                                    |                   | Start MH: F31.1B<br>End MH: LAT 1<br>Total Length: |        |
| Purpose:<br>Use:<br>Catchment:       | Structural Defects<br>FOUL<br>P1 Schedule | Size/Shape: Circular dia 100mm<br>Material: PLASTIC<br>Lining:<br>Category: |                   |                                                    |        |

Position Code Observation

0.0M ST Start Of Survey  
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

|                    |                         |
|--------------------|-------------------------|
| Structural Defects | Constructional Features |
| Service Defects    | Miscellaneous Features  |