


Inspection Report

|                                      |                                           |                                                                             |                   |                                               |        |
|--------------------------------------|-------------------------------------------|-----------------------------------------------------------------------------|-------------------|-----------------------------------------------|--------|
| Date:<br>17/12/24                    | Job No:                                   | Weather:<br>Dry                                                             | Operator:<br>Mick | Section Number<br>44                          | PLR:   |
| Present:                             | Vehicle:<br>WM69 YNA                      | Camera:<br>Camera 1                                                         | Preset:           | Cleaned:<br>YES                               | Grade: |
| Site; Tye Lane<br>Place: Warblington |                                           | Division:<br>District: S.W<br>Tape No: 1                                    |                   | Start MH: F31<br>End MH: F30<br>Total Length: |        |
| Purpose:<br>Use:<br>Catchment:       | Structural Defects<br>FOUL<br>P1 Schedule | Size/Shape: Circular dia 150mm<br>Material: PLASTIC<br>Lining:<br>Category: |                   |                                               |        |

Position Code Observation

0.0M ST Start Of Survey  
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

|                    |                         |
|--------------------|-------------------------|
| Structural Defects | Constructional Features |
| Service Defects    | Miscellaneous Features  |