

Inspection Report

Date: 17/12/24	Job No:	Weather: Dry	Operator: Mick	Section Number 55	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: YES	Grade:
Site; Tye Lane Place: Warblington		Division: District: S.W Tape No: 1		Start MH: S13.2 End MH: S13.1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%
0.7M JN Line Drops In From The Right

2.2M JN Laine Drops In From The Right

3.6M JN Line Drops In From The Left

8.5M MH Cameras Enters Manhole S13.1

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features