


Inspection Report

|                                      |                                            |                                                                             |                   |                                                   |        |
|--------------------------------------|--------------------------------------------|-----------------------------------------------------------------------------|-------------------|---------------------------------------------------|--------|
| Date:<br>17/12/24                    | Job No:                                    | Weather:<br>Dry                                                             | Operator:<br>Mick | Section Number<br>64                              | PLR:   |
| Present:                             | Vehicle:<br>WM69 YNA                       | Camera:<br>Camera 1                                                         | Preset:           | Cleaned:<br>YES                                   | Grade: |
| Site; Tye Lane<br>Place: Warblington |                                            | Division:<br>District: S.W<br>Tape No: 1                                    |                   | Start MH: S11.1<br>End MH: LAT 2<br>Total Length: |        |
| Purpose:<br>Use:<br>Catchment:       | Structural Defects<br>STORM<br>P1 Schedule | Size/Shape: Circular dia 100mm<br>Material: PLASTIC<br>Lining:<br>Category: |                   |                                                   |        |

Position Code Observation

0.0M ST Start Of Survey  
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS IN THIS SECTION OF PIPE

|                    |                         |
|--------------------|-------------------------|
| Structural Defects | Constructional Features |
| Service Defects    | Miscellaneous Features  |