


Project-Information

Project Name: 386 Yapton	Contract Number:	Contact:	Date: 01/05/25
-----------------------------	------------------	----------	-------------------

Client:	Parchow Groundworks Limited
Contact:	
Position:	
Road:	New Down Lane
Town:	Waterlooville
Post Code:	PO7 5SE
County:	Hampshire
Telephone:	
Contractor:	All Hours Plumbing Ltd
Contact:	Steve Guest
Position:	Owner
Road:	70 Widley Road, Stamshaw
Town:	Portsmouth
County:	Hampshire
Telephone:	[REDACTED]
Fax:	[REDACTED]
E-Mail:	[REDACTED]
Site:	386
Engineer:	
Position:	
Road:	
Town:	Yapton
County:	Hampshire
Telephone:	

Page 1

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 2	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S15 End MH: S16 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 3	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S16 End MH: S20 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

--	--	--	--	--	--

Depth:	M	Position	Code	Observation
		0.0M	ST	Start Of Survey
		0.0M	WL	Water Level 20 %
		7.3M	L	Line From Left
		9.6M	L	Line From Left
		14.5M	L	Line From Right
		17.0M	L	Line From Left
		18.6M	L	Line From Left
		30.4M	MH	S20

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 4	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S18 End MH: S17 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

Page 4

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 5	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S20 End MH: S21 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 20 %

S20

Flow

8.5M L Line From Left

13.6M MH S21

S21

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 6	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S5 End MH: S2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 20 %

S5



10.4M L Line From Left From S 1, But Manhole S 1 Not Installed

19.1M MH S2

Flow

S2

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 7	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S5 End MH: S12 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 8	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: Culvert End MH: US Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 20 %

Culvert

5.0M E End Of Line

Flow

US

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 9	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S36 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

--	--	--	--	--	--

Depth:	M	Position	Code	Observation
		0.0M	ST	Start Of Survey
		0.0M	WL	Water Level 0 %
		0.1M	L	Line From Right
		11.1M	L	Line From Right
		14.8M	L	Line From Right
		16.7M	L	Line From Right
		20.2M	MH	Manhole


REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 10	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S36 End MH: S12 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

--	--	--	--	--	--




REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 11	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S12 End MH: S13 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 12	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S13 End MH: S21 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



18.7M MH S21

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 13	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S31 End MH: S41 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 14	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S31 End MH: S30 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		


Page 14

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 15	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S39 End MH: S39A Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 100mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects


Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 16	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S39 End MH: S22 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



5.8M MH S22

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 17	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S22 End MH: S38 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

--	--	--	--	--	--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK. MANHOLE S 38 WAS NOT INSTALLED AND LINE TURNS UP TO DOWNPIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 18	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S22 End MH: S23 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.5M MH S23

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 19	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S23 End MH: S24 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

--	--	--	--	--	--




REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 20	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S25 End MH: S24 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 21	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw	orks	Division: District: Tape No: 1		Start MH: S25 End MH: S40 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		


Page 21

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 22	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S25 End MH: S26 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



7.2M MH S26

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 23	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S32 End MH: LAT 1 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %

S32

7.7M L Line From Right

14.7M L Line From Right

21.8M MH Manhole

Flow

LAT 1

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects


Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 24	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S32 End MH: S31 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 25	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S33 End MH: S32 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

--




REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 26	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S33 End MH: S34 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		




Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 27	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S34 End MH: S35 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 28	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw Place ; Yapton Site	orks	Division: District: Tape No: 1		Start MH: S35 End MH: Crates Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 225mm Plastic		

--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 29	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S27 End MH: S26 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 300mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %

2.8M L Line From Right

10.5M L Line From Right

15.5M L Line From Right

23.2M L Line From Right

24.2M L Line From Right

38.2M L Line From Right

41.1M MH S26

Flow

S26

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 30	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S26 End MH: S21 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 300mm Plastic		

Depth: M Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0 %

S26

26.3M L Line From Right

33.8M L Line From Right

46.1M MH S21

Flow

S21

REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects

Constructional Features


Service Defects

Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 31	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundw orks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S27 End MH: S28 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 300mm Plastic		

--	--	--	--	--	--




REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 01/05/25	Job No :	Weather: Dry	Operator: KEV	Section Number 32	PLR:
Present:	Vehicle: LC17 YPU	Camera: Camera 2	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place ; Yapton Site		Division: District: Tape No: 1		Start MH: S28 End MH: S29 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 300mm Plastic		

--	--	--	--	--	--



REM, THERE ARE NO PROBLEMS WITH THIS SECTION OF PIPEWORK.


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 33	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton		Division: District: S.W Tape No: 1		Start MH: SMH 36 End MH: LAT 2 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 150mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 34	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton		Division: District: S.W Tape No: 1		Start MH: SMH 4 End MH: SMH 5 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 150mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 35	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton		Division: District: S.W Tape No: 1		Start MH: SMH 3 End MH: SMH 4 Total Length:	
Purpose: Structural Defects Use: STORM Catchment: P1 Schedule		Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%
0.2M JN Line Drops In From The Left



8.3M JN Line Drops In From The Left

18.7M JN Line Drops In From The Left From SMH 4A

21.0M LD Line Drops Down
21.8M MH Camera Enters Manhole S 4

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 36	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton		Division: District: S.W Tape No: 1		Start MH: SMH 4A End MH: MAIN Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 100mm PLASTIC		

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



1.7M JN Line Drops In From The Left

2.9M JN Line Drops In From The Right

12.1M JN Line Drops In From The Left
12.9M LD Line Drops Into Main

REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects

Constructional Features

Service Defects

Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 37	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton24.2		Division: District: S.W Tape No: 1		Start MH: SMH 14 End MH: SMH 15 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 150mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%


5.4M PR Start Of Patch Repair
6.0M PR End Of Patch

9.4M JN Line Drops In From The Left

12.3M JN Line Drops In From The Left

19.1M JN Line Drops In From The Left

24.2M MH Camera Enters Manhole S 15



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 38	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton24.2		Division: District: S.W Tape No: 1		Start MH: SMH 17A End MH: SMH 1A Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 100mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE


Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 39	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton24.2		Division: District: S.W Tape No: 1	Start MH: SMH 17A End MH: SOAKAWAY Total Length:		
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Material: Lining: Category:	Circular dia 150mm PLASTIC		

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features

Inspection Report

Date: 13/05/25	Job No:	Weather: Dry	Operator: Mick	Section Number 40	PLR:
Present:	Vehicle: WM69 YNA	Camera: Camera 1	Preset:	Cleaned: Yes	Grade:
Site; Parchow Groundworks Place: Yapton24.2		Division: District: S.W Tape No: 1		Start MH: SMH 33 End MH: SMH 46 Total Length:	
Purpose: Use: Catchment:	Structural Defects STORM P1 Schedule	Size/Shape: Circular dia 150mm Material: PLASTIC Lining: Category:			

Position Code Observation

0.0M ST Start Of Survey
0.0M WL Water Level 0%

1.6M JN Line Drops In From The Left


8.1M JN Line Drops In From The Left

14.6M JN Line Drops In From The Left

21.8M JN Line Drops In From The Left

24.8M JN Line Drops In From The Left

31.0M MH Camera Enters Manhole S 46



REM ; THERE ARE NO DEFECTS WITH THIS SECTION OF PIPE

Structural Defects	Constructional Features
Service Defects	Miscellaneous Features