

Heritage statement 19 Maltravers Street Arundel

Boundary wall/fence repair and resite with new wooden fence

The proposed alteration are for a rear boundary wall/fence only and are in keeping with the current brick wall, although some bricks will need repair.

The metal gate is broken and the metal railings are in disrepair. Similar to the neighbouring houses we wish to have improved security with a more secure and more attractive wooden gate and fence screen on top of the existing brickwork.

The proposal by no means affects the l
'look of the building' or access to it. It enhances it.