



North side of building (facing London Road)




South side of building (facing courtyard)



Main Hall looking WEST



Elements for retention and re-use - glazed doors and panelling



View of courtyard gate to be widened



Main Hall looking EAST - servery and bar on lhs



Elements for stripping out - servery and bar area, with infill in arched openings removed to form open arches where shown on plan



Lower Ground floor meeting room area - showing cast iron posts and infill to external arches where brickwork and windows are to be removed and new glazing screens installed in historic open arches



View of courtyard gate to be widened

<div>GENERAL NOTES</div> <div>SCALING OFF THIS DRAWING SHOULD NOT BE RELIED UPON.</div> <div>Use Mapped dimensions where shown.</div> <div>Site measurements should be taken to ensure accuracy</div> <div>NEW WORK OR ANY EXISTING WORK AFFECTED IS SHOWN IN RED ON DRAWINGS.</div> <div>This drawing to be read in conjunction with Structural Engineer's Calculations.</div> <div>Check dimensions prior to construction or off-site fabrication.</div> <div>Please inform Architect or Drawing Originator of any discrepancy immediately.</div>		Revisions:		ARUNDEL CATHEDRAL	
PHOTOGRAPHIC IMAGES OF BUILDING AS EXISTING		ST. MARY'S HALL Refurbishment			
Dwg no.	766/22/25	Rev.			
ST ANN'S GATE ARCHITECTS LLP The Close, Salisbury, SP1 2EB Tel: 01722 555200 Fax: 01722 555201 e: admin@stannsgate.com w: www.stannsgate.com					
Scale:		Not applicable			
Date:		FEB 2011		Drawn: MTL	
© This drawing may not be reproduced without the prior knowledge and consent of St Ann's Gate Architects LLP					