

Shripney Road Flood waters at drive entrance to 2 New Cottages 11 June 2012



We understand from our clients the water level was 150mm above the crown of the road



the crown being 1.0m below ground level at the front door. There is evidently no substantial run off from the higher land adjacent to the house with the gardens remaining flood free