




Sent: 29 July 2015 13:18

To: Simon Davis

Cc: Peter Greenwood; Sandy White

Subject: 11 Marquis Way - AW/181/15/HH

john wheatley
architecture

Dear Simon

I have realised that the position of the existing dormer window, within the existing elevations (PL09 B) located in the eastern elevation of the existing garage roof, is located in the wrong position, within the roof slope (closer to the main facade).

I have therefore amended this drawing and attach a revised copy (PL09 C), plus an amended copy of the overlay drawing PL40 (now revision A), issued yesterday.

This is a minor amendment but I thought it better to ensure a true representation of the existing elevation.

Kind regards

John Wheatley

30 Maltravers Street - Arundel - West Sussex - BN18 9BU

