

Our ref. J36.06

TREE INSPECTIONS AT
ALDWICK BAY ESTATE, ALDWICK, WEST SUSSEX

Broad Oak Tree Consultants Ltd.
November 2010
Updated January 2016
Re-inspected July 2021

Tree ref. no.	Species	Height (m.)	Crown spread (m.)				Diam. at breast ht. (cm)	Maturity class	Longevity	Work Priority	Vigour	Notes	Recommendations
			N	E	S	W							
130	Scots Pine	8	4	7	4	4.5	42	MA	10-20	M	L	Thinning crown. Deadwood. Kinked stem to E. and bowed over. Tear wound at 3.5m to N. Deadwood.	Deadwood crown.
132	Pine	8	2.5	4	4	2.5	40	MA	<10	-	L	Thinning foliage. Lopsided crown. Three stems from under 2m. Stem to E. reduced to stub. Deadwood.	
133	Italian Alder	14	6	5	4.5	4.5	68	MA	40+	-	G	Thinning upper crown.	
134	Crimson Norway Maple	8	2.5	5	4	3.5	37	Y	40+	-	AV		
135	Pine	9	6.5	7.5	6.5	5	80	Y	40+	-	G	Dense crown. Surface root wounding.	
136	Eucalyptus	10	c5	6	4.5	4	c70	MA	40+	-	G	Reduced all over in past. Kinked stem.	
137	Maple	9	4.5	4	4.5	4	55	MA	10-20	-	L	Thinning upper crown. Multi stemmed at 1.7m. Crown raised in past.	
138	Eucalyptus	10	c6	4	4.5	4	<40	MA	40+	-	G	Multi stemmed from under 1.3m. Reduced in past with vigorous regrowth.	
139	Holm Oak	11	4	5.5	c3	4.5	<50	Y	40+	-	G	Multi stemmed from under 2m with weak unions. Recently pruned back to N. in past and topped.	