




- INDICATIVE OVERHEAD POWER CABLE AT THE SOUTHERN BOUNDARY LINE



KEY TO HEALTH AND SAFETY SYMBOLS

ABNORMAL OR UNUSUAL RESIDUAL RISK
ASSOCIATED WITH THE DESIGN OUTCOME
OWN ON THIS DRAWING MAYBE INDICATE
MEANS OF THE FOLLOWING SYMBOLS.

	INDICATES A RESIDUAL RISK REQUIRING A COMPULSORY ACTION
	INDICATES A RESIDUAL RISK FOR INFORMATION.
	INDICATES A RESIDUAL RISK REQUIRING A PROHIBITIVE ACTION
	INDICATES A RESIDUAL RISK AS WARNING.

FLOW ADDED AT S17, S25, S42, S43, S44, S45. R BUTTS INDICATED	AK	BO	BAC	12.06.26
CONTRIBUTING AREA UPDATED	AK	BO	BAC	30.03.26
INDWATER MONITORING RESULTS NOTED, SA1 STED	AK	BO	BAC	05.03.26
SHAPE ADJUSTED	AK	BO	BAC	03.11.25
SA3 AND SA4 UPDATES TO ADDRESS ARUN DC MENTS OF 12/09/2025	AK	BO	BAC	09.10.25
amendments	Drrn	Chk	App	Date

 **ODYSSEY**

Tuscany House
White Hart Lane
Basingstoke
Hampshire RG21 4AF

Telephone: 01256 331144
Fax: 01256 331134
E: info@odysseyconsult.co.uk
W: www.odysseyconsult.co.uk

FORMER SHRUBLANDS NURSERY
ROUNDSTONE LANE, ANGMERING

DRAINAGE ALTERATION WORKS

SIGMA HOMES

Scale 1:200 @A1	Date JUL 2025	Designed AK	
Drawn AK	Checked BO	Approved BAC	
Job No 21-254	Drawing No 21-254-703		Rev E