

TREE CONSTRAINTS KEY

Existing tree/hedgerow, as surveyed.

Trees included in the Tree Report LLD288, but not found in the topographic survey so may not be present on site. Locations and dated are approximate. The spread shown is taken from Report LLD288

trees for removal.

Direction of inclination of tree (if applicable).

line of root protection area (RPA).
Dimension noted.

Tree data taken from Report LLD288 (Revised 10 May 2011).
Tree spreads and locations as surveyed by Aworth Land
Surveys, October 2013.

tree protection fencing as shown above
protective fencing to be moved to temporary
position to allow for construction
Areas to be constructed using No dig
method of construction

Free Protection

The protective fencing shall comprise of scaffolded framework in accordance with Figure 2 of British Standard BS5937 (2012) comprising of a vertical and horizontal framework, well braced to resist lateral impacts, with vertical bays spaced at a maximum interval of 3 m. On the widest panel there shall be securely fastened with wire or scaffold clamps. Widesheet panel on rubber or concrete feet shall be resistant to impact and shall not be used. Construction Erection Zone signs shall be used to every fourth panel. Once erected this fencing must remain in situ until the development has been completed.

Where branches of retained trees are outside the protection fencing, then felling should be moved further out to protect branches from vehicle/machine damage, if space permits.

If there is not sufficient space then end as shown but advise the consultant arboriculturist who will be able to advise on the best course of action (e.g. tree surgery).

All tree protection fencing should have all weather notices stating "construction exclusion zone - no access"


No material to be stored within the PRA areas or in a position where accidental spillage would cause damage to a tree.

Fencing will be ended prior to any trades (with the exception of tree surgeons) working near trees. All trades, especially civil engineering sub-contractors and group workers, will be made aware that damaged fencing erected around trees is to be reported to the site management immediately, who will ensure that the fencing repaired as soon as possible. Any tree work required is to be notified to the local authority tree officer. Offending sub-contractors may be penalised.

Above soil surfacing within RPA's

and sufficient for the proposed driveway within the RPA of the bus/sharing clubbing stall be constructed using a below oil surface design. This shall be in accordance with Motor Vehicle Practice Note 12 (2007). Through the items to be developed and also in accordance with guidance set out in section A.1.5 of BS 5307: 2012 (2) in relation to design, construction and construction - Recommendations. There shall be no lowering of existing levels or interference of any roads.

Example of Above soil surfacing




- Conversation with in RPAs

[illegible]

Figure 2 Default specification for protective barrier

Figure 2 Default specification for protective barrier



Free Protection

The protective fencing shall comprise of scaffolded framework in accordance with Figure 2 of British Standard BS5937 (2012) comprising of a vertical and horizontal framework, well braced to resist lateral impacts, with vertical bays spaced at a maximum interval of 3 m. On the widest panel there shall be securely fastened with wire or scaffold clamps. Widesheet panel on rubber or concrete feet shall be resistant to impact and shall not be used. Construction Erection Zone signs shall be used to every fourth panel. Once erected this fencing must remain in situ until the development has been completed.

Where branches of retained trees are outside the protection fencing, then felling should be moved further out to protect branches from vehicle/machine damage, if space permits.

If there is not sufficient space then end as shown but advise the consultant arboriculturist who will be able to advise on the best course of action (e.g. tree surgery).

All tree protection fencing should have all weather notices stating "construction exclusion zone - no access"


No material to be stored within the PRA areas or in a position where accidental spillage would cause damage to a tree.

Fencing will be ended prior to any trades (with the exception of tree surgeons) working near trees. All trades, especially civil engineering sub-contractors and group workers, will be made aware that damaged fencing erected around trees is to be reported to the site management immediately, who will ensure that the fencing repaired as soon as possible. Any tree work required is to be notified to the local authority tree officer. Offending sub-contractors may be penalised.

Above soil surfacing within RPA's

and sufficient for the proposed driveway within the RPA of the bus/sharing clubbing stall be constructed using a below oil surface design. This shall be in accordance with Motor Vehicle Practice Note 12 (2007). Through the items to be developed and also in accordance with guidance set out in section A.1.5 of BS 5307: 2012 (2) in relation to design, construction and construction - Recommendations. There shall be no lowering of existing levels or interference of any roads.

Example of Above soil surfacing



- Conversation with in RPAs

[illegible]