




18 Frogmore Road
Hemel Hempstead
Hertfordshire
HP3 8RT
UK

Our Ref: 1921454L01/nba
12 May 2021

Matthew Homes
Matthew House,
45-47 High Street,
Potters Bar
EN6 5AW



For the attention of T Griffiths

Dear Sirs,

THE LILIES, YAPTON ROAD, BARNHAM – WINTER GROUNDWATER MONITORING 2020/2021

1. BACKGROUND

RSK Environment Limited (RSK) was commissioned by Matthew Homes (the client) to carry out an additional ground investigation at the above named site.

Geo-environmental site assessments have previously been undertaken at the site, which are outlined in the following reports*:

- John Sime and Associates Limited – Site Investigation ref CL/5872, dated November 2015.
- Herts and Essex – Site investigation ref MRS/14074, dated May 2017.

*these reports are available upon request

The site is planned for residential redevelopment comprising low rise residential properties with associated infrastructure and soft landscaping.

The objective of the additional site investigation/monitoring was to establish groundwater levels over the winter of 2020/2021.

This letter report is subject to the service constraints laid out in **Appendix A**.



THE QUEEN'S AWARD
FOR ENTERPRISE
FOR EXPORTING
2019



MANAGEMENT SYSTEM CERTIFICATION
ISO 9001:2015 ISO 14001
ISO 45001



INVESTORS
IN PEOPLE

RSK Environment Ltd

Registered office

88 Sussex Street • Glasgow • Scotland • G4 1DX • UK

Registered in Scotland No. 115530

www.rsk.co.uk

2. GROUNDWATER MONITORING

A total of 6 window sample holes (Locations 1 to 6) were sunk on 20th October 2020 for the purpose of measuring groundwater levels over a period of time within the development area. The locations are shown on Figure 1.

3.1 Historical monitoring

John Sime and Associates – November 2015

Groundwater monitoring was carried out as part of their Site Investigation and the results indicate that during the excavation of ten trial pits, groundwater was encountered between 1.80 m and 2.00 m below existing ground level. When these levels are compared to the topographical levels on site, the northern level TP 10 was at 6.90 mAoD and the southern location TP2 was at 5.60 mAoD.

Herts and Essex SI - April 2017

Groundwater monitoring was carried out as part of their Site Investigation and the results indicate that during the drilling of the 8 window sample holes, groundwater was encountered between 1.70 m and 2.20 m below existing ground level. When these levels are compared to the topographical levels on site, the northern level at WS1 was at 6.85 mAoD and the southern location WS4 was at 5.60 mAoD.

3. RSK MONITORING


Groundwater monitoring was carried out by RSK on 6 occasions (2/11/2020 to 16/03/2021) and the results are attached. Some of the standpipes were lost on the later monitoring rounds as development has proceeded through the site, however it is considered that there is sufficient data to inform design of the drainage system.

The monitoring was carried out during one of the wettest October to February periods in recorded history. In summary when these levels are compared to the existing topographical levels on site, the highest northern level recorded was in Hole 1 on 17 November 2020 was at 7.43 mAoD and the southern location WS4 was at 6.98 mAoD on 2 November 2020.

We trust this is sufficient for your immediate needs, however if there are any queries please do not hesitate to contact the undersigned.

Yours sincerely,

For RSK Environment Limited



Nigel Austin

Director

Enc.

Figures:

Figure 1 Site Location Plan

Appendices:

Appendix A Service Constraints

Appendix B RSK Groundwater Monitoring

FIGURES

[illegible]

7. Create an outline of what is to be recorded with regard to the 2 A's.

2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 2681, 26

2000-2001-2002

2024-2025

5000-10000-2000-3000-4000-5000-6000-7000-8000-9000-10000-11000-12000-13000-14000-15000-16000-17000-18000-19000-20000-21000-22000-23000-24000-25000-26000-27000-28000-29000-30000-31000-32000-33000-34000-35000-36000-37000-38000-39000-40000-41000-42000-43000-44000-45000-46000-47000-48000-49000-50000-51000-52000-53000-54000-55000-56000-57000-58000-59000-60000-61000-62000-63000-64000-65000-66000-67000-68000-69000-70000-71000-72000-73000-74000-75000-76000-77000-78000-79000-80000-81000-82000-83000-84000-85000-86000-87000-88000-89000-90000-91000-92000-93000-94000-95000-96000-97000-98000-99000-100000-101000-102000-103000-104000-105000-106000-107000-108000-109000-110000-111000-112000-113000-114000-115000-116000-117000-118000-119000-120000-121000-122000-123000-124000-125000-126000-127000-128000-129000-130000-131000-132000-133000-134000-135000-136000-137000-138000-139000-140000-141000-142000-143000-144000-145000-146000-147000-148000-149000-150000-151000-152000-153000-154000-155000-156000-157000-158000-159000-160000-161000-162000-163000-164000-165000-166000-167000-168000-169000-170000-171000-172000-173000-174000-175000-176000-177000-178000-179000-180000-181000-182000-183000-184000-185000-186000-187000-188000-189000-190000-191000-192000-193000-194000-195000-196000-197000-198000-199000-200000-201000-202000-203000-204000-205000-206000-207000-208000-209000-210000-211000-212000-213000-214000-215000-216000-217000-218000-219000-220000-221000-222000-223000-224000-225000-226000-227000-228000-229000-230000-231000-232000-233000-234000-235000-236000-237000-238000-239000-240000-241000-242000-243000-244000-245000-246000-247000-248000-249000-250000-251000-252000-253000-254000-255000-256000-257000-258000-259000-260000-261000-262000-263000-264000-265000-266000-267000-268000-269000-270000-271000-272000-273000-274000-275000-276000-277000-278000-279000-280000-281000-282000-283000-284000-285000-286000-287000-288000-289000-290000-291000-292000-293000-294000-295000-296000-297000-298000-299000-300000-301000-302000-303000-304000-305000-306000-307000-308000-309000-310000-311000-312000-313000-314000-315000-316000-317000-318000-319000-320000-321000-322000-323000-324000-325000-326000-327000-328000-329000-330000-331000-332000-333000-334000-335000-336000-337000-338000-339000-340000-341000-342000-343000-344000-345000-346000-347000-348000-349000-350000-351000-352000-353000-354000-355000-356000-357000-358000-359000-360000-361000-362000-363000-364000-365000-366000-367000-368000-369000-370000-371000-372000-373000-374000-375000-376000-377000-378000-379000-380000-381000-382000-383000-384000-385000-386000-387000-388000-389000-390000-391000-392000-393000-394000-395000-396000-397000-398000-399000-400000-401000-402000-403000-404000-405000-406000-407000-408000-409000-410000-411000-412000-413000-414000-415000-416000-417000-418000-419000-420000-421000-422000-423000-424000-425000-426000-427000-428000-429000-430000-431000-432000-433000-434000-435000-436000-437000-438000-439000-440000-441000-442000-443000-444000-445000-446000-447000-448000-449000-450000-451000-452000-453000-454000-455000-456000-457000-458000-459000-460000-461000-462000-463000-464000-465000-466000-467000-468000-469000-470000-471000-472000-473000-474000-475000-476000-477000-478000-479000-480000-481000-482000-483000-484000-485000-486000-487000-488000-489000-490000-491000-492000-493000-494000-495000-496000-497000-498000-499000-500000-501000-502000-503000-504000-505000-506000-507000-508000-509000-510000-511000-512000-513000-514000-515000-516000-517000-518000-519000-520000-521000-522000-523000-524000-525000-526000-527000-528000-529000-530000-531000-532000-533000-534000-535000-536000-537000-538000-539000-540000-541000-542000-543000-544000-545000-546000-547000-548000-549000-550000-551000-552000-553000-554000-555000-556000-557000-558000-559000-560000-561000-562000-563000-564000-565000-566000-567000-568000-569000-570000-571000-572000-573000-574000-575000-576000-577000-578000-579000-580000-581000-582000-583000-584000-585000-586000-587000-588000-589000-590000-591000-592000-593000-594000-595000-596000-597000-598000-599000-600

For a complete conference, visit www.elsevier.com/locate/locate/locate

Agosto 04 - 2004 (10 años de existencia)

State	Inventory number	Rev
B	H11102-F1	C

APPENDIX A

SERVICE CONSTRAINTS

1. This report and the site investigation carried out in connection with the report (together the "Services") were compiled and carried out by RSK Environment Limited (RSK) for Matthew Homes (the "Client") in accordance with the terms of a contract between RSK and the Client. The Services were performed by RSK with the reasonable skill and care ordinarily exercised by an environmental consultant at the time the Services were performed. Further, and in particular, the Services were performed by RSK taking into account the limits of the scope of works required by the client, the time scale involved and the resources, including financial and manpower resources, agreed between RSK and the Client.
2. Other than that, expressly contained in paragraph 1 above, RSK provides no other representation or warranty whether express or implied, in relation to the Services.
3. Unless otherwise agreed in writing, the Services were performed by RSK exclusively for the purposes of the Client. RSK is not aware of any interest of or reliance by any party other than the Client in or on the Services. Unless expressly provided in writing, RSK does not authorise, consent or condone any party other than the client relying upon the Services. Should this report or any part of this report, or otherwise details of the Services or any part of the Services be made known to any such party, and such party relies thereon that party does so wholly at its own and sole risk and RSK disclaims any liability to such parties. **Any such party would be well advised to seek independent advice from a competent environmental consultant and/or lawyer.**
4. It is RSK's understanding that this report is to be used for the purpose described in the introduction to the report. That purpose was a significant factor in determining the scope and level of the Services. Should the purpose for which the report is used, or the proposed use of the site change, this report may no longer be valid and any further use of or reliance upon the report in those circumstances by the client without RSK's review and advice shall be at the client's sole and own risk. Should RSK be requested to review the report after the date of this report, RSK shall be entitled to additional payment at the then existing rates or such other terms as agreed between RSK and the client.
5. The passage of time may result in changes in site conditions, regulatory or other legal provisions, technology or economic conditions which could render the report inaccurate or unreliable. The information and conclusions contained in this report should not be relied upon in the future without the written advice of RSK. In the absence of such written advice of RSK, reliance on the report in the future shall be at the Client's own and sole risk. Should RSK be requested to review the report in the future, RSK shall be entitled to additional payment at the then existing rate or such other terms as may be agreed between RSK and the client.
6. The observations and conclusions described in this report are based solely upon the Services which were provided pursuant to the agreement between the Client and RSK. RSK has not performed any observations, investigations, studies or testing not specifically set out or required by the contract between the client and RSK. RSK is not liable for the existence of any condition, the discovery of which would require performance of services not otherwise contained in the Services. For the avoidance of doubt, unless otherwise expressly referred to in the introduction to this report, RSK did not seek to evaluate the presence on or off the site of asbestos, invasive plants, electromagnetic fields, lead paint, heavy metals, radon gas or other radioactive or hazardous materials, unless specifically identified in the Services.
7. The Services are based upon RSK's observations of existing physical conditions at the Site gained from a visual inspection of the site together with RSK's interpretation of information, including documentation, obtained from third parties and from the Client on the history and usage of the site, unless specifically identified in the Services or accreditation system (such as UKAS ISO 17020:2012 clause 7.1.6):
 - a. The Services were based on information and/or analysis provided by independent testing and information services or laboratories upon which RSK was reasonably entitled to rely.

- b. The Services were limited by the accuracy of the information, including documentation, reviewed by RSK and the observations possible at the time of the visual inspection.
- c. The Services did not attempt to independently verify the accuracy or completeness of information, documentation or materials received from the client or third parties, including laboratories and information services, during the performance of the Services.



RSK is not liable for any inaccurate information or conclusions, the discovery of which inaccuracies required the doing of any act including the gathering of any information which was not reasonably available to RSK and including the doing of any independent investigation of the information provided to RSK save as otherwise provided in the terms of the contract between the Client and RSK.



- 8. The intrusive environmental site investigation aspects of the Services are a limited sampling of the site at pre-determined locations based on the known historic / operational configuration of the site. The conclusions given in this report are based on information gathered at the specific test locations and can only be extrapolated to an undefined limited area around those locations. The extent of the limited area depends on the properties of the materials adjacent and local conditions, together with the position of any current structures and underground utilities and facilities, and natural and other activities on site. In addition, chemical analysis was carried out for a limited number of parameters (as stipulated in the scope between the client and RSK, based on an understanding of the available operational and historical information) and it should not be inferred that other chemical species are not present.
- 9. Any site drawing(s) provided in this report is (are) not meant to be an accurate base plan but is (are) used to present the general relative locations of features on, and surrounding, the site. Features (intrusive and sample locations etc) annotated on site plans are not drawn to scale but are centred over the approximate location. Such features should not be used for setting out and should be considered indicative only.
- 10. The comments given in this report and the opinions expressed are based on the ground conditions encountered during the site work and on the results of tests made in the field and in the laboratory. However, there may be conditions pertaining to the site that have not been disclosed by the investigation and therefore could not be taken into account. In particular, it should be noted that there may be areas of made ground not detected due to the limited nature of the investigation or the thickness and quality of made ground across the site may be variable. In addition, groundwater levels and ground gas concentrations and flows, may vary from those reported due to seasonal, or other, effects and the limitations stated in the data should be recognised.
- 11. Asbestos is often observed to be present in soils in discrete areas. Whilst asbestos-containing materials may have been locally encountered during the fieldworks or supporting laboratory analysis, the history of brownfield and demolition sites indicates that asbestos fibres may be present more widely in soils and aggregates, which could be encountered during more extensive ground works.
- 12. Unless stated otherwise, only preliminary geotechnical recommendations are presented in this report and these should be verified in a Geotechnical Design Report, once proposed construction and structural design proposals are confirmed.





APPENDIX B

RSK GROUNDWATER MONITORING







14/12/2020 - Holes 1, 2 and 6 affected by localised dewatering