




Our Ref: PJW/SD/30058

14 March 2019

Nicola Spencer
Technical Support Manager
Planning Department
Arun District Council
Maltravers Road
Littlehampton
West Sussex
BN17 5LF



Dear Nicola

**Structural Repairs to stabilize front wall
The Bognor Club, 2 Sudley Road, Bognor Regis**


I refer to your e-mail 21 February 2019. I have now had an opportunity to prepare paper copies of my application for Listed Building Consent in respect of structural repair work at the above address. I enclose three copies of all information submitted by e-mail to Martyn White on 10 January 2019 as follows:

- E-mail of 10 January 2019 to Martyn White and his of 08 November 2018 to me
- Application for Listed Building Consent and copies of Plans all referred to in my e-mail
- My e-mail report of 23 October 2018 and accompanying sketch and photographs copied to Martyn White
- Further copy of the front elevation at A2 size and therefore reasonably to scale marked up to show the locations of Cement ties

Please note that all plans are scans of drawings held by the club and relating to other works in 2004. I have made use of these to assist your consideration of location and elevation to save the club the expense of new plans.

All works are now complete. The patten plates are painted white so blending in with the render work.

Yours sincerely,



Peter Willmott **CEng; FStructE**
Consultant
for **ARCHIBALD SHAW**

Enc

cc: Martyn White, Arun District Council (Martyn.white@arun.gov.uk) only
Raymond Proctor, The Bognor Club  only

