

Condition 4 - Material schedule for Clay tile roof repairs to Mill House principle wing.**Clay tiles:**

Re-use existing clay tiles and deficit made up with new reclaimed tiles to match existing.

The new reclaimed tile we would like to use is the one approved for Mill Cottage roof 23/18/L documented in an email dated 12 September 2018, enclosed in this application.

A sample of this same tile can be delivered to Council offices if required.


Existing iron rainwater goods:

Re-fix existing and overhauled cast iron rainwater goods including hoppers and downpipes. Where upvc has been installed this shall be removed and replaced with cast iron to match existing. There is no upvc rainwater goods on this part of the roof and the existing cast iron goods are capable of refurbishment, so we are not using replacement cast iron rainwater goods hence no sample is provided.

Photographs of BEFORE and AFTER of the overhauled cast iron rainwater goods are included below.



BEFORE



AFTER

