

Existing Fence line with gaps between panels where dead trees or rotten posts impact the fence line.

All these panels will be considered for retention, during protection coating it appears that at least 10 panels can be retained

Current Fence is not level, this will be corrected as part of the project

Scale 1:100

