

Inspected: From 01/10/2025
 Site: OUTERWYKE ROAD (1100822)
 Sequence Number: 1000020.00 to 1000020.00
 Report Type: Assessment

Site: OUTERWYKE ROAD (1100822) Area: FELPHAM
 Seq No.: 1,000,020.00 Asset Id - Location: Os 75
 Asset Type: Quercus robur Contract Area: West Sussex | Trees

Batch: 1520153 - Inspection Batch

Route: TREE: One off Western Month 1 Officer: Darren Wilkinson (ARB)[BW]

Date: 22/10/2025

Observation Type	Code	Grade	Score	Notes
1.Root System	TR01	Good Condition	.0000	
2.Butt and Main Stem	TR02	Poor Condition	.0000	Small area of bark death at base N
				Various areas of localised bark necrosis and stem exudate. No clear cause at present. No signs of decay on exposed sapwood.
3.Limb and Branch Framework	TR03	Good Condition	.0000	Honey fungus on all compass points at base. Minor dw
4.Leaves, Shoots and Buds	TR04	Poor Condition	.0000	Moderate crown density/shoot extension across outer upper crown
				Canopy thinning on west side approx 25-30% affected with some notable deadwood. Works raised to remove deadwood and crown reduce to encourage re trenchment.
				Oct 25 - Further thinning, tree is not responding well to reduction. large mass of

Defect No.	Description	Log Date	Location	Type	Organisation	Status
873079	Fell to surface level	22/10/2025	Outside 75-77	INT		Uncommitted



