




From: Susan Leeson [REDACTED]
Sent: 09 May 2018 08:25
To: Ross Leal
Cc: Fiona Fitzgerald
Subject: FP/69/18/PL

Good Morning Ross

With regard to the odour control, the problem has been identified as a faulty fan control, please see confirmation below. This has now been rectified and Mr Noor has asked for an independent monitoring to ensure that this has fixed the problem.

Best regards
Susan

SUSAN LEESON
ASSOCIATE

T. 02392 597139
A. West Suite, Coles Yard Barn, North Lane, Clanfield, Hampshire, PO8 0RN
[REDACTED]

Company Registration No. 07164666. Registered Office is at 1 & 2 The Barn, West Stake Road, Chichester, West Sussex, PO18 9AA.

From: Michael Noor [REDACTED]
Sent: Tuesday, May 8, 2018 3:43 PM

To: Susan Leeson [REDACTED]
Subject: Fwd: MaXfan Compac

Sent from my iPhone

Begin forwarded message:

From: Adam Butcher (FläktGroup) [REDACTED]
Date: 8 May 2018 at 14:40:14 BST
To: "m" [REDACTED]
Subject: FW: MaXfan Compac

Hi Michael,

Please see below as discussed today.

You can get spare interfaces from Ian at EIV – N17 9QP t: 0208 808 1952.

Thanks
Adam

Kind regards,

Adam Butcher
Woods Distribution External Sales
Fläkt Woods Limited (Colchester, UK)



<image001.jpg> [Follow us on Twitter](#)

<image004.jpg>

From: Adam Butcher (FläktGroup)
Sent: 03 May 2018 13:52
To: [REDACTED]
Subject: MaXfan Compac

Hi Michael,

As discussed, we have sent out a new FC101 screen out to replace the current one on site. It would appear that the old screen was regulating up & down due to the POT / Dial becoming stuck.

With the new screen this will not happen so the fan can run at full speed without dropping down.

Thanks
Adam

Kind regards,

Adam Butcher
Woods Distribution External Sales
Fläkt Woods Limited (Colchester, UK)



<image001.jpg> [Follow us on Twitter](#)

<image002.jpg>