
RE: Ford - Drainage Response

From Julson Delishaj [REDACTED]
To John Longhorn [REDACTED] Gardiner Hanson [REDACTED] Andrew Dennis [REDACTED] Charlie Cooper [REDACTED]

Hi all,

@ Ardent Team Please see data we have to date during this winter period for oct 2025 to Jan 2026, please include the table below in you report along with the soak away testing.

@Gardiner Hanson @John Longhorn Ultimately, the gw levels are no worse than previous data i.e. predominantly DRY, hence we proceeded with the testing as per Ardent testing document.

Kind Regards.

30019 - Ford
Airfield

	17/10/2025		19/11/2025		27/11/2025		10/12/2025		21/01/26	
Exploratory Hole Number	Dip	Base	Dip	Base	Dip	Base	Dip	Base	Dip	Base
WM1	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM2	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM3	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM4	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM5	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM6	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM7	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM8	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM9	DRY	4	DRY	4	DRY	4	DRY	4	DRY	4
WM10			DRY	4	DRY	4	DRY	4	DRY	4

WM11			DRY	4	DRY	4	DRY	4	DRY	4
WM12			DRY	4	DRY	4	DRY	4	DRY	4
WM13			DRY	4	DRY	4	DRY	4	DRY	4
WM14			DRY	4	DRY	4	DRY	4	DRY	4
WM15			DRY	4	DRY	4	DRY	4	DRY	4
WM16			DRY	4	DRY	4	DRY	4	DRY	4
WM17			DRY	4	DRY	4	DRY	4	DRY	4
P1	DRY	1.85	DRY	1.85	DRY	1.85	DRY	1.85	DRY	1.85
BH6	5.75	9.1	5.4	9.1	5.29	9.1	5.12	9.1	4.2	9.1
WS403	DRY	3	DRY	3	DRY	3	DRY	3	DRY	3
P12	Unable to dip		DRY	2	DRY	2	DRY	2	DRY	2
WS408	DRY	4.75	DRY	4.75	DRY	4.75	DRY	4.75	4.5	4.75
WS411	2.02	4.51	1.7	4.51	1.53	4.51	1.45	4.51	1.1	4.51
WS6	DRY	2.45	DRY	2.45	DRY	2.45	DRY	2.45	DRY	2.45
WS8	DRY	2.65	DRY	2.65	DRY	2.65	DRY	2.65	DRY	2.65
DS6Z			DRY	1.7	DRY	1.7	DRY	1.7	DRY	1.7
DS7Z			DRY	2	4.6	4.9	4.4	4.9	3.75	4.9
P4			DRY	1.8	DRY	1.8	DRY	1.8	DRY	1.8

Juls Delishaj

Engineering & Adoptions Manager



Vistry South East

Regus | Abbey House | 25 Clarendon Road

Redhill | RH1 1QZ |

(Temporary address until late summer 2026)